

San Juan County Master PLS Record

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
2622C36	640140	quarter corner	Obliterated	brass cap	Local	1963	Local Surveys	in concrete collar	3205214.312	678762.191	4818.026
2622E36	700140	quarter corner	Obliterated	wood post	other	0	Parole	ceadr post NE crnr corral	3205233.207	679566.147	4906.293
2622N35	540200	quarter corner	Existent	brass cap	County	0	Possession/Surveys	at fence crnr sw	3205984.076	677129.988	4701.778
2622N36	640200	quarter corner	Existent	brass cap	Local	2010	BT S25,S36	set new mon.from B.T.s	3206019.619	678745.097	5061.132
2622NE36	700200	section corner	Existent	stone corner	GLO	1902	BT S31 S30		3206038.729	679548.341	5301.915
2622NW35	500200	section corner	Existent	brass cap	GLO	1912	Original Monument	openfield,post E-W	3205966.939	676323.12	4692.836
2622NW36	600200	section corner	Existent	brass cap	GLO	1912	Original Monument	@ fence corner	3206001.098	677936.849	4748.398
2622S35	540100	Quarter Corner	Obliterated	Re-Bar & Cap	Private	1998	CAP REBAR	Set from ROS889	3204371.852	677165.765	4810.769

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
2622S36	640100	quarter corner	Obliterated	rebar	other	0	R.M. S.1 & S.36	rebar w/ ties in S1&36	3204407.954	678778.717	4856.584
2622SE36	700100	section corner	Existent	brass cap	GLO	1911	Original Monument	in fence projects E&W	3204425.425	679583.694	4903.844
2622SW36	600100	section corner	Existent	brass cap	GLO	1911	Original Monument	in field	3204390.203	677972.282	4812.874
2622W35	500140	quarter corner	Existent	brass cap	GLO	1912	Original Monument	T-post/sign 1's	3205161.424	676340.802	4764.649
2622W36	600140	quarter corner	Obliterated	brass cap	other	0	Locally Accepted	brass cap not stamped	3205195.503	677955.301	4773.225
262633CNTYMKR	336140	County Boundary	No Observation	Brass Tablet	County	1967	Brass Tablet	Set by Blake and Newell San Juan & Grand County Surveyors	3206258.008	712819.6	0
2722E12	700540	quarter corner	Existent	brass cap	GLO	1911	none	@ edge of pit	3202002.864	679636.049	5049.024
2722E13	700440	quarter corner	Existent	brass cap	GLO	1911	BT,s13,s18	in mnd of stone	3200388.517	679671.114	5219.761
2722N28	340300	quarter corner	Existent	brass cap	GLO	1911	none	12"out of grnd	3197832.103	674090.434	5547.073

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
2722N33	340200	quarter corner	Existent	brass cap	GLO	1911	none	12"out of grnd	3196223.927	674126.723	5367.195
2722N36	640200	quarter corner	Existent	brass cap	GLO	1911	none	10"abv mnd of stn	3196332.962	678957.9	5649.989
2722NW02	500700	section corner	Existent	brass cap	GLO	1911	BT S2,3&34	in mnd of stn	3204354.778	676359.068	5057.842
2722NW15	400500	section corner	Existent	brass cap	GLO	1911	BTs16,s15down	8"out of grnd 15ft S of E/W rd	3201067.535	674819.772	5464.523
2722NW27	400300	section corner	Existent	brass cap	GLO	1911	none	14"out of grnd	3197850.645	674894.307	5538.133
2722NW28	300300	section corner	Existent	brass cap	GLO	1911	none	12"out of grnd	3197813.587	673285.946	5545.241
2722NW34	400200	section corner	Existent	brass cap	GLO	1911	none	14"out of grnd	3196241.911	674931.174	5471.921
2722NW36	600200	section corner	Existent	brass cap	GLO	1911	BT,s36	12"out of grnd	3196314.951	678149.563	5329.631
2722S01	640600	quarter corner	Existent	brass cap	BLM	1911	none	by lg. metal post disturbed	3202765.715	678814.29	4939.945
2722S33	340100										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Existent	brass cap	GLO	1911	BTs33	15"above stn mnd	3194613.358	674164.666	5439.299
<i>2722S36</i>	<i>640100</i>										
		quarter corner	Existent	brass cap	GLO	1911	none	in mnd of stn	3194723.806	678990.626	5582.509
<i>2722SE01</i>	<i>700600</i>										
		closing corner	Existent	brass cap	GLO	1911	none		3202784.438	679619.226	5001.876
<i>2722SE12</i>	<i>700500</i>										
		closing corner	Existent	brass cap	GLO	1911		mnd of stn to W	3201174.117	679654.465	5089.62
<i>2722SE13</i>	<i>700400</i>										
		closing corner	Existent	brass cap	GLO	1911	none	in a mnd of stone	3199565.231	679688.442	5261.806
<i>2722SW01</i>	<i>600600</i>										
		section corner	Existent	brass cap	GLO	1911	BTs02		3202747.194	678009.619	4957.418
<i>2722SW36</i>	<i>600100</i>										
		section corner	Existent	brass cap	GLO	1911	none	10"abv mnd of stn	3194705.119	678186.094	5504.367
<i>2722W21</i>	<i>300340</i>										
		quarter corner	Existent	brass cap	GLO	1911	none	14"out of grnd	3198617.862	673267.681	5323.12
<i>2722W27</i>	<i>400240</i>										
		quarter corner	Existent	brass cap	GLO	1911	none	15"out of grnd	3197046.199	674912.697	5487.159
<i>2723C06</i>	<i>140640</i>										
		witness corner	Existent	aluminum cap	BLM	1995	none	witness corner grn fnc pst alongside	3203633.415	680302.882	5059.878
<i>2723C22</i>											

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>2723C22</i>	<i>440340</i>	quarter corner	Existent	aluminum cap	BLM	1995	none	6"out of grnd	3198898.485	685322.368	5938.928
<i>2723CE1622</i>	<i>460340</i>	sixteenth corner	Existent	brass cap	BLM	1995	none	4"above mnd of stn	3198906	685724.544	5993.481
<i>2723CSSN23</i>	<i>540345</i>	1/256th corner	Existent	aluminum cap	USFS	1985	USFS Monument	t-post/sign 2'e&n	3199034.835	686932.15	6113.189
<i>2723CSSNE23</i>	<i>560345</i>	1/256th corner	Existent	aluminum cap	USFS	1985	USFS Monument	post/sign 3'W 2'S	3199045.37	687337.415	6261.716
<i>2723E01</i>	<i>700640</i>	quarter corner	Existent	brass cap	GLO	1911	BTs01,	14"out of grnd LineTree1. 28ch N.	3203835.269	689239.846	7801.958
<i>2723E24</i>	<i>700340</i>	quarter corner	Existent	brass cap	GLO	1934	BT,s24	in mnd of stn	3198992.629	689358.344	6678.747
<i>2723N06</i>	<i>140700</i>	quarter corner	Existent	aluminum cap	BLM	1995	BLM Monument	@ crnr S&Wfnc	3204442.075	680343.952	4974.574
<i>2723N08</i>	<i>240600</i>	quarter corner	Existent	brass cap	GLO	1911	BT,s05 found down	in mound of stone BT,s08 not found	3202861.222	681995.074	5181.096
<i>2723N12</i>	<i>640600</i>	quarter corner	Existent	brass cap	GLO	1911	BT,s01,s12	in mnd of stone	3203009.365	688450.894	7370.988
<i>2723N14</i>											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
2723N14	542500	quarter corner	Existent	brass cap	GLO	1911	BT,s11,s14	10"abv mnd of stn for sec 14 only	3201352.974	686876.01	6569.571
2723N19	140400	quarter corner	Existent	stone corner	GLO	0	none	stone loose coulee 20ft to East	3199598.759	680456.791	5211.212
2723N20	240400	quarter corner	Existent	stone corner	other	0	none	in a mnd of stone	3199635.935	682072.374	5570.806
2723N21	340400	quarter corner	Existent	brass cap	BLM	1995	none	in mnd of stone	3199670.773	683687.143	5628.992
2723N22	440400	quarter corner	Existent	aluminum cap	BLM	1995	none	12"out of grnd in mnd of stone	3199704.03	685305.144	5855.895
2723N25	640300	quarter corner	Existent	stone corner	GLO	0	BT,s25	red stl fnc pst 1.5'W	3198167.47	688572.502	6460.536
2723N27	440300	quarter corner	Existent	aluminum cap	BLM	1995	alumcap1/2"rbrN79dW	in mnd of stone acc. diff from notes	3198098.601	685339.228	6411.636
2723N32	240200	quarter corner	Existent	brass cap	GLO	1915	BT,s32	14"abv grnd	3196405.065	682147.081	5724.072
2723N33	340200	quarter corner	Existent	brass cap	GLO	1911	BTs33	12"abv mnd of	3196441.715	683761.499	6021.22

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
									"Utah Coordinate System 1983 South Zone"		
									stn		
<i>2723NE06WC</i>	<i>200700</i>										
		witness corner	Existent	brass cap	GLO	1911	BLM Monument, W.P.	mnd stone	3204460.003	681150.715	5408.385
<i>2723NE06WP</i>	<i>200707</i>										
		witness point	Existent	aluminum cap	BLM	1995	BLM Monument, W.C.	WP, mnd of stone	3204465.146	681374.41	5837.065
<i>2723NE12</i>	<i>700600</i>										
		section corner	Existent	brass cap	GLO	1911	none	in mnd of stn	3203029.666	689259.722	7607.723
<i>2723NE25</i>	<i>700300</i>										
		section corner	Existent	brass cap	BLM	1970	BT S24&25	in a mnd of stone	3198186.303	689378.475	6606.352
<i>2723NW08</i>	<i>200600</i>										
		section corner	Existent	nail	GLO	0	2ref mon E&W of road	buried cntr rd	3202844.944	681187.124	5096.284
<i>2723NW12</i>	<i>600600</i>										
		section corner	Existent	brass cap	GLO	1911	BT,s2,s11	in mnd of stn	3202984.663	687640.371	6945.659
<i>2723NW13</i>	<i>600500</i>										
		section corner	Existent	brass cap	GLO	1911	BT,s11,s12,s13,s14	12"abv mnd of stn	3201374.232	687679.682	6956.687
<i>2723NW14</i>	<i>500500</i>										
		section corner	Existent	brass cap	GLO	1911	BTs14,s15,s10,s11	in mnd of stn	3201331.993	686070.235	6618.302
<i>2723NW19</i>	<i>100400</i>										
		section corner	Existent	brass cap	GLO	1911	none	in a mnd of stone	3199580.541	679688.082	5281.643
<i>2723NW20</i>	<i>200400</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		section corner	Existent	stone corner	GLO	0	none	in mound of stone	3199617.671	681263.571	5284.602
<i>2723NW24</i>	<i>600400</i>										
		section corner	Existent	brass cap	BLM	1970	BTs24	w/mnd of stn to W att. sign1.61ft to E	3199763.472	687718.51	6523.224
<i>2723NW25</i>	<i>600300</i>										
		section corner	Existent	stone corner	GLO	0	none	10"above mnd of stn	3198149.46	687765.904	6314.523
<i>2723NW26</i>	<i>500300</i>										
		section corner	Existent	aluminum cap	USFS	1995	none	4"outofgrnd 3ft W of N/S fnc ln	3198109.661	686145.181	6574.278
<i>2723NW27</i>	<i>400300</i>										
		section corner	Existent	aluminum cap	BLM	1995	BTs22&s28	6"out of grnd	3198078.483	684532.501	6312.468
<i>2723NW30</i>	<i>100300</i>										
		section corner	Existent	brass cap	GLO	1911	BT,s24&s25	4"above grnd	3197968.453	679722.117	5571.184
<i>2723NW31</i>	<i>100200</i>										
		witness corner	Existent	brass cap	GLO	1911	3BT's	S of cf boulder	3196350.605	679759.166	5466.836
<i>2723NW32</i>	<i>200200</i>										
		section corner	Existent	brass cap	GLO	1911	BT,s30	16"out of grnd	3196386.979	681337.902	5759.85
<i>2723NW33</i>	<i>300200</i>										
		section corner	Existent	brass cap	GLO	1911	BT,s28,s29,s32,s33	12"abv mnd of stn	3196423.196	682954.52	5910.326
<i>2723NW34</i>	<i>400200</i>										
		section corner	Existent	brass cap	GLO	1911	BTs33&s34	14"abv mnd of stn reinforced mnd	3196460.818	684567.901	6130.531

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
2723S06	140600	quarter corner	Existent	brass cap	GLO	1911	none		3202827.283	680380.936	5060.679
2723S11	540500	Quarter Corner	Lost	Stone Corner	GLO	1915	NONE	NO EVIDENCE	3201352.745	686869.699	6571.088
2723S1622/23	500320	sixteenth corner	Existent	aluminum cap	USFS	1985	USFS Monument	TPOST/SIGN 4'N/S/E	3198511.451	686136.119	6116.885
2723S29	237200	Quarter Corner	Existent	Brass Cap	GLO	1917	N32 MON. BT S32	RESET ORIG MON	3196405.001	682145.487	5724.571
2723S31	140100	quarter corner	Existent	brass cap	GLO	1915	none	in mnd of stn	3194757.616	680571.394	5605.911
2723S32	240100	quarter corner	Existent	brass cap	GLO	1915	none	16" out of grnd std. corner	3194792.897	682181.452	5734.353
2723SE1622	460320	sixteenth corner	Existent	aluminum cap	BLM	1996	BLM Monument	t-post/sign 2'E	3198504.933	685733.39	6170.868
2723SW06	100600	section corner	Existent	brass cap	GLO	1911	none		3202810.987	679618.644	5000.316
2723SW07	100500	section corner	Existent	brass cap	GLO	1911	none	in mnd of stone	3201195.829	679653.919	5088.947
2723SW1623	520320										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		sixteenth corner	Existent	aluminum cap	USFS	1985	USFS Monument	T-POST/SIGN 2.5'E	3198525.113	686542.022	6161.195
2723SW31	100100										
		section corner	Existent	brass cap	GLO	1911	BTs06,s01,s36,s31	12"abv mnd of stn std. corner	3194743.021	679794.686	5262.512
2723SW32	200100										
		closing corner	Existent	brass cap	GLO	1911	BT,s32	6"above mnd of stn std. corner	3194775.52	681374.971	5690.889
2723SW33	300100										
		closing corner	Existent	brass cap	GLO	1911	none	14"abv mnd of stn AP to the E /std cor	3194809.661	682988.141	5701.454
2723W01	600640										
		quarter corner	Existent	brass cap	GLO	1911	BTs02		3203789.772	687623.244	7307.181
2723W05	200640										
		quarter corner	Existent	brass cap	GLO	1911	none	in mound of stone firmly set	3203651.9	681169.547	5126.784
2723W06	100640										
		quarter corner	Existent	brass cap	GLO	1911	none	@S&E fence line	3203618.338	679601.191	4956.941
2723W08	200540										
		quarter corner	Existent	aluminum cap	BLM	1995	none	in rock pile	3202037.244	681207.05	5182.592
2723W11	500540										
		quarter corner	Existent	brass cap	GLO	1911	BTs10	16" abv stone mnd mon in N/S fnc line	3202135.822	686051.291	6659.468
2723W13	600440										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Existent	stone corner	GLO	0	BTs13,s14		3200567.702	687698.831	6888.084
2723W14	500440										
		quarter corner	Existent	aluminum cap	USFS	1995	none	in mnd of stn	3200525.881	686089.525	6495.64
2723W15	400440										
		quarter corner	Existent	brass cap	GLO	1911	BTs15	12"abv mnd of stn	3200494.29	684479.64	5815.424
2723W1607/06	120600										
		sixteenth corner	Existent	aluminum cap	BLM	1995	none	W1/16 s6/s7	3202818.703	679978.103	5034.031
2723W19	100340										
		quarter corner	Existent	brass cap	GLO	1911	none	16"abv mnd of stn	3198775.701	679703.918	5701.554
2723W22	400340										
		quarter corner	Existent	aluminum cap	BLM	1995	none	6" out of grnd	3198883.66	684515.797	5870.604
2723W31	100140										
		quarter corner	Existent	brass cap	GLO	1911	none	6"above mnd of stn	3195547.311	679777.196	5490.627
2723W32	200140										
		quarter corner	Existent	brass cap	GLO	1911	no BTs found	in ring of stone	3195582.294	681356.33	5384.356
2723W33	300140										
		quarter corner	Existent	brass cap	GLO	1911	BT,s33,s32	10"abv mnd of stn	3195617.229	682971.161	5821.596
2724E24	100337										
		Quarter Corner	No Observation	Brass Cap	GLO	1934	B.C. Flush w/ stone collar	BT well marked W	3199218.438	699572.399	0
2724E36											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
"Utah Coordinate System 1983 South Zone"											
2724E26	100137	Quarter Corner	No Observation	Brass Cap	GLO	1934	B.C. 10" ABV. GRND	N-S fence 4' W, 60' W of road	3196000.411	699632.224	0
2724NW07	100600	closing corner	Existent	brass cap	GLO	1934	none		3202996.61	689260.421	7589.301
2724NW30CC	100297	closing corner	Existent	brass cap	BLM	1970	BT S30	in a mnd of stone	3198179.876	689378.786	6601.497
2724SE13	100397	Section Corner	No Observation	Brass Cap	GLO	1934	B.C. 7" ABV GRND	2 BT's well marked SW and NW of corner	3200020.971	699558.276	0
2724SE24	100297	Section Corner	No Observation	Brass Cap	GLO	1934	B.C. 8" ABV GRND	In mnd stone with mnd also 2' E	3198415.891	699585.744	0
2724SE25	100197	Section Corner	No Observation	Brass Cap	GLO	1934	B.C. 14" ABV. GRND	N-S fence 2.5' W, 70' N of E-W trail	3196805.84	699614.107	0
2724W06	100640	closing corner	Existent	brass cap	GLO	1934	none	20"abv grndMon bent over	3203800.856	689240.646	7775.167
2724W19	100340	quarter corner	Existent	brass cap	GLO	1934	BT,s19	in mnd of stn	3198981.221	689358.981	6674.183
2725S33	340100										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Quarter Corner	Obliterated	Wood Post	USFS	1918	FNC JCTN	FNC PROJECTS E-W	3195570.409	703623.298	8537.541
2725SE19	100300										
		Section Corner	No Observation	Brass Cap	GLO	1922	B.C. 8" ABV GRND	2 BT's well marked NE and SE	3198648.46	699581.625	0
2725SE33	400100										
		Section Corner	Existent	Stone Corner	GLO	1880	Orig bt stumps S33&34	New BT's S3&34	3195592.676	704423.756	8589.522
2725SW30	100200										
		Section Corner	No Observation	Brass Cap	GLO	1922	B.C. 17" ABV. GRND	In N-S fence	3197041.384	699609.132	0
2725SW33	300100										
		Section Corner	Existent	Aluminum Cap	Private	1985	BT's 32&33	3 ORIG BT STUMPS	3195544.474	702816.998	8550.006
2725W19	100340										
		Quarter Corner	No Observation	Brass Cap	GLO	1922	B.C. 8" ABV GRND	Large mound of stone W of corner.	3199452.007	699568.256	0
2725W30	100240										
		Quarter Corner	No Observation	Brass Cap	GLO	1922	B.C. 12" ABV GRND	2 BT's NW and SE	3197844.929	699595.767	0
2725W31	100140										
		Quarter Corner	No Observation	Brass Cap	GLO	1922	B.C.	N-S fence 3.8' W, Stream bears SE 8' N, 33' SW of cabin remains	3196241.945	699627.108	0
2726CW1616	320440										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
2726E16	400440	Sixteenth Corner	No Observation	Aluminum Cap	USFS	1986	Aluminum Cap	Mon. flush in collar of stone.	3201469.289	712592.345	0
2726NW28	300300	Quarter Corner	No Observation	Aluminum Cap	USFS	1986	A.C. 10" ABV GRND	1' E of State Line wire fence.	3201478.722	712942.826	0
2726SE08	300500	Section Corner	No Observation	Aluminum Cap	USFS	1995	Orig Stone	Found broken stone and BTs. Set new Mon.	3199079.116	712258.461	0
2726SE17	300400	Section Corner	No Observation	Brass Cap	BLM	1965	B.C. 8" ABV GRND	Found 4 orig BTs SW BT is dead in fence.	3202249.656	712175.226	0
2726SW28	300200	Section Corner	No Observation	Aluminum Cap	USFS	1986	BTs	Found orig BTs NE dead. Reset from record calls in rock collar.	3200666.748	712211.671	0
2726W1616	320400	Section Corner	No Observation	None	GLO	0	No evidence found	No remaining evidence found.	3197455.4	712299.893	0
2726W28	300240	Sixteenth Corner	No Observation	Aluminum Cap	USFS	1986	B.C. 2" ABV GRND	Mon. 5.4' E of "+" on top of boulder.	3200679.362	712613.59	0
		Quarter Corner	No Observation	None	GLO	0	No evidence found	No remaining evidence found.	3198266.746	712278.799	0

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>2822NW01</i>	<i>600700</i>								<i>"Utah Coordinate System 1983 South Zone"</i>		
		closing corner	Existent	brass cap	GLO	1916	none	18"abv mnd of stn notes not used	3194704.906	678177.797	5503.807
<i>2823N05</i>	<i>240700</i>										
		quarter corner	Existent	brass cap	GLO	1911	BT,s05	24" out of grnd	3194795.276	682203.56	5716.447
<i>2823N06</i>	<i>140700</i>										
		quarter corner	Existent	brass cap	GLO	1911	BTs06	18"abv mnd of stn	3194758.296	680591.093	5584.708
<i>2823NW04</i>	<i>300700</i>										
		closing corner	Existent	brass cap	GLO	1916	BT,s05	16"abv mnd of stn AP to the W	3194811.017	683036.614	5721.696
<i>2823NW05</i>	<i>200700</i>										
		closing corner	Existent	brass cap	GLO	1916	BT,s06	12"out of grnd AP to the West	3194776.604	681429.25	5690.024
<i>2823S33</i>	<i>337700</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	Orig B.C. monument.	Referenced in card for 2923N4.	3185061.395	684069.137	0
<i>2823SW33</i>	<i>300100</i>										
		Section Corner	No Observation	Brass Cap	GLO	1915	B.C. monument	Set spike w/washer in two BTs.	3185048.792	683263.403	0
<i>2825C22</i>	<i>440340</i>										
		Quarter Corner	No Observation	Aluminum Cap	USFS	1992	A.C. 8" ABV GRND	Mon. in collar of stone.	3189843.232	705040.102	0
<i>2825C26</i>	<i>540240</i>										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Quarter Corner	No Observation	Aluminum Cap	USFS	1994	A.C. 8" ABV GRND	Mon. in collar of stone.	3188271.175	706733.526	0
2825CE1626	560240										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	0	A.C. 12' ABV GRND	Mon. in Mound of stone to cap.	3188280.152	707153.005	0
2825CENW25	630260										
		1/64 Corner	No Observation	Aluminum Cap	BLM	1993	A.C. 14" ABV GRND	Mon. in collar stones.	3188705.099	708148.99	0
2825CEWE17	255440										
		1/256 Corner	No Observation	Aluminum Cap	USFS	1986	A.C. Flush with stone collar	Mon. in Mound of stone staked to top.	3191323.606	702267.151	0
2825CEWSE17	255420										
		1/256 Corner	No Observation	Aluminum Cap	USFS	1986	A.C. Flush with stone collar	Mon. in stone collar to top of cap.	3190918.689	702274.205	0
2825CN1622	440360										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1992	A.C. 6" ABV GRND	Mon. in mound of stone.	3190251.046	705011.754	0
2825CS1617	240420										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1986	A.C. Flush with stone collar	5.2' S of fence E-W	3190909.537	701968.977	0
2825CW1626	520240										
		Sixteent Corner	No Observation	Aluminum Cap	BLM	1994	A.C. 3" above ground	E-W fence 2.5' S. In ring of stones.	3188263.393	706328.921	0
2825CWEE17	265440										
		1/256 Corner	No Observation	Aluminum cap	USFS	1986	A.C. Flush with stone collar	30' S and 30' E of diagonal fence, in ring	3191325.155	702468.745	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
									of stones		
2825CWENW25	625260	1/256 Corner	No Observation	Aluminum Cap	USFS	1993	A.C. 22" Above ground	3' N of E-W fence. Stone staked to top of cap.	3188701.872	708046.017	0
2825CWEW25	625240	1/256 Corner	No Observation	Aluminum Cap	USFS	1993	A.C. 9" Above ground	7.5' W of N-S fence.	3188299.683	708048.065	0
2825CWNESW25	625230	1/256 Corner	No Observation	Aluminum Cap	USFS	1993	A.C. 29" Above ground	Near SE fence corner of Private land on S side of road.	3188103.921	708057	0
2825E16	400440	Quarter Corner	No Observation	Aluminum Cap	GLO	1915	B.C. 14" Above ground	At N-S-W fence junction, small mound of stone W of corner.	3191368.292	704370.49	0
2825E18	200440	Quarter Corner	No Observation	None	none	0	None	Extensive search no findings.	3191292.488	701155.359	0
2825E21	400340	Quarter Corner	No Observation	Aluminum Cap	USFS	1992	A.C. 7" above ground	E-W fence S a gate is 10-15 W of corner.	3189821.888	704263.687	0
2825E26	600240	Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C. 10" above ground	Monument straighted and reset no BTs burned area.	3188288.289	707552.866	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
2825EW24-25	630300	1/64 Corner	No Observation	Aluminum Cap	USFS	1993	A.C. 10" above ground	In N-S fence, 3' S of E-W fence.	3189110.342	708136.227	0
2825N1623	500360	Quarter Corner	No Observation	Brass Cap	USFS	1992	A.C. 12" above ground	SW of ditch 10', E-W fence 75-100' N.	3190274.105	705873.986	0
2825N1626	600260	Sixteenth Corner	No Observation	Aluminum Cap	USFS	1993	A.C. 6" above ground	In N-S fence and 7' N of E-W fence.	3188691.614	707543.412	0
2825N1627-26	500260	Sixteenth Corner	No Observation	Aluminum Cap	BLM	1994	A.C. in mound of stone.	Protected by 2 USFS Boundary markers.	3188654.244	705914.045	0
2825N17	240500	Quarter Corner	No Observation	Brass Cap	GLO	0	B.C. 13" above ground	At N edge dense Oak clump in rock mound.	3192116.523	701938.543	0
2825N21	338400	Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C. 12" above ground	E-W fence 1' S no rock mound.	3190618.652	703416.088	0
2825N25	640300	Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C. 12" above ground	At edge of tree with rock mound to N.	3189115.523	708338.438	0
2825NE17	300500										

"Utah Coordinate System 1983 South Zone"

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Section Corner	No Observation	Aluminum Cap	GLO	1915	B.C. 12" above rock mound.	A ditch center is 53' N.	3192136.179	702741.679	0
2825NE20	298400										
		Section Corner	No Observation	Stone	GLO	0	Marked stone 3" above ground	10"X8" marked granite stone 3 on S, 4 on E	3190586.66	702634.261	0
2825NE21	398400										
		Section Corner	No Observation	Brass Cap	GLO	1915	B.C. 20" above ground	Stone mound S, E-W fence 30' N, N-S fence 75' W	3190634.274	704239.55	0
2825NE22WC	498400										
		Witness Corner	No Observation	Aluminum Cap	USFS	1992	A.C. 10' above ground	WC 10.72' E of true position on steep slope into ditch	3190681.052	705864.166	0
2825NE27	500300										
		Section Corner	No Observation	Brass Cap	BLM	1970	B.C. in stone mound	24" dia. Ponderosa N42E 59.5', fence cor proj. W & S	3189053.325	705903.511	0
2825NS26-25	600230										
		1/64 Corner	No Observation	Aluminum Cap	USFS	1993	A.C. 16" above ground	E-W fence 2.5' N, in stone collar	3188089.109	707550.233	0
2825NW1622	420360										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1992	A.C. 5" above ground	Drainage bears SE is 30' W	3190239.561	704631.686	0
2825NW1626	520260										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1994	A.C. 20" above ground	Corner in Pinion Pine	3188662.928	706317.295	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
2825S1626-25	600220							stand 300' N of open feild.			
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1993	A.C. 6" above ground	Stone collar on SW facing slope.	3187884.975	707562.321	0
2825S22	440300										
		Quarter Corner	No Observation	Aluminum Cap	USFS	1992	A.C. 14' above ground	Found well marked stone replaced with Aluminum Mon.	3189032.429	705095.535	0
2825S34	440100										
		Quarter Corner	No Observation	Aluminum Cap	USFS	0	Stone projecting 6" above ground	Reset stone in mound of stone from BTs stumps	3185768.665	705163.564	0
2825SE07	200500										
		Section Corner	No Observation	Brass Cap	GLO	1915	B.C. 13" above ground	Rock mound 2.5' W of monument.	3192096.936	701135.393	0
2825SE1626	560220										
		Sixteenth Corner	No Observation	Aluminum Tablet	USFS	1994	Alum. tablet in sandstone	Set tablet in base of sandstone ledge	3187877.862	707161.385	0
2825SE16CC	400402										
		Closing Corner	No Observation	Brass Cap	GLO	1915	B.C. 13" above ground	N-S fence 3' E, In line with E-W fence.	3190639.196	704389.23	0
2825SE21WC	400300										
		Witness Corner	No Observation	Aluminum Cap	USFS	1992	A.C. 8' above ground	#6 rebar in road marks	3189009.503	704287.816	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
2825SE26	600200							actual position 31.30' W of WC			
		Section Corner	No Observation	Brass Cap	USFS	1993	A.C. 7" above ground	In stone collar mound W, 8.25' W of N-S fence	3187481.651	707571.767	0
2825SE33	400100										
		Section Corner	No Observation	None	Lost	0	Found BT dead out of position	Found scribed tree down dead out of position bulldozer	3185759.149	704357.661	0
2825SSN17	300445										
		1/256 Corner	No Observation	Aluminum Cap	USFS	1986	A.C. 11" above ground	24' S of E-W fence, 34' W of N-S fence	3191449.174	702758.945	0
2825SW1617	220420										
		1/16 Corner	No Observation	Aluminum Cap	USFS	1986	A.C. flush with ground	3.5' NW fence. 3.7' NW mon.marked as same corner.	3190899.942	701567.432	0
2825SWSWNE17	255445										
		1/256 Corner	No Observation	Aluminum Cap	USFS	1986	A.C. flush with ground	In rock stacked to top.	3191451.396	702466.332	0
2825W1617-20	218400										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1986	A.C. Flush with ground	In E-W fence 1.2' W of corner to N-S fence.	3190558.959	701576.049	0
2825W1622-15	418400										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1992	A.C. 11" above ground	Two track road 3' N of monument.	3190646.428	704611.654	0
2826E28	400240										
		Quarter Corner	No Observation	Aluminum Cap	USFS	1991	A.C. 10" above ground	Utah-Colorado State line N-S fence 2.6' E	3188377.651	713281.517	0
2826E29	300240										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C. 6" above ground	Both BTs with signs found intact.	3188355.393	712487.423	0
2826E30	200240										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C. 12" above ground	Single BT w/sign dead and down N-65-E 32 lks.	3188320.749	710878.807	0
2826E31	200140										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C. 13" above ground	Both BTs found. SW BT cut for fence post.	3186711.238	710918.933	0
2826S29WC	240200										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C. 15" above ground	In E-W fence at west edge of orchard.	3187534.641	711702.7	0
2826SE 21CC	400300										
		Closing Corner	No Observation	Brass Cap	GLO	1915	B.C. 12" above ground	In N-S Fence 2 BTs w-signs.	3189181.741	713260.639	0
2826SE16CC	400400										
		Closing Corner	No Observation	Brass Cap	GLO	1915	B.C. 36" above ground	2 BTs NW dead. 13.5' S is State Line Mile marker 94	3190789.98	713221.763	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
2826SE28CC	400200							well marked stone.			
		Closing Corner	No Observation	Brass Cap	GLO	1915	B.C. flush with ground	2 BTs SW tree dead and down. 4' S of Utah/Colo. State line mile marker chiseled in boulder.	3187573.592	713302.387	0
2826SE30	200200										
		Section Corner	No Observation	Brass Cap	GLO	1915	B.C. 8" above ground	Research and reset this monument 8' NW of fence corner. Moved 6.5'	3187515.376	710898.457	0
2826SE32	300100										
		Section Corner	No Observation	Brass Cap	GLO	1915	B.C. 11" above ground	In rock collar.	3185948.773	712546.626	0
2826SE33CC	400100										
		Closing Corner	No Observation	Brass Cap	GLO	1915	B.C. 7" above ground	On Utah/Colo. state line 5.5' S of Mile marker 91	3185969.54	713344.784	0
2922NW32	200200										
		Section Corner	No Observation	Stone	GLO	0	5"X9"X18" stone 4 bars on E side.	Set 3/4" Brass Discs marked PLS 166642 on 3 BTs	3176757.017	672195.237	0
2922S32	240100										
		Quarter Corner	No Observation	Brass Cap	BLM	1954	B.C. 8" above ground.	Set 3/4" Brass Discs marked PLS 166642 on 3 BTs	3175163.056	673037.001	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
2922SE32	300100								"Utah Coordinate System 1983 South Zone"		
		Section Corner	No Observation	Brass Cap	BLM	1954	B.C. 9" above ground	Set 3/4" Brass Discs marked PLS 166642 on 2 BTs	3175180.429	673841.092	0
2922SW32	200100										
		Section Corner	No Observation	Brass Cap	BLM	1954	B.C. 1.1' above ground	Set 3/4" Brass Discs marked PLS 166642 on 3 BTs	3175144.133	672233.076	0
2923CE1615	460440										
		sixteenth corner	Existent	aluminum cap	BLM	0	fence line N/S	set in mound stone 40 ft. west HWY191	3181079.797	686171.4	6083.843
2923CS1615	440420										
		sixteenth corner	Existent	aluminum cap	BLM	1996	none	4" above grdd. lot 93 common corner	3180667.127	685778.075	6086.562
2923E08	300540										
		Quarter Corner	No Observation	Stone	GLO	0	12"X5" Stone 8" above ground	Set two 5/8" rebars with no cap as reference monuments	3182632.669	683319.281	0
2923E10	500540										
		quarter corner	Existent	aluminum cap	BLM	1996	none	6" above grnd.	3182704.848	686537.45	6115.069
2923E15	500440										
		quater corner	Existent	aluminum cap	BLM	1996	mound of stone W	10" above ground no BT's found	3181088.102	686572.944	6231.418
2923E1615/22	460400										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		sixteenthcorner	Existent	rebar	BLM	0	mound of stone	rebar W/ no cap alum. cap not found	3180271.424	686188.091	6061.874
2923E17	300440										
		Quarter Corner	No Observation	Aluminum Cap	GLO	2003	A.C. on rebar	Set new Mon. in deteriorated rock mound.	3181021.524	683355.835	0
2923E22	500340										
		quarter corner	Existent	aluminum cap	BLM	1996	Called For Monument		3179471.481	686611.994	6128.416
2923N04	340700										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	Orig B.C. monument	Set spike w/washer on 2 BTs	3185061.619	684077.723	0
2923N08	240600										
		Quarter Corner	No Observation	Stone	GLO	0	12"X6" stone 14" above ground	Found rebar with cap 1.5' south of monument.	3183420.771	682495.877	0
2923NE10	500600										
		section corner	Existent	aluminum cap	BLM	1996	none	stone pile, down 4x4 post & lath	3183513.136	686518.878	6083.658
2923S08	240500										
		Quarter Corner	No Observation	Stone	GLO	0	12"X2" stone 13" above ground	Found two original BTs	3181810.164	682533.117	0
2923S10	440500										
		quarter corner	Existent	aluminum cap	BLM	1996	none	6" above grnd 500 west HWY 191	3181884.306	685753.429	6128.122
2923S15	440400										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
"Utah Coordinate System 1983 South Zone"											
2923S22	440300	quarter corner	Existent	aluminum cap	BLM	1996	mound of stone north	6" above grnd.	3180262.946	685786.397	5997.954
2923SE08	300500	quarter corner	Existent	stone	GLO	0	none	reset in place stone is weathered	3178657.808	685824.206	5944.834
2923SE10	500500	Section Corner	No Observation	Aluminum Cap	GLO	2003	A.C. on rebar	Double proportion to set mon. Set two new BTs.	3181827.193	683338.021	0
2923SE15	500400	section corner	Existent	aluminum cap	BLM	1996	none	6" above grnd.	3181896.554	686556.167	6181.7
2923SE22	500300	section corner	Existent	aluminum cap	BLM	1996	mound of stone west	5" above grnd.	3180279.913	686589.761	6100.416
2923SW03	400600	section corner	Existent	stone	GLO	0	Called For Monument		3178675.013	686628.508	6060.224
2923SW04	300600	section corner	Existent	stone corner	GLO	0	none		3183473.87	684911.68	6018.225
2923SW08	200500	Section Corner	No Observation	Aluminum Cap	GLO	2000	Stone Upright 15" above ground	Set Spike and washer on two BTs	3183438.145	683300.542	0
2923SW10	400500	Section Corner	No Observation	Stone	GLO	0	Stone 10"X4"-18" above ground	Set spike and washers on two BTs	3181793.224	681728.21	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
2923SW15	400400	section corner	Existent	aluminum cap	BLM	1996	none	4" above grnd.	3181863.264	684949.273	6173.485
2923SW22	400300	section corner	Existent	aluminum cap	BLM	1996	BT s16 & s21	in mound of stone fence Inct S/E	3180246.089	684982.725	6010.211
2923SW27	400200	Section Corner	No Observation	Stone	GLO	0	Stone	Marked stone firmly set. Two RPs set N, and E	3178637.02	685021.854	0
2923W03	400640	Section Corner	No Observation	Stone	GLO	0	Stone	Marked stone firmly set. Two RPs set N, and E	3177028.276	685062.635	0
2923W04	300640	quarter corner	Obliterated	80P nail	GLO	0	fence corner	80P nail in stones	3184275.933	684889.262	6104.137
2923W08	200540	Quarter Corner	No Observation	Stone	GLO	2000	Stone 8" above ground	Referenced by two rebar and plastic cap	3184242.643	683281.971	0
2923W15	400440	Quarter Corner	No Observation	Stone	GLO	0	Stone 12"X4", 12" above ground	Set mag nail w/washer in two BTs.	3182598.355	681709.709	0
2923W22	400340	quater corner	Existent	aluminum cap	BLM	1996	mound of stone W	no BT's found	3181054.684	684966.162	6453.485

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Obliterated	rebar	local	0	subdivision plat	rebar and cap #171004 wilson arch resort	3179443.864	685000.691	5980.436
2924S08	240500										
		Quarter Corner	No Observation	Brass Cap	GLO	0	B.C. 3' in ground.	Buried appx 3' under ground	3182240.667	692393.848	0
2924SE03	500600										
		Section Corner	No Observation	Aluminum Cap	Private	0	A.C. flush with ground		3183928.141	696227.709	0
2924SE04	400600										
		Section Corner	No Observation	PK Nail	Private	0	PK nail w/RPs	In intersection of C.R. 149 & 151	3183866.795	694610.916	0
2924SE05CC	300600										
		Section Corner	No Observation	Brass Cap	GLO	1915	B.C. in stone ring.	In horse pasture E of SJC road 151 113 intersection.	3183864.011	692976.441	0
2924SE10WC	503500										
		Witness Corner	No Observation	Brass Cap	GLO	1915	B.C. 4" above ground	NE of C.R. 115 & 149 intersection	3182302.583	696265.43	0
2924SW09	302500										
		Section Corner	No Observation	Brass Cap	GLO	1915	B.C. 12" above ground	In N-S fence. E of 113 Big Indian Road	3182170.535	693012.349	0
2925NE31	200200										
		Section Corner	No Observation	Wood Post	Other	0	6"X6" Post		3177647.686	701356.853	0
2925NW31	100200										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		Section Corner	No Observation	Brass Cap	GLO	1915	B.C. 9" above ground	4"X4" post alongside monument	3177606.492	699741.453	0
<i>2925SE31</i>	<i>200100</i>										
		Section Corner	No Observation	Brass Cap	GLO	1916	B.C. 1.2' above ground	Brass cap on 1" pipe.	3176023.066	701400.788	0
<i>2925SW31</i>	<i>100100</i>										
		Section Corner	No Observation	Stone Mound	GLO	0	Mound of stone	Mound of stones 3'X2'X1'	3175983.966	699776.429	0
<i>2926NE05CC</i>	<i>297100</i>										
		Closing Corner	No Observation	Brass Cap	GLO	1922	B.C. 15" above ground	Monument in stone collar.	3185947.419	712494.749	0
<i>3023E10</i>	<i>500540</i>										
		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 3" above ground	Set 2 RPs	3171425.057	686022.8	0
<i>3023E11</i>	<i>600538</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 1' above ground	Set 2 RPs	3171460.881	687664.571	0
<i>3023E14</i>	<i>600438</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 7" above ground	Set 2 RPs	3169852.569	687694.204	0
<i>3023E15</i>	<i>500440</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 6" above ground	Set 2 RPs	3169817.631	686061.203	0
<i>3023E16</i>	<i>400440</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 3" above ground	Set 2 RPs	3169779.707	684452.751	0
<i>3023E17</i>	<i>300440</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 3" above ground	Set 2 RPs	3169745.254	682850.934	0

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3023E23	600338										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 1' above ground	Set 2 RPs	3168244.367	687727.206	0
3023N14	540500										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 8" above ground	Set 2 RPs	3170638.885	686845.791	0
3023NE11	600598										
		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 7" above ground	Set 2 RPs	3172265.041	687651.153	0
3023NE16	400500										
		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 10" above ground	Set 2 RPs	3170583.643	684433.426	0
3023NE17	300500										
		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 7" above ground	Set 2 RPs	3170549.05	682832.528	0
3023NE22	500400										
		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 4" above ground	Set 2 RPs	3169013.76	686080.638	0
3023NW12	600600										
		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 7" above ground	Set 2 RPs	3172276.511	687650.974	0
3023S09	340500										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 3" above ground	Set 2 RPs	3170566.307	683632.968	0
3023S14	540400										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 3" above ground	Set 2 RPs	3169030.878	686884.84	0
3023S16	340400										
		Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 8" above ground	Set 2 RPs	3168958.586	683670.711	0
3023S31	100140										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Lost	none	GLO	1925	NONE	NO TRACE	3164063.162	680572.448	6152.325
<i>3023S32</i>	<i>240100</i>										
		quarter corner	Existent	brass cap	GLO	1925	Original Monument	IN FENCELINE	3164103.059	682183.433	6190.227
<i>3023S32AP</i>	<i>237700</i>										
		Angle Point	Lost	none	GLO	0	None	No evidence remaining. Near cattle gathering pens.	3164098.434	682176.315	0
<i>3023S33</i>	<i>340100</i>										
		quarter corner	Existent	brass cap	GLO	1925	Original Monument	8" ABOVE GRND	3164139.515	683793.524	6172.185
<i>3023S34</i>	<i>440100</i>										
		quarter corner	Existent	brass cap	GLO	1925	Original Monument	STANDARD CORNER	3164178.93	685399.947	6206.985
<i>3023S35</i>	<i>540100</i>										
		quarter corner	Existent	brass cap	GLO	1925	OLD SC STONE ALONGSIDE	STONE	3164216.834	687007.943	6051.384
<i>3023SE02</i>	<i>602598</i>										
		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 1' above ground	Set 2 RPs	3172263.498	687611.966	0
<i>3023SE10</i>	<i>500500</i>										
		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 6" above ground	Set 2 RPs	3170621.502	686041.779	0
<i>3023SE14</i>	<i>600398</i>										
		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 8" above ground	Set 2 RPs	3169048.416	687710.369	0
<i>3023SE16</i>	<i>400400</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
"Utah Coordinate System 1983 South Zone"											
<i>3023SE17</i>		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 3" above ground	Set 2 RPs	3168975.791	684472.079	0
	<i>300400</i>										
<i>3023SE31AP</i>		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 3" above ground	Set 2 RPs	3168941.47	682869.352	0
	<i>197100</i>										
<i>3023SE32AP</i>		angle point	Lost	none	GLO	1902	NONE		3164081.572	681354.897	6211.362
	<i>297100</i>										
<i>3023SE33AP</i>		angle point	Existent	none	GLO	1902	NONE	fence1'S bears E&W	3164119.973	682967.046	6163.432
	<i>397100</i>										
<i>3023SW12</i>		angle point	Existent	stone corner	GLO	1884	BT remnants	stone AP	3164158.164	684574.226	6368.839
	<i>600500</i>										
<i>3023SW13</i>		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 3' above ground	Set 2 RPs	3170667.783	687677.834	0
	<i>600400</i>										
<i>3023SW31</i>		Section Corner	No Observation	Brass Cap	GLO	1925	B.C. 6" above ground	Set 2 RPs	3169059.476	687710.152	0
	<i>100100</i>										
<i>3023SW32</i>		section corner	Existent	brass cap	GLO	1911	BT,S31,S36, X IN ROCK	RESET ON X	3164043.77	679751.391	6151.665
	<i>200100</i>										
<i>3023SW33</i>		section corner	Existent	brass cap	GLO	1925	Original Monument	IN FENCELINE	3164082.111	681378.599	6210.665
	<i>300100</i>										
<i>3023SW34</i>		quarter corner	Existent	brass cap	GLO	1925	Original Monument	8" ABOVE GRND	3164120.423	682987.587	6162.405
	<i>400100</i>										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3023SW35	500100	section corner	Existent	brass cap	GLO	1925	BT,S33&34 dead on grnd	mndstone/new bt's	3164158.529	684594.951	6370.209
3023SW36	600100	section corner	Existent	brass cap	GLO	1925	Original Monument	@ DRY WASH	3164199.161	686203.643	6120.802
3023W12	600540	section corner	Existent	brass cap	GLO	1925	Original Monument	SC-6th St.Parallel	3164241.14	687810.914	5977.918
3023W13	600440	Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 2.5' above ground	Set 2 RPs	3171472.142	687664.403	0
3023W24	600340	Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 8" above ground	Set 2 RPs	3169863.629	687693.987	0
3024E16	400440	Quarter Corner	No Observation	Brass Cap	GLO	1925	B.C. 1.2' above ground	Set 2 RPs	3168255.427	687726.979	0
3024E31	200140	Quarter Corner	No Observation	Cap	Other	0	Marked Cap	From D.V. Blake notes 1966	3170015.822	694104.729	0
3024E32	300140	Section Corner	No Observation	Brass Cap	GLO	1919	B.C.	Monument set in stone Mound	3165113.177	691009.468	0
3024N32	240200	Quarter Corner	No Observation	Brass Cap	GLO	1919	B.C.	1.2' above ground	3165151.217	692616.013	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Quarter Corner	No Observation	Brass Cap	GLO	1919	B.C.	1.5' above ground.	3165936.191	691791.829	0
3024S31	140100										
		quarter corner	Existent	brass cap	GLO	1911	none	std crnr	3164291.593	690227.418	5905.898
3024S32	240100										
		quarter corner	Existent	aluminum cap	County	2006	BTs32	set 3" alum cap Std Crnr	3164328.788	691833.684	5884.459
3024S33	340100										
		quarter corner	Existent	brass cap	GLO	1911	BTs33	in mound of stone Std Crnr	3164366.12	693439.741	6291.181
3024S34	440100										
		witness corner	Existent	brass cap	GLO	1911	none	in mound of stone stnd crnr	3164406.275	695066.971	6299.32
3024SE16	400400										
		Section Corner	No Observation	Cap	Other	0	Marked Cap	From D.V. Blake notes 1966	3169211.866	694124.517	0
3024SE32	300100										
		section corner	Existent	brass cap	GLO	1911	none	std crnr	3164346.963	692635.96	6050.39
3024SE33	400100										
		section corner	Existent	brass cap	GLO	1911	BTs34-down	Std Crnr	3164385.559	694243.017	6172.664
3024SW29	200200										
		Section Corner	No Observation	Brass Cap	GLO	1919	B.C.	Monument set in mound of stone.	3165917.029	690987.776	0
		Section Corner	No Observation	Brass Cap	GLO	1919	B.C.	1.2' above ground	3165955.422	692595.881	0
3024SW32											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3024W22	200100	section corner	Existent	brass cap	GLO	1911	none	in smll rock pile std crnr	3164309.276	691031.409	5807.33
3024W22	400340	Quarter Corner	No Observation	Cap	Other	0	Marked Cp	From D.V. Blake notes 1966	3168407.719	694143.829	0
3025E25	700240	quarter corner	Existent	brass cap	GLO	1916	BT,s25		3167159.475	708640.963	6740.026
3025E36	700140	quarter corner	Existent	brass cap	GLO	1916	BT, s36,sS31		3165552.963	708681.726	6459.913
3025N25	640300	quarter corner	Existent	brass cap	GLO	1916	BTs,s24,s25	in mound of stone	3167946.951	707815.618	6613.39
3025N26	540300	quarter corner	Existent	brass cap	GLO	1916	none	6"abv grnd	3167903.942	706212.513	6366.925
3025N27	440300	quarter corner	Existent	brass cap	GLO	1916	none	16"shwng abv grnd	3167860.139	704608.179	6701.509
3025N34	440200	quarter corner	Existent	brass cap	GLO	1916	BT, s34	in mound of stone	3166254.135	704648.039	6634.371
3025N36	640200	quarter corner	Existent	brass cap	GLO	1916	none	in mnd of stn	3166338.781	707859.086	6524.261
3025NE04CC	323100										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Closing Corner	No Observation	Brass Cap	GLO	1916	B.C. 1.2' above ground	Wood post as guard alongside.	3176075.467	703587.373	0
3025NE25	700300										
		section corner	Existent	brass cap	GLO	1916	BTs,s19,s24,s25,s30	in mound of stone	3167961.387	708621.232	6593.635
3025NE36	700200										
		section corner	Existent	brass cap	GLO	1916	BT,s30	20"abv grnd	3166356.336	708661.351	6529.249
3025NW25	600300										
		section corner	Existent	brass cap	GLO	1916	none		3167926.432	707013.77	6357.935
3025NW26	500300										
		section corner	Existent	brass cap	GLO	1916	BTs,s22,s23,s26,s27	14" abv grnd	3167880.216	705409.77	6525.554
3025NW27	400300										
		section corner	Existent	brass cap	GLO	1916	none		3167842.144	703806.543	6728.741
3025NW34	400200										
		section corner	Existent	brass cap	GLO	1916	BTs,s27,s28,s33,s34	in mound of stone	3166233.402	703846.464	6552.042
3025S04	340600										
		Quarter Corner	No Observation	Brass Cap	GLO	1916	B.C. 2.7' above ground	In mound of stones.	3172646.529	702876.509	0
3025S24WC	640300										
		Witness Corner	No Observation	Aluminum Cap	Private	2011	A.C. on #6 rebar	Set RPs duplex nail and washer in cedar post and cedar tree	3158262.714	708197.578	0
3025s36	640100										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Existent	quarter corner	GLO	1916	none		3164729.694	707899.777	6497.658
3025SE04	400600										
		Section Corner	No Observation	Brass Cap	GLO	1916	B.C. 13" above ground	Monument in mound of stone.	3172668.98	703680.535	0
3025SE09	400500										
		Section Corner	No Observation	Brass Cap	GLO	1916	B.C. 1.8' above ground	Set in mound of stones.	3171058.582	703721.793	0
3025SE27	500200										
		section corner	Existent	brass cap	GLO	1916	none		3166274.217	705450.095	6504.136
3025SE36	700100										
		section corner	Existent	brass cap	GLO	1916	none		3164750.033	708702.818	6423.19
3025SW04	300600										
		Section Corner	No Observation	Brass Cap	GLO	1916	B.C. 12" above ground	In mound of stone with wood marker post.	3172624.147	702072.479	0
3025SW25	600200										
		section corner	Existent	brass cap	GLO	1916	none		3166318.456	707056.481	6628.989
3025SW31	700100										
		section corner	Existent	brass cap	GLO	1916	BTs36,s31	std crnr	3164505.15	699065.802	6263.882
3025SW31WC	100100										
		witness corner	Existent	brass cap	GLO	1916	BTs destroyed	not as described size & stamp differ	3164504.831	699054.333	6263.823
3025W23	500340										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3025W25	600240	quarter corner	Existent	brass cap	GLO	1916	steel post 1' N	reset	3168686.333	705389.427	6425.398
3025W26	500240	quarter corner	Existent	brass cap	GLO	1916	none		3167122.962	707031.834	6385.278
3025W27	400240	quarter corner	Existent	brass cap	GLO	1916	none	12"shwng abv grnd	3167078.252	705429.879	6477.117
3026NW32	200200	quarter corner	Existent	brass cap	GLO	1916	BTs,s28,s27		3167038.297	703829.156	6524.735
3026S30	140200	section corner	Existent	brass cap	GLO	1916	BTs,s29,s30,s31,s32		3166400.18	710268.701	6509.165
3026S31	140100	Quarter Corner	Existent	Aluminum Cap	BLM	2013	Original B.T.'s, S 30 & 31	Re-set In small stone pile by BLM in 2013	3166379.052	709466.121	6469.044
3026S32	240100	quarter corner	Existent	brass cap	GLO	1916	photo B100_0274	bent\ reset	3164770.206	709506.53	6420.088
3026SW32	200100	quarter corner	Existent	brass cap	GLO	1916	none	18"showing	3164813.62	711114.524	6310.814
3026SW33	300100	section corner	Existent	brass cap	GLO	1916	none	12"shwng abv grnd	3164791.966	710310.374	6341.351
3026W29		section corner	Existent	brass cap	GLO	1916	none	12"shwng abv grnd	3164834.916	711918.59	6449.729

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
									"Utah Coordinate System 1983 South Zone"		
<i>3026W20</i>	<i>200240</i>										
		quarter corner	Existent	brass cap	GLO	1916	none	6"blw grnd srfc	3167205.17	710247.475	6425.668
<i>3026W32</i>	<i>200140</i>										
		quarter corner	Existent	brass cap	GLO	1916	BT s31&mnd of stn 2'W	12"shwng abv grnd	3165595.792	710289.427	6358.705
<i>3122NE13CC</i>	<i>700500</i>										
		closing corner	Existent	brass cap	GLO	1911	BT, S.13		3159986.522	680016.275	6130.583
<i>3122NE24CC</i>	<i>700400</i>										
		closing corner	Existent	brass cap	GLO	1911	BT, S.13 in mnd stone		3158371.531	680050.237	6238.861
<i>3122NE25CC</i>	<i>700300</i>										
		section corner	Existent	brass cap	GLO	1911	BTs, S.25&24	MND STONES	3156765.625	680086.841	6193.783
<i>3122NE36CC</i>	<i>700200</i>										
		closing corner	Existent	brass cap	GLO	1911	BTs, S.35 & S.36	MND STONE	3155154.731	680125.767	6328.18
<i>3122S36</i>	<i>640100</i>										
		quarter corner	Existent	brass cap	GLO	1911	BTs, S.36&01		3153527.424	679356.187	6526.808
<i>3122SE01CC</i>	<i>700600</i>										
		closing corner	Existent	brass cap	GLO	1911	BT, S.1 & S.12		3161589.471	679981.502	6086.978
<i>3122SE36</i>	<i>700100</i>										
		section corner	Existent	brass cap	GLO	1911	BT, S.01		3153544.061	680161.1	6447.889
<i>3123E01</i>	<i>700640</i>										
		quarter corner	Existent	brass cap	GLO	1916	none	bent grnd level	3163468.206	689448.965	5983.485
<i>3123E12</i>	<i>700540</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Existent	aluminum cap	County	2006	cfm rusted out	set 3" alum cap copy from T31SR24E	3161855.233	689503.113	6017.658
<i>3123E13</i>	<i>700440</i>										
		quarter corner	Existent	brass cap	GLO	1916	BTs13, X in rock	reset N/S fence line	3160244.086	689552.417	5966.349
<i>3123E19</i>	<i>200340</i>										
		quarter corner	Existent	stone corner	GLO	1902	MND STONE	ONLY EVIDENCE	3158424.14	681606.38	6304.779
<i>3123e24</i>	<i>700340</i>										
		quarter corner	Existent	brass cap	GLO	1916	cnr N fence		3158629.967	689604.049	5951.288
<i>3123E25</i>	<i>700240</i>										
		quarter corner	Lost	none	other	0	none	pt in road mon not found	3157000.951	689655.145	6011.73
<i>3123E31</i>	<i>200140</i>										
		quarter corner	Existent	stone corner	GLO	1902	MND STONE		3155205.159	681679.284	6196.085
<i>3123E36</i>	<i>700140</i>										
		quarter corner	Existent	brass cap	GLO	1916	N/S fence		3155401.005	689709.011	6151.049
<i>3123N01</i>	<i>640700</i>										
		quarter corner	Lost	none	GLO	1884	NONE	25' S. of E&W fence	3164254.675	688620.057	5871.34
<i>3123N07</i>	<i>140600</i>										
		quarter corner	Existent	aluminum cap	County	2010	BT, S6	SET NEW MON FROM BT	3162424.464	680716.054	6065.654
<i>3123N09</i>	<i>340600</i>										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3123N19	140400	quarter corner	Lost	wood post	GLO	1902	POST REMNANTS		3162504.675	683927.298	6243.029
3123N20	240400	quarter corner	Existent	stone corner	GLO	1902	BT, S.18 S.19		3159211.331	680788.748	6279.414
3123N27	440300	quarter corner	Lost	none	GLO	1902	NONE	NO TRACE	3159248.495	682393.205	6205.588
3123N29	240300	quarter corner	Obliterated	other	other	2007	Possession/Surveys	IN WOOD POST	3157713.763	685647.92	6251.086
3123N30	140300	quarter corner	Existent	aluminum cap	County	2010	STONE MONUMENT	SET NEW MON @ STONE	3157640.225	682431.769	6349.567
3123N31	140200	quarter corner	Existent	aluminum cap	County	2010	BT, S30	SET NEW MON FROM BT	3157601.62	680819.711	6253.288
3123N32	240200	quarter corner	Existent	stone corner	GLO	1902	Original Monument		3155990.134	680854.183	6245.872
3123N33	340200	quarter corner	Lost	none	GLO	1902	OLD POST REMNANTS	IN FENCE LINE	3156030.814	682467.209	6268.365
3123N34	440200	quarter corner	Existent	stone corner	GLO	1902	MND STONE	ONLY EVIDENCE	3156070.508	684077.159	6465.934
		quarter corner	Existent	stone corner	GLO	1902	Original Stone	surveycap	3156106.633	685685.506	6287.561

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3123N35	540200	quarter corner	Lost	none	GLO	1902	NONE		3156142.755	687294.63	6076.854
3123NE12	700600	section corner	Existent	brass cap	GLO	1916	none		3162664.358	689476.067	6000.205
3123NE13	700500	section corner	Existent	brass cap	GLO	1916	none		3161048.343	689527.407	5974.515
3123NE30	200300	section corner	Existent	aluminum cap	County	2010	STONE MON	SET NEW MON @ STONE	3157619.42	681625.176	6236.497
3123NE31	200200	section corner	Lost	none	GLO	1902	NONE	NO TRACE	3156009.309	681660.849	6145.136
3123NW02CC	500700	closing corner	Obliterated	other	GLO	1902	Possession/Surveys	@ FENCE CORN	3164201.285	686304.071	6117.415
3123NW03CC	400700	closing corner	Existent	stone corner	GLO	1902	BT's, S3&S4	mnd stone	3164160.94	684692.909	6363.806
3123NW04CC	300700	closing corner	Existent	wood post	GLO	1902	WOOD POST REMNANT	6" BELOW GND, CC	3164122.784	683086.582	6159.98
3123NW05CC	200700	section corner	Lost	none	GLO	1902	NONE	CLOSING CORNER	3164084.42	681478.139	6197.986
3123NW06CC	100700										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3123NW14	500500	closing corner	Existent	brass cap	GLO	1911	ORIG. STONE	@ Fence Jct.	3164047.632	679924.689	6174.359
3123NW19	100400	section corner	Lost	none	GLO	1902	NONE	fence jct .n,e,w.	3160955.831	686377.246	6153.574
3123NW21	300400	section corner	Existent	stone corner	GLO	1902	ORIGINAL STONE	IN SAGE FLAT	3159193.073	680035.96	6313.649
3123NW28	300300	section corner	Existent	wood post	GLO	1902	Original Post	Fencecor. proj N&E	3159267.946	683195.349	6288.896
3123NW30	100300	section corner	Existent	stone corner	GLO	1902	MND.STONE		3157654.214	683230.239	6536.132
3123NW31	100200	section corner	Existent	stone corner	GLO	1902	BT, S. 19 MND STN		3157582.323	680069.073	6215.103
3123NW33	300200	section corner	Existent	aluminum cap	County	2010	BTs, S.30,31,25,36	reset newfrom BT's	3155976.306	680105.832	6290.079
3123NW34	400200	section corner	Lost	none	GLO	1902	NONE	IN FENCE LINE	3156052.66	683265.371	6330.958
3123NW35	500200	section corner	Obliterated	wood post	GLO	1902	Orig. Post alongside	@ fence jct.	3156088.468	684881.583	6278.351
3123S01	640600	section corner	Existent	stone corner	GLO	1902	MND.STONE	SURVEY CAP	3156125.392	686490.433	6176.422

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
"Utah Coordinate System 1983 South Zone"											
<i>3123S02</i>	<i>540600</i>	quarter corner	Lost	none	GLO	1884	NONE	NO TRACE	3162645.709	688670.636	6079.188
<i>3123S03</i>	<i>440600</i>	quarter corner	Existent	stone corner	GLO	1902	ORIGINAL STONE	RESET IN GRND	3162580.462	687145.42	6049.387
<i>3123S05</i>	<i>240600</i>	quarter corner	Lost	none	GLO	1902	NONE	post remnants	3162543.06	685535.421	6113.382
<i>3123S07</i>	<i>140500</i>	quarter corner	Lost	none	GLO	1902	NONE		3162462.716	682321.443	6244.143
<i>3123S08</i>	<i>240500</i>	quarter corner	Existent	stone corner	GLO	1902	BT,S7&18	RESET FROM BT'S	3160821.139	680749.496	6306.519
<i>3123S09</i>	<i>340500</i>	quarter corner	Lost	none	GLO	1902	NONE	NO TRACE	3160857.136	682358.549	6247.709
<i>3123S10</i>	<i>440500</i>	quarter corner	Lost	none	GLO	1920	FENCE 10' S	FENCE 10' S	3160900.614	683964.82	6223.234
<i>3123S11</i>	<i>540500</i>	quarter corner	Lost	none	GLO	1902	FENCELINE	on fenceline	3160936.09	685573.085	6172.384
<i>3123S12</i>	<i>640500</i>	quarter corner	Lost	none	GLO	1902	16' N. of Stone ?		3160974.406	687181.413	6182.069
<i>3123S13</i>	<i>640400</i>	quarter corner	Lost	none	GLO	1902	NONE	30' E. of wash	3161027.581	688720.652	6027.846

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Lost	stone corner	GLO	1902	Stone in area, moved!		3159417.277	688753.768	5983.994
3123S14	540400										
		section corner	Lost	none	GLO	1902	NONE	dirt work at location	3159354.964	687217.487	6106.168
3123S15	440400										
		quarter corner	Existent	stone corner	GLO	1902	BT remnants S22	STONES NORTH	3159322.845	685610.479	6441.821
3123S16	340400										
		quarter corner	Existent	stone corner	GLO	1902	BT, S15 & S23		3159286.14	684001.535	6575.292
3123S21	340300										
		quarter corner	Lost	none	GLO	1902	NONE		3157670.421	684034.807	6570.773
3123S23	540300										
		quarter corner	Lost	none	GLO	1902	NONE	ON N/S FENCELINE	3157750.319	687255.678	6092.516
3123S24	640300										
		quarter corner	Lost	none	GLO	1902	NONE	IN HWY ROW FENCE 7'E	3157798.606	688819.322	5984.882
3123S25	640200										
		quarter corner	Existent	stone corner	GLO	1885	BT's, S25,S36	E,S,W fence 20'S	3156181.649	688880.687	6108.479
3123S31	140100										
		quarter corner	Lost	none	GLO	1902	NONE		3154397.201	680893.993	6248.245
3123S32	240100										
		quarter corner	Existent	stone corner	GLO	1902	BT, S.5 and S.32		3154425.847	682502.696	6352.614
3123S33	340100										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3123S34	440100	quarter corner	Existent	stone corner	GLO	1902	BT, S.33		3154464.005	684115.615	6606.861
3123S35	540100	quarter corner	Existent	stone corner	GLO	1902	BT, S.34		3154500.233	685721.597	6239.293
3123S36	640100	quarter corner	Existent	stone corner	GLO	1902	MND.STONE ON N.		3154536.625	687331.411	6210.508
3123SE07	200500	quarter corner	Existent	aluminum cap	County	2006	MND STONES		3154574.29	688927.539	6103.27
3123SE09	400500	section corner	Lost	none	GLO	1902	NONE	NO TRACE OF STONE	3160839.329	681553.58	6264.705
3123SE11CC	600498	section corner	Lost	none	GLO	1902	NONE	@ WATERTANK	3160918.871	684762.931	6200.181
3123SE13	700400	closing corner	Lost	none	GLO	1902	NONE		3160995.424	687914.404	6092.646
3123SE14	600400	section corner	Existent	brass cap	GLO	1916	none	18"E N/S fence line	3159438.162	689578.287	5929.884
3123SE24	700300	section corner	Obliterated	other	other	0	1/2" Pipe, Survey Lath	1/2" pipe unknow origin	3159366.964	687978.581	5996.563
		section corner	Lost	none	other	0	none	pt in road ROW mon not found	3157821.571	689622.608	5991.48

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3123SE25	70200	section corner	Lost	none	other	0	none	pt in road row mon not found	3156206.354	689683.118	6029.417
3123SE33	400100	section corner	Existent	stone corner	GLO	1902	MND STONE		3154482.311	684918.627	6425.574
3123SW01	600600	Section Corner	Existent	Aluminum Cap	County	2012	DETERIORATED STN	PST WITH GRD PLAQ 2FT N	3162616.523	687856.009	6053.414
3123SW02	500600	section corner	Existent	stone corner	GLO	1902	Original Stone	@ N.S.fenceline	3162562.574	686340.583	6066.677
3123SW03	400600	section corner	Lost	none	GLO	1902	POST REMNANTS	post remnants	3162521.445	684730.359	6169.581
3123SW04	300600	section corner	Existent	stone corner	GLO	1902	BT, S4,5,8,9	reset from BT's	3162487.161	683123.115	6482.264
3123SW05	200600	section corner	Existent	stone corner	GLO	1902	BTs, S5,6,7,8	firmly set	3162444.913	681516.016	6120.763
3123SW06	100600	section corner	Existent	stone corner	GLO	1902	Original Stone	IN FENCELINE	3162406.699	679961.816	5989.492
3123SW07	100500	section corner	Existent	aluminum cap	County	2010	BT, S.18, REMAINS S.13		3160803.747	679999.304	6322.24
3123SW09	300500										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3123SW12	600500	section corner	Lost	none	GLO	1902	NONE		3160878.749	683159.273	6485.008
3123SW14	500400	section corner	Lost	none	GLO	1902	INCONCLUSIVE	IN SPARSE SAGE	3161006.893	687913.947	6094.785
3123SW15	400400	section corner	Existent	stone corner	GLO	1902	Original Stone	& CEDAR POST	3159340.634	686413.351	6202.13
3123SW16	300400	section corner	Lost	none	GLO	1902	NONE	N/S fence 10'E	3159304.755	684806.002	6312.294
3123SW17	200400	section corner	Existent	brass cap	GLO	1916	none	Mon. bent over	3159490.705	692931.68	5962.027
3123SW22	400300	section corner	Existent	stone corner	GLO	1902	BT's, S. 18, 19, 20		3159230.231	681588.795	6315.752
3123SW23	500300	section corner	Obliterated	other	Local	2007	RLS 171004 survey cap	survey cap	3157694.883	684844.648	6317.23
3123SW24	600300	section corner	Obliterated	other	other	2007	Post, RLS171004 surv. cap	Post & Cap in post	3157731.988	686451.652	6167.448
3123SW25	600200	section corner	Lost	none	GLO	1902	NONE	rockslide	3157763.743	688035.214	6174.824
3123SW31	100100	section corner	Obliterated	other	other	2004	FENCE JCT.	@ FNC.JCT.	3156156.708	688079.183	6043.344

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		section corner	Existent	brass cap	GLO	1911	ORIGINAL MONUMENT		3154372.841	680141.973	6397.005
3123SW32	200100										
		section corner	Existent	aluminum cap	County	2010	STONE MOUND	SET NEW MON FR ROCK&CC	3154408.06	681701.431	6211.399
3123SW33	300100										
		section corner	Existent	stone corner	GLO	1902	Original Stone	IN OPEN SAGE	3154444.03	683305.202	6411.93
3123SW35	500100										
		section corner	Existent	stone corner	GLO	1902	MOUNDSTONE	Tpost 2'E&S OF MON	3154517.69	686527.276	6218.219
3123SW36	600100										
		section corner	Existent	stone corner	GLO	1902	BT, S.1,2,36	RESET IN MOUND	3154555.68	688131.701	6333.22
3123W01	600640										
		quarter corner	Lost	none	GLO	1884	NONE		3163431.08	687843.114	5971.837
3123W02	500640										
		quarter corner	Lost	none	GLO	1902	NONE	IN N/S FENCE	3163366.863	686322.817	6105.465
3123W03	400640										
		quarter corner	Lost	none	GLO	1902	post remnants??	post remnants	3163325.623	684711.995	6225.766
3123W04	300640										
		quarter corner	Lost	other	GLO	1902	BT ?	CROSS NOT FOUND	3163287.421	683105.503	6296.91
3123W05	200640										
		quarter corner	Lost	none	GLO	1902	STONE FRAGMENTS	Near stone	3163249.103	681497.692	6141.317

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3123W06	100640							pieces			
		quarter corner	Existent	stone corner	GLO	1902	BT's, S6 & S1	mnd stone	3163207.491	679942.016	6078.627
3123W07	100540										
		quarter corner	Existent	stone corner	GLO	1902	BT, S.1		3161604.861	679981.796	6085.908
3123W08	200540										
		quarter corner	Existent	stone corner	GLO	1902	Marked stone	post alongside	3161638.617	681534.646	6221.952
3123W10	400540										
		section corner	Lost	none	GLO	1902	POST REMNANTS	post remnants	3161719.222	684748.916	6164.669
3123W11	500540										
		quarter corner	Lost	none	GLO	1902	FENCELINE	on fence line	3161758.358	686358.39	6107.76
3123W12	600540										
		quarter corner	Lost	none	GLO	1902	Very Old Fence	3'W. VERY OLD FENCE	3161816.701	687881.69	6129.293
3123W13	600440										
		quarter corner	Lost	none	GLO	1902	NONE	NO TRACE	3160196.893	687946.141	6042.333
3123W14	500440										
		quarter corner	Lost	none	GLO	1902	NONE	NO TRACE	3160144.869	686395.067	6175.38
3123W15	400440										
		quarter corner	Lost	none	GLO	1902	NONE	N/Sfence5'E	3160108.933	684787.638	6268.058
3123W16	300440										
		quarter corner	Existent	stone corner	GLO	1902	ORIGINAL STONE		3160071.554	683178.216	6281.11

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3123W17	200440	quarter corner	Lost	none	GLO	1902	POST REMNANTS	post remnants	3160034.348	681570.504	6143.17
3123W18	100440	quarter corner	Existent	aluminum cap	County	2010	BT, S.18	Set New Monument	3159996.347	680016.877	6123.117
3123W19	100340	quarter corner	Existent	aluminum cap	County	2010	BT, S19	SET NEW MON FROM BT	3158386.368	680052.848	6245.508
3123W21	300340	quarter corner	Lost	none	GLO	1902	NONE	NO EVIDENCE	3158458.318	683212.08	6359.555
3123W22	400340	quarter corner	Lost	none	GLO	1902	NONE	IN CHAINED AREA	3158501.145	684826.418	6533.623
3123W23	500340	quarter corner	Lost	none	GLO	1902	NONE	NO TRACE	3158536.363	686431.582	6214.272
3123W24	600340	quarter corner	Lost	none	GLO	1902	NONE	FENCE JCT 22'E	3158563.942	688003.284	6043.201
3123W25	600240	quarter corner	Lost	none	GLO	1902	NONE	in fenceline	3156959.4	688055.938	6060.479
3123W26	500240	quarter corner	Existent	stone corner	GLO	1902	ORIGINAL STONE	& survey cap	3156929.072	686471.934	6185.604
3123W27	400240										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3123W28</i>	<i>300240</i>	quarter corner	Obliterated	other	GLO	1902	FENCE JNCT.	Fence Jct.	3156891.294	684863.688	6301.662
<i>3123W29</i>	<i>200240</i>	quarter corner	Lost	none	GLO	1902	NONE		3156849.871	683248.52	6317.438
<i>3123W30</i>	<i>100240</i>	quarter corner	Existent	stone corner	GLO	1902	MOUND STONE		3156813.843	681645.058	6180.079
<i>3123W31</i>	<i>100140</i>	quarter corner	Existent	stone corner	GLO	1902	BT, S.24		3156779.851	680086.627	6196.239
<i>3123W33</i>	<i>300140</i>	quarter corner	Existent	stone corner	GLO	1902	BT, S.31		3155174.771	680125.431	6330.196
<i>3123W34</i>	<i>400140</i>	quarter corner	Existent	aluminum cap	County	2010	ORIGINAL POST		3155245.013	683287.09	6394.385
<i>3123W35</i>	<i>500140</i>	quarter corner	Existent	stone corner	GLO	1902	ORIGINAL STONE		3155285.09	684900.611	6281.506
<i>3123W36</i>	<i>600140</i>	quarter corner	Existent	stone corner	GLO	1902	ORIGINAL STONE		3155321.281	686509.287	6139.399
<i>3123W9</i>	<i>300540</i>	quarter corner	Lost	none	GLO	1902	NONE	IN FENCELINE	3155358.7	688103.581	6117.21
<i>3124E01</i>	<i>700640</i>	quarter corner	Lost	none	GLO	1902	NONE	NO TRACE	3161682.932	683141.199	6305.753

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Existent	brass cap	GLO	1916	BT,s01		3163660.178	699257.539	6629.687
<i>3124E05</i>	<i>300640</i>										
		quarter corner	Existent	brass cap	GLO	1916	none		3163509.948	692833.026	5885.299
<i>3124E06</i>	<i>200640</i>										
		quarter corner	Existent	brass cap	GLO	1916	none	mound of stone to W	3163470.055	691227.839	5833.696
<i>3124E09</i>	<i>400540</i>										
		witness corner	Existent	aluminum cap	County	2006	BO x on snd stn face	set 3" alum cap in stone mound	3161886.497	694485.821	6025.986
<i>3124E15</i>	<i>500440</i>										
		quarter corner	Existent	aluminum cap	County	2006	cfm pipe stem	set 3" alum cap rusted in half	3160374.861	696129.858	5895.984
<i>3124E16</i>	<i>400440</i>										
		quarter corner	Lost	none	other	0	fence	fnc pst @ locus old fnc 60 ft W.	3160328.953	694526.935	5866.296
<i>3124E23</i>	<i>600340</i>										
		quarter corner	Existent	brass cap	GLO	1916	none		3158800.918	697770.464	5917.24
<i>3124E24</i>	<i>700340</i>										
		witness corner	Existent	brass cap	GLO	1916	none		3158868.996	699380.893	6012.54
<i>3124E25</i>	<i>700240</i>										
		quarter corner	Existent	brass cap	GLO	1916	BT s30, s25	in mound of stone BT s25 down	3157236.786	699421.069	6067.713
<i>3124N07</i>	<i>140600</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Existent	aluminum cap	County	2006	stem of 1916 BC	rusted out set 3" alum cap	3162650.288	690449.09	5842.513
<i>3124N08</i>	<i>240600</i>										
		quarter corner	Existent	aluminum cap	County	2006	stem of 1916 BC	rusted out set 3" alum cap	3162686.361	692051.143	5822.262
<i>3124N17</i>	<i>240500</i>										
		quarter corner	Existent	brass cap	GLO	1916	none		3161078.415	692088.426	5896.27
<i>3124N32</i>	<i>240200</i>										
		quarter corner	Existent	brass cap	GLO	1916	BT, s29,s32	reset from BT FROM BT s32	3156259.879	692208.21	7190.104
<i>3124N33</i>	<i>340200</i>										
		quarter corner	Existent	brass cap	GLO	1916	none	area railed	3156298.517	693817.851	7114.222
<i>3124N34</i>	<i>440200</i>										
		quarter corner	Existent	brass cap	GLO	1916	BT, s34	reset, fnd bent/buried in place	3156334.069	695425.344	7066.1
<i>3124N35</i>	<i>540200</i>										
		quarter corner	Existent	brass cap	GLO	1916	BTs35	in mound of stone	3156373.071	697028.032	7071.281
<i>3124NE01</i>	<i>700700</i>										
		closing corner	Existent	brass cap	GLO	1916	none	CC crnr N/S fence line 4ft E	3164509.404	699240.148	6256.827
<i>3124NE05</i>	<i>300700</i>										
		closing corner	Existent	aluminum cap	County	2006	BT,s04	out of position set 3"cap senior ln.	3164351.176	692811.949	6057.063
<i>3124NE06</i>	<i>200700</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		closing corner	Existent	brass cap	GLO	1916	none	N/E06 N/W05	3164313.381	691208.101	5812.985
<i>3124NE07</i>	<i>200600</i>										
		section corner	Existent	brass cap	GLO	1916	BT s06,		3162666.908	691247.259	5885.465
<i>3124NE08</i>	<i>300600</i>										
		section corner	Existent	aluminum cap	County	2006	BT,s9 stone mnd	set 3" alum cap BTs4,s5,s8 down	3162705.288	692852.429	6007.53
<i>3124NW03</i>	<i>400700</i>										
		closing corner	Existent	brass cap	GLO	1916	none	in mound of stone CC corner	3164390.091	694425.371	6379.548
<i>3124NW06</i>	<i>100700</i>										
		section corner	Existent	other	GLO	0	mound of stone 2ftN/E	chisled X in Bedrock	3164273.318	689423.264	5909.069
<i>3124NW07</i>	<i>100600</i>										
		section corner	Existent	brass cap	GLO	1916	none		3162630.552	689477.034	6004.619
<i>3124NW16</i>	<i>300500</i>										
		section corner	Lost	none	other	0	fence jnct	S/E fence jnct	3161098.428	692891.865	5859.14
<i>3124NW18</i>	<i>100500</i>										
		section corner	Existent	brass cap	GLO	1916	none		3161023.734	689528.167	5973.051
<i>3124NW19</i>	<i>100400</i>										
		section corner	Existent	brass cap	GLO	1916	none	6"E N/S fence line	3159417.171	689578.437	5929.305
<i>3124NW33</i>	<i>300200</i>										
		section corner	Existent	brass cap	GLO	1916	BTs28	in N/S fnc line	3156278.88	693011.734	7160.323

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
									@ S gate post		
3124NW34	400200										
		section corner	Existent	brass cap	GLO	1916	BT,s34	reset from BT s34	3156315.567	694621.699	7093.66
3124NW35	500200										
		section corner	Existent	brass cap	GLO	1916	none		3156356.213	696225.942	7109.128
3124S03	440600										
		quarter corner	Existent	brass cap	GLO	1916	BTs10,s03	in mound of stone BTs03 down	3162766.937	695270.373	6429.783
3124S04	340600										
		quarter corner	Existent	brass cap	GLO	1916	none		3162723.017	693658.235	6024.316
3124S07	140500										
		quarter corner	Existent	brass cap	GLO	1916	none		3161042.545	690481.499	5896.589
3124S09	340500										
		quarter corner	Existent	brass cap	GLO	1916	none		3161116.202	693698.215	5850.557
3124S10	440500										
		quarter corner	Existent	aluminum cap	County	2006	mound of stone	set 3" alum cap BT not as desc.	3161152.488	695307.913	5953.163
3124S15	440400										
		quarter corner	Existent	brass cap	GLO	1916	BT, S15	date from notes mon not stamped	3159547.466	695346.948	5952.756
3124S16	340400										
		quarter corner	Existent	brass cap	GLO	1916	none		3159508.886	693738.418	5952.099

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3124S17	240400	quarter corner	Existent	brass cap	GLO	1916	none		3159470.813	692128.407	5996.304
3124S18	140400	quarter corner	Existent	brass cap	GLO	1916	none	E/W fence line	3159435.013	690522.161	5955.295
3124S24	640300	quarter corner	Lost	none	other	0	hub & tack	ucfm @ locusbottom land	3158016.968	698597.496	5936.058
3124S32	240100	quarter corner	Existent	brass cap	GLO	1911	none	in railed area	3154652.449	692247.164	7180.666
3124S33	340100	quarter corner	Lost	none	other	0	none	pt in railed area	3154690.815	693855.053	7087.551
3124S34	440100	quarter corner	Existent	brass cap	GLO	1911	none	in S/E fnc crnr in cleared land	3154728.895	695463.613	7011.012
3124SE03	500600	section corner	Existent	brass cap	GLO	1916	none		3162785.446	696073.523	6756.467
3124SE04	400600	section corner	Existent	brass cap	GLO	1916	BT, s09		3162740.865	694465.353	6006.04
3124SE09	400500	section corner	Existent	brass cap	GLO	1916	BT,s09,s16	crnr in N/S fence lin	3161132.823	694504.582	5912.899
3124SE10	500500										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3124SE14	600400	section corner	Existent	brass cap	GLO	1916	BT,s10		3161175.304	696111.673	5942.023
3124SE15	500400	section corner	Existent	brass cap	GLO	1916	none		3159605.065	697750.936	5950.224
3124SE16	400400	section corner	Existent	brass cap	GLO	1916	none	in E/W fence line	3159570.55	696147.638	5939.142
3124SE23	600300	section corner	Existent	brass cap	GLO	1916	none		3159524.443	694546.07	5929.122
3124SE25	700200	section corner	Existent	brass cap	GLO	1916	none		3157997.33	697790.574	5960.935
3124SE33	300100	section corner	Existent	brass cap	GLO	1916	RM S31, RM S36	on edge of wash loss of monument	3156432.651	699440.092	5964.385
3124SW08	200500	section corner	Lost	none	other	0	none	pt in road way	3154670.619	693050.985	7122.71
3124SW17	200400	section corner	Existent	brass cap	GLO	1916	none		3161058.636	691285.745	5969.393
3124SW19	100300	section corner	Existent	brass cap	GLO	1916	none	in E/W fence line bent over grnd level	3159450.129	691325.711	6024.913
		section corner	Lost	none	other	0	none	pt in road row mon wired to fence	3157808.754	689622.875	5992.491

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3124SW30	100200	section corner	Lost	none	other	0	none	pt in road row no mon found	3156202.419	689683.333	6030.571
3124SW31	100100	section corner	Existent	stone corner	GLO	0	none	crnr in rck pile crnr@N/W fence jnc.	3154594.668	689732.805	6123.076
3124SW34	400100	section corner	Existent	brass cap	GLO	1911	none	5ft W of 2 track	3154709.845	694659.247	7062.265
3124SW35	500100	section corner	Existent	brass cap	GLO	1911	none	in S,E/W fnc ln	3154748.473	696266.107	7015.366
3124W03	400640	quarter corner	Existent	brass cap	GLO	1916	BT,s03,s04	in mound of stone edge of canyon	3163551.178	694445.433	6385.286
3124W06	100640	quarter corner	Lost	none	other	0	none	pt in road no mon found	3163434.684	689449.995	5986.193
3124W07	100540	quarter corner	Existent	aluminum cap	County	2006	stem of 1916 BC	rusted out set 3" alum cap	3161827.672	689504.074	6023.056
3124W08	200540	quarter corner	Existent	aluminum cap	local	2007	photo B100_0035	bent over set new alum cap	3161863.044	691266.809	5979.29
3124W09	300540	quarter corner	Existent	brass cap	GLO	1916	BTs09	by post in grnd	3161903.242	692872.086	5839.678

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3124W16	300440	quarter corner	Existent	brass cap	GLO	1916	none	BTs not found	3160294.62	692911.509	5971.172
3124W17	200440	quarter corner	Existent	brass cap	GLO	1916	none		3160254.246	691305.22	5961.794
3124W18	100440	quarter corner	Existent	brass cap	GLO	1916	none	crnr n/e fence	3160220.344	689553.128	5973.66
3124W19	100340	quarter corner	Existent	brass cap	GLO	1916	8"x10"R R Tie 1ft N		3158613.09	689604.294	5951.071
3124W26	500240	quarter corner	Existent	brass cap	GLO	1916	BT, s26,s27		3157159.749	696207.356	7062.162
3124W28	300240	quarter corner	Existent	brass cap	GLO	1916	BTs28,29	in N/S fence BTs29 down	3157082.392	692991.297	7164.013
3124W30	100240	quarter corner	Lost	none	other	0	none	pt in road no mon found	3156992.418	689655.894	6012.051
3124W31	100140	quarter corner	Existent	brass cap	GLO	1916	N/S fence		3155398.383	689709.171	6151.183
3124W33	300140	quarter corner	Lost	none	other	0	none	pt in road way	3155474.754	693031.331	7144.123
3124W34	400140	section corner	Existent	brass cap	GLO	1916	BT, s34	reset, fnd bent/buried in	3155513.431	694640.078	7125.997

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
3124W35	500140							place			
		quarter corner	Existent	brass cap	GLO	1916	none		3155551.914	696245.748	7095.374
3126	140200										
		Quarter Corner	No Observation	Brass Cap	GLO	0	B.C. bent over in stones	Set RPs duplex nail and washer in two cedar trees	3156696.129	709847.957	0
3126NW04	300700										
		closing corner	Existent	brass cap	GLO	1917	none	16"abv grnd	3164837.923	712049.949	6446.002
3126NW05	200700										
		closing corner	Existent	brass cap	GLO	1917	none		3164795.154	710443.341	6320.781
3126NW06	100700										
		closing corner	Existent	brass cap	GLO	1917	none		3164753.837	708835.632	6414.056
3126S19	140300										
		Quarter Corner	No Observation	Brass Cap	GLO	0	B.C. buried and bent over	Set RPs duplex nail and washer in two cedar posts	3158303.284	709804.793	0
3126SE19	200300										
		Section Corner	No Observation	Survey Cap	Private	0	#5 rebap plastic cap LS 155675	Set RPs in cedar fence posts	3158323.206	710608.948	0
3223E13	700440										
		Quarter Corner	No Observation	Brass Cap	GLO	1911		Found in Place	3149809.522	689993.581	0
3223E24	700340										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Quarter Corner	No Observation	Brass cap	GLO	1911		Found in Place	3148216.925	690032.794	0
3223E26	598240										
		Quarter Corner	No Observation	Brass Cap	GLO	1911		Found in Place	3146493.407	688457.667	0
3223E30	200240										
		Quarter Corner	No Observation	Brass Cap	GLO	1917	B.C. 14" above ground	Found bent over flat to ground. Both BTs dead and out of position.	3146350.448	682003.078	0
3223N13	640500										
		Quarter Corner	No Observation	Brass cap	GLO	1911		Found in Place,BT in S13	3150577.37	689130.479	0
3223N24	640400										
		Quarter Corner	No Observation	Called For Monument	GLO	1911		ROS 333	3149004.634	689208.578	0
3223NE13	700500										
		Section Corner	No Observation	Brass Cap	GLO	1912		Found in Place at Fence Corners	3150596.858	689974.57	0
3223NE13AP	700507										
		Angle Point	No Observation	Brass Cap	GLO	1917		Found laying loose at fence corner	3150630.788	689973.782	0
3223NE24CC	700400										
		Closing Corner	No Observation	Brass Cap	GLO	1911		Corner Card dated Nov. 2005	3149023.172	690011.769	0
3223NE26WC	600300										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Witness Corner	No Observation	Plastic Cap/Re-bar	Private	1997		Set as per ROS 236, Orig. corner in Hwy.	3147298.592	688439.362	0
3223NE29	300300										
		Section Corner	No Observation	Brass Cap	GLO	1917	B.C. 10" above ground	In N-S fence, 22' S of fence corner fences prj. S and West from corner	3147190.608	683588.389	0
3223NW01CC	600700										
		closing corner	Existent	brass cap	GLO	1917	BT's, S.1 & S.2	STONE MOUND	3154558.324	688233.886	6310.653
3223NW02CC	500700										
		closing corner	Existent	brass cap	GLO	1917	Original Monument	Tpost 2' E&S	3154520.708	686634.662	6216.752
3223NW03CC	400700										
		closing corner	Existent	brass cap	GLO	1917	BT, S.4	STONE MOUND	3154485.384	685028.823	6325.376
3223NW04CC	300700										
		closing corner	Existent	brass cap	GLO	1917	BT, S.4 and S.5		3154447.491	683422.639	6450.177
3223NW05CC	200700										
		closing corner	Existent	brass cap	GLO	1917	BTs, S.5 and S.6		3154410.616	681816.591	6250.467
3223NW24	600400										
		Section Corner	No Observation	Brass Cap	GLO	1917		Set 2 B.O.'s S13, S23 in 2007	3148976.172	688404.826	0
3223NW29	200300										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Section Corner	No Observation	Brass Cap	GLO	1917	B.C. 14" above ground	28' S of E-W fence	3147154.894	681983.473	0
3223NW35	600200										
		Section Corner	No Observation	Brass Cap	GLO	1917		Corner Card dated Nov. 2005	3145689.702	688464.415	0
3223S24	640300										
		Quarter Corner	No Observation	Stone	GLO	1884	Orig. Stone	Corner Card dated Nov. 2005	3147396.063	689248.01	0
3223S29	240200										
		Quarter Corner	No Observation	Brass Cap	GLO	1917	B.C. 15" above ground	Bent over to ground by chaining project.	3145563.697	682824.598	0
3223S30	140200										
		Quarter Corner	No Observation	Brass Cap	GLO	1917	B.C. 17" above ground	Bent two BTs are dead and out of place.	3145528.69	681219.146	0
3223S32	240100										
		Quarter Corner	Existent	Brass Cap	GLO	1917	ORIG BTs	set 1 new BT	3143959.89	682862.297	7388.896
3223SE24	700300										
		Section Corner	No Observation	Stone	GLO	1884	Orig. Stone	Corner Card dated Nov. 2005	3147410.654	690053.031	0
3223SE29	300200										
		Section Corner	No Observation	None	None	0	BTs dead out of position	Four BTs dead down out of position.	3145581.48	683626.499	0
3223SE30	200200										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Section Corner	No Observation	Brass Cap	GLO	1917	B.C. 13" above ground	Near large stone mound, one remaining BT	3145545.993	682022.684	0
3223W13WC	600440										
		Quarter Corner	No Observation	Brass Cap	GLO	1917		Corner Card dated Nov. 2006	3149786.868	688403.612	0
3223W24	600340										
		Quarter Corner	No Observation	Stone	GLO	0	Original Stone	Beneath "X" chiseled in ledge. Place mag nail and washer in X	3148166.227	688406.39	0
3224NW06	100700										
		closing corner	Existent	brass cap	GLO	1911	none	3"brass cap	3154597.932	689880.738	6139.288
3224NW31CC	100200										
		Closing Corner	No Observation	Brass Cap	GLO	1911		Monument for 3223NE26 laying on ground nearby.	3145727.644	690068.261	0
3225NE01	700700										
		section corner	Obliterated	aluminum cap	Local	1989	NONE	buried in roadway LS#5705	3155069.247	709085.634	7079.953
3226C29	240240										
		Quarter Corner	No Observation	Aluminum Cap	Private	2002	A.C. in Mound of stone	Set cap LS4938755 RPs NE & SE in fenceline	3147077.076	711697.21	0
3226E16	400440										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C. 14" above ground	Set new RPs 60d nail and 2"	3150357.595	714029.272	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
								washer in tree and fence post			
3226E28	400240	Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C. on iron pipe	Set two RMs in fence N & S of corner washer and nail	3147138.818	714107.501	0
3226NE21	400400	Section Corner	No Observation	Brass Cap	GLO	1911	B.C.	Set two RMs on fence posts 2" washer and 60d nail	3149552.552	714048.205	0
3226NE26	600300	Section Corner	No Observation	Brass Cap	GLO	1911	B.C. on iron pipe	Set RMs in fence 2" washer and 60d nail.	3147990.01	715855.196	0
3226NE29	300300	Section Corner	Existent	Brass Cap	GLO	1911	RP SET 1961	MAGNET MEMORIAL-IN VAULT	3147903.049	712484.953	7027.362
3226S08	240500	Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C. 8" above ground	1.5' S of fence corner set RMs on fence post N & E	3151100.791	711599.056	0
3226S28	340200	Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C.	Set two RMs washer and 60d nail in fence post & powerpole	3146313.832	713323.227	0
3226S29	240200										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C.	Set two RMs in fencepost. N-E-W fence junction	3146272.892	711717.14	0
3226SE28	400200										
		Section Corner	No Observation	Brass Cap	GLO	1911	B.C.	One BT remains and set two RMs on two more trees	3146334.568	714126.67	0
3226SW29	200200										
		Section Corner	No Observation	Brass Cap	GLO	1911	B.C.	At fence junction. Projecting N,S,E,W	3146252.689	710914.507	0
3226W29	200240										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C.	In fenceline S of C.R.329	3147056.505	710894.568	0
3320N34	440200										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C. 18" above ground	Two BTs in relatively open area. Gentle Slope SE	3135385.038	657521.535	0
3321 SE07	200500										
		Section Corner	No Observation	Stone	GLO	0	Marked Stone	One BT remains. Well notched stone.	3140319.872	663020.641	0
3321E7	200540										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C. 16" above ground	One BT in S7	3141124.103	663002.695	0
3322W14	500440										
		Quarter Corner	Existent	Stone Corner	GLO	1906	ORIG. STONE/ALUM. GAURD POST	IN MND. STONE SET B.T. SEC. 14	3139819.219	677387.634	8412.782

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3323C07</i>	<i>140540</i>										
		quarter corner	Existent	aluminum cap	BLM	1993	mound		3141497.023	681324.361	7759.487
<i>3323C08</i>	<i>240540</i>										
		quarter corner	Existent	aluminum cap	BLM	1993	mound		3141534.029	682927.47	7644.359
<i>3323C09</i>	<i>340540</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	mound \ post	shot as an offset	3141570.754	684535.585	7412.476
<i>3323C17</i>	<i>240440</i>										
		quarter corner	Existent	aluminum cap	BLM	1993	mound	shot as an offset	3139920.242	682965.179	7692.946
<i>3323C34</i>	<i>440140</i>										
		quarter corner	Existent	aluminum cap	USFS	1988	posts		3135167.008	686287.168	7537.882
<i>3323CE1609</i>	<i>360540</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	steel post	shot as an offset	3141578.791	684935.496	7333.506
<i>3323CE1617</i>	<i>260440</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	mound		3139929.59	683371.879	7601.665
<i>3323CN1609</i>	<i>340560</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	mound		3141975.678	684526.504	7367.352
<i>3323CN1617</i>	<i>240460</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	mound		3140322.372	682955.29	7643.246
<i>3323CN1634</i>	<i>440160</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		sixteenth corner	Existent	aluminum cap	County	2005	RM's	set 3" alum. cap from RM's	3135566.237	686279.204	7521.454
<i>3323CN1635</i>	<i>540160</i>										
		sixteenth corner	Existent	aluminum cap	USFS	1985	in mound of stone	fenceline	3135602.696	687888.047	7244.318
<i>3323CNNW35</i>	<i>520170</i>										
		64th	Existent	aluminum cap	USFS	1985	signs	64 corner	3135794.09	687480.977	7299.672
<i>3323CS1617</i>	<i>240420</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	mound		3139525.11	682974.613	7671.441
<i>3323CS1626</i>	<i>540220</i>										
		sixteenth corner	Existent	aluminum cap	USFS	1985	mound	in open pasture	3136405.678	687871.633	7275.872
<i>3323CW1607</i>	<i>120540</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	mound	shot as an offset	3141488.922	680922.073	7815.179
<i>3323CW1617</i>	<i>220440</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	post		3139910.794	682565.589	7782.981
<i>3323CW1634</i>	<i>420140</i>										
		sixteenth corner	Existent	aluminum cap	USFS	1988	posts		3135158.227	685885.987	7617.839
<i>3323CWNENW35</i>	<i>525170</i>										
		256th	Existent	aluminum cap	USFS	1985	signs	256 corner sec 35	3135796.385	687581.719	7271.506
<i>3323E04</i>	<i>400640</i>										
		quarter corner	Existent	aluminum cap	BLM	1993	mound		3143208.369	685288.204	7226.001

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3323E09	400540	quarter corner	Existent	aluminum cap	BLM	1993	mound of rock	in fence in highway shot as an offset	3141586.616	685335.477	7239.43
3323E11	600540	quarter corner	Lost	none	other	0	none	in wheat field	3141664.981	688548.599	7002.487
3323E16	400440	quarter corner	Lost	none	other	0	fenceline	fenceline	3139963.733	685369.209	7422.989
3323E1604/09	360600	sixteenth corner	Existent	aluminum cap	BLM	1993	mound	e1/6 04/09	3142388.406	684918.818	7340.013
3323E1608/17	260500	sixteenth corner	Existent	aluminum cap	BLM	1993	mound	e1/16 08/17	3140736.786	683348.195	7561.067
3323E17	300440	quarter corner	Existent	aluminum cap	BLM	1993	rocks		3139938.785	683779.223	7431.247
3323E19	200340	quarter corner	Lost	none	other	0	none	none	3138280.923	682195.845	8055.473
3323E27	500240	quarter corner	Existent	aluminum cap	USFS	1985	mound \ sign		3136788.864	687059.432	7339.451
3323E30	200240	quarter corner	Lost	none	other	0	rocks	lots of rock	3136673.976	682235.026	8191.71
3323E32	300140										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3323E33	400140	quarter corner	Existent	stone corner	GLO	0	BT s33 \ mound		3135119.892	683867.732	8081.372
3323E36	700140	quarter corner	Existent	stone corner	GLO	0	mound \ marked stone	undisturbed	3135141.535	685491.07	7701.831
3323N01	640700	quarter corner	Existent	aluminum cap	County	2005	2ft buried tee bar		3135259.481	690310.386	6960.828
3323N02	540700	quarter corner	Lost	none	other	0	none	in highway	3144100.047	689287.839	6952.407
3323N03	440700	quarter corner	Lost	brass cap	GLO	1917	brass caps	each township both out of ground	3144063.2	687679.542	7006.707
3323N04	340700	quarter corner	Lost	none	other	0	fence corner		3144038.153	686064.409	7133.274
3323N05	240700	quarter corner	Lost	none	other	0	NONE		3143993.778	684468.266	7319.534
3323N06	140700	Quarter Corner	Existent	Stone Corner	GLO	1900	ORIG BT	SET NEW BT S5	3143959.844	682858.691	7390.8
3323N07	140600	quarter corner	Existent	stone corner	GLO	0	marked stone	steel post	3143925.728	681263.49	7653.556
3323N09	340600	quarter corner	Existent	aluminum cap	BLM	1993	mound	shot as an offset	3142305.555	681304.428	7675.112

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3323N10</i>	<i>440600</i>	quarter corner	Existent	aluminum cap	BLM	1993	mound		3142380.482	684517.549	7433.417
<i>3323N13</i>	<i>640500</i>	quarter corner	Lost	none	other	0	in corral		3142415.796	686123.285	7149.781
<i>3323N14</i>	<i>540500</i>	quarter corner	Lost	none	other	0	none		3140858.076	689370.235	7008.806
<i>3323N15</i>	<i>440500</i>	quarter corner	Existent	stone corner	GLO	0	marked stone	near fenceline 40 ft south of inters	3140840.114	687763.972	7116.528
<i>3323N1609/10</i>	<i>400560</i>	quarter corner	Lost	none	other	0	fence intersection	stone mound 40ft E	3140789.204	686154.325	7249.764
<i>3323N1617/16</i>	<i>300460</i>	sixteenth corner	Existent	aluminum cap	BLM	1993	steel post	n1/16 9\10	3141992.093	685327.289	7302.56
<i>3323N1618/17</i>	<i>200460</i>	sixteenth corner	Existent	aluminum cap	BLM	1993	mound	n1/16 16/17	3140343.874	683764.907	7497.99
<i>3323N22</i>	<i>440400</i>	sixteenth corner	Existent	aluminum cap	BLM	1993	fence\mound	n1/16 17/18	3140300.989	682153.102	7719.601
<i>3323N23</i>	<i>540400</i>	quarter corner	Existent	stone corner	GLO	0	MARKED STONE	FENCE INTERSECT	3139184.081	686193.913	7432.389

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3323N25	640300	quarter corner	Lost	none	other	0	FENCE INTERSECT	fence jct.	3139228.927	687803.689	7300.114
3323N26	540300	quarter corner	Existent	stone corner	GLO	0	MARKED STONE	reset by SJC from info on SP#322	3137650.859	689451.28	7106.132
3323N28	340300	quarter corner	Existent	stone corner	GLO	0	marked stone	mound \ old fence it looked untouched	3137609.829	687847.076	7284.92
3323N29	240300	quarter corner	Lost	none	other	0	NONE	IN BLADED ROAD	3137535.818	684624.327	7810.248
3323N32	240200	quarter corner	Existent	stone corner	GLO	0	MOUNDIMARKED STONE	MARKED STONE IS CRACKED IN TWO	3137495.218	683017.265	8019.704
3323N33	340200	quarter corner	Existent	brass cap	BLM	1970	none	in fenceline	3135890.979	683055.543	8164.661
3323N34	440200	quarter corner	Existent	stone corner	GLO	0	marked stone	stone mound north	3135924.229	684664.353	7845.505
3323N35	540200	quarter corner	Existent	brass cap	BLM	1970	none	10 ft east of fence	3135965.413	686271.178	7508.761
3323N36	640200	quarter corner	Existent	aluminum cap	USFS	1985	fence		3136003.661	687879.85	7170.868

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3323NE02</i>	<i>600700</i>	quarter corner	Existent	Aluminum Cap	County	2011	RP	In vault.	3136042.497	689491.203	7089.644
<i>3323NE03</i>	<i>500700</i>	section corner	Lost	none	other	0	none	middle of pasture	3144081.584	688483.696	6970.895
<i>3323NE04</i>	<i>400700</i>	section corner	Lost	none	other	0	fence intersect	BC disturbed out of ground	3144037.189	686885.547	7058.918
<i>3323NE05</i>	<i>300700</i>	section corner	Existent	aluminum cap	BLM	1998	MOUND	IN FENCE	3144018.861	685257.027	7244.847
<i>3323NE06</i>	<i>200700</i>	section corner	Existent	stone corner	GLO	0	MARKED STONE	IN FENCE MISSING 4 BT S?	3143974.879	683676.637	7303.383
<i>3323NE07</i>	<i>200600</i>	section corner	Existent	stone corner	GLO	0	mound	steel post	3143943.06	682066.131	7536.175
<i>3323NE09</i>	<i>400600</i>	section corner	Existent	aluminum cap	BLM	1993	mound		3142324.741	682107.928	7665.331
<i>3323NE10</i>	<i>500600</i>	section corner	Existent	aluminum cap	BLM	1993	none		3142397.646	685319.133	7241.685
<i>3323NE11</i>	<i>600600</i>	section corner	Existent	aluminum cap	BLM	1993	mound	in fenceline	3142432.572	686921.859	7114.687
		section corner	Lost	none	other	0	none	in cultivated field	3142469.154	688530.158	7015.156

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3323NE14</i>	<i>600500</i>								<i>"Utah Coordinate System 1983 South Zone"</i>		
		section corner	Existent	aluminum cap	County	2005	BT, s14	reestablished & set by SJC from bT	3140855.563	688568.1	7037.265
<i>3323NE1609</i>	<i>360560</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	steel post		3141983.831	684926.89	7342.774
<i>3323NE1617</i>	<i>260460</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1993	mound		3140333.236	683360.004	7628.527
<i>3323NE2</i>	<i>600700</i>										
		Section Corner	Existent	Aluminum Cap	BLM	2011	T POST		3144085.229	688488.044	6970.954
<i>3323NE25</i>	<i>700300</i>										
		section corner	Existent	stone corner	GLO	0	MARKED STONE	FENCE INTERSECT IN MOUND	3137671.887	690253.565	6989.236
<i>3323NE29</i>	<i>300300</i>										
		section corner	Existent	brass cap	BLM	1970	FENCE INTERSECT		3137515.902	683822.229	8025.545
<i>3323NE31</i>	<i>200200</i>										
		section corner	Existent	stone corner	GLO	0	mound of stone	fence corner sp#326	3135870.701	682251.68	8339.931
<i>3323NE34</i>	<i>500200</i>										
		section corner	Obliterated	aluminum cap	County	2008	SURVEY PLAT #18	SJC set new 3 1/2" cap #3831 PARKER,BK2, PG32	3135984.718	687073.954	7364.8
<i>3323NW06</i>	<i>100700</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3323NW09</i>	<i>300600</i>	section corner	Existent	stone corner	GLO	0	marked stone\mound	steel post	3143909.434	680491.495	7757.314
<i>3323NW14</i>	<i>500500</i>	section corner	Existent	aluminum cap	BLM	1993	mound	shot as an offset	3142361.083	683710.372	7533.097
<i>3323NW1617</i>	<i>220460</i>	section corner	Lost	none	other	0	fence corner		3140809.593	686961.05	7199.088
<i>3323NW1634</i>	<i>420160</i>	sixteenth corner	Existent	aluminum cap	BLM	1993	mound west		3140311.587	682554.053	7728.444
<i>3323NW1635</i>	<i>520160</i>	sixteenth corner	Existent	aluminum cap	USFS	1988	protective signs		3135557.054	685877.87	7597.332
<i>3323NW17</i>	<i>200500</i>	sixteenth corner	Lost	none	other	0	none	bar ditch	3135592.12	687487.443	7319.606
<i>3323NW23</i>	<i>500400</i>	section corner	Existent	brass cap	BLM	1970	fence		3140700.254	682139.484	7676.063
<i>3323NW25</i>	<i>600300</i>	section corner	Lost	none	other	0	FENCE INTERSECTION	fence intersection	3139204.877	687000.202	7373.873
<i>3323NW27</i>	<i>400300</i>	section corner	Existent	stone corner	GLO	0	OM MARKED STONE	MOUND TO WEST	3137634.322	688654.555	7193.118
		section corner	Existent	brass cap	BLM	1970	MOUND \ WOOD POST	6 FT NORTH FENCE	3137553.908	685428.478	7656.773

"Utah Coordinate System 1983 South Zone"

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3323NW30	100300	section corner	Existent	stone corner	GLO	0	marked stone	no bt s	3137438.733	680638.438	8717.607
3323NW33	300200	section corner	Existent	brass cap	BLM	1970	fence intersection		3135905.908	683857.885	7983.862
3323NW34	400200	section corner	Existent	stone corner	GLO	0	mound of stone	red steel post	3135946.892	685468.502	7680.827
3323NW36	600200	section corner	Obliterated	aluminum cap	Local	1976	none	3 1/4" alum. Cap LS#1929/water vault	3136022.385	688685.735	7174.962
3323S01	640600	quarter corner	Lost	none	other	0	none	in highway	3142487.766	689334.05	6992.697
3323S02	540600	quarter corner	Lost	none	other	0	fence line	nearby post.	3142452.685	687725.921	7055.329
3323S05	240600	quarter corner	Existent	aluminum cap	BLM	1993	mound		3142342.975	682909.132	7631.921
3323S07	140500	quarter corner	Existent	brass cap	BLM	1970	mound		3140689.145	681343.317	7825.85
3323S08	240500	quarter corner	Existent	aluminum cap	BLM	1993	mound		3140724.813	682945.188	7613.444
3323S09	340500										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
"Utah Coordinate System 1983 South Zone"											
<i>3323S13</i>	<i>640400</i>	quarter corner	Existent	aluminum cap	BLM	1993	stone mound	in pile of wood	3140768.203	684553.284	7331.935
<i>3323S16</i>	<i>340400</i>	quarter corner	Lost	none	other	0	none	in wheat field	3139265.593	689412.25	7112.444
<i>3323S1617/18</i>	<i>200420</i>	quarter corner	Lost	none	other	0	fence gate	recently bladed	3139153.362	684588.329	7656.698
<i>3323S17</i>	<i>240400</i>	sixteenth corner	Existent	aluminum cap	BLM	1993	steel post	s1/16 18/17	3139497.56	682175.285	7855.388
<i>3323S18</i>	<i>140400</i>	quarter corner	Existent	brass cap	BLM	1970	mound	in fence	3139130.338	682984.366	7581.615
<i>3323S19</i>	<i>140300</i>	quarter corner	Lost	none	other	0	none	none	3139081.413	681379.118	8300.808
<i>3323S22</i>	<i>440300</i>	quarter corner	Lost	none	other	0	none	none	3137459.593	681406.185	8467.3
<i>3323S32</i>	<i>240100</i>	quarter corner	Existent	brass cap	BLM	1970	FENCE INTERSECT		3137571.454	686233.786	7526.182
<i>3323S33</i>	<i>340100</i>	quarter corner	Existent	brass cap	BLM	1970	BT S05 S32	1 ft. south fence shot as offset	3134296.131	683084.033	8365.446
<i>3323S34</i>	<i>440100</i>	quarter corner	Existent	brass cap	BLM	1970	mound of stone		3134334.909	684692.76	7909.525

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3323S35</i>	<i>540100</i>	quarter corner	Existent	aluminum cap	USFS	1988	fenceline		3134368.773	686303.311	7573.12
<i>3323S36</i>	<i>640100</i>	quarter corner	Existent	stone corner	GLO	0	mound of stone	old fence intersection	3134403.654	687912.665	7267.852
<i>3323SE09</i>	<i>400500</i>	quarter corner	Obliterated	aluminum cap	County	2008	fence intersect	reset un-filed survey LS#155675	3134437.576	689522.733	7050.968
<i>3323SE16</i>	<i>400400</i>	section corner	Existent	aluminum cap	BLM	1993	fence	buried 1 inch south of fence post	3140787.77	685355.659	7268.412
<i>3323SE17</i>	<i>300400</i>	section corner	Existent	stone corner	GLO	0	steel post	marked stone missing mound fence	3139170.722	685392.325	7426.54
<i>3323SE19</i>	<i>200300</i>	section corner	Existent	aluminum cap	BLM	1993	mound	fence intersect	3139128.808	683786.298	7600.989
<i>3323SE22</i>	<i>500300</i>	section corner	Lost	none	other	0	none	none	3137486.252	682210.171	7856.257
<i>3323SE32</i>	<i>300100</i>	section corner	Lost	none	other	0	cedar post/rocks	fence \ rocks no marked rock\mound	3137592.41	687038.84	7394.071
		section corner	Existent	aluminum cap	USFS	1977	BT- s32, s33 ,s04	15 east fenceline shot as offset	3134315.73	683888.401	8119.426

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3323SE34	500100	section corner	Existent	stone corner	GLO	0	2 BT's \ marked stone	fence corner/ post	3134385.552	687106.792	7382.643
3323SW06	100600	section corner	Existent	aluminum cap	BLM	1993	mound of stone		3142289.841	680532.963	7768.974
3323SW07	100500	section corner	Existent	aluminum cap	BLM	1993	mound	50 ft. N of fenceline	3140673.637	680568.57	7931.849
3323SW09	300500	section corner	Existent	aluminum cap	BLM	1993	stone mound	fenceline	3140748.986	683750.997	7502.406
3323SW13	600400	section corner	Lost	none	other	0	fence intersect	fnc jnct	3139247.179	688608.963	7193.279
3323SW1617	220420	sixteenth corner	Existent	aluminum cap	BLM	1993	mound		3139511.359	682575	7781.123
3323SW1626	520220	sixteenth corner	Existent	aluminum cap	USFS	1985	signs	north of e/w fence	3136396.28	687469.119	7274.468
3323SW17	200400	section corner	Existent	brass cap	BLM	1970	warning post		3139093.475	682184.507	7912.084
3323SW32	200100	section corner	Existent	aluminum cap	USFS	1977	none		3134282.858	682297.281	8601.978
3323SW34	400100										

"Utah Coordinate System 1983 South Zone"

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3323SW36</i>	<i>600100</i>	section corner	Existent	stone corner	GLO	0	stone mound north	steel post	3134351.996	685500.458	7732.215
<i>3323W01</i>	<i>600640</i>	section corner	Existent	stone corner	GLO	0	marked stone	fence intersect	3134420.598	688718.685	7019.68
<i>3323W02</i>	<i>500640</i>	quarter corner	Lost	none	other	0	fence intersect	fnc jnct	3143277.444	688508.386	7010.261
<i>3323W04</i>	<i>300640</i>	quarter corner	Lost	none	other	0	fence intersect	fnc jnct	3143241.83	686903.68	7063.308
<i>3323W05</i>	<i>200640</i>	quarter corner	Existent	stone corner	GLO	0	mound		3143168.174	683693.406	7476.712
<i>3323W06</i>	<i>100640</i>	quarter corner	Lost	none	other	0	FENCE		3143141.726	682084.519	7468.175
<i>3323W07</i>	<i>100540</i>	quarter corner	Existent	brass cap	BLM	1970	mound		3143094.981	680518.457	7768.305
<i>3323W08</i>	<i>200540</i>	quarter corner	Existent	aluminum cap	BLM	1993	mound		3141481.703	680550.828	7857.741
<i>3323W09</i>	<i>300540</i>	quarter corner	Existent	aluminum cap	BLM	1993	mound		3141512.562	682123.891	7793.223
<i>3323W11</i>	<i>500540</i>	quarter corner	Existent	aluminum cap	BLM	1993	mound		3141555.194	683730.431	7447.378

"Utah Coordinate System 1983 South Zone"

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Lost	none	other	0	fence intersect	fnc jct	3141632.135	686937.355	7139.151
3323W13	600440										
		quarter corner	Lost	none	other	0	fenceline	fence	3140051.485	688587.426	7140.273
3323W14	500440										
		quarter corner	Lost	none	other	0	FENCE INTERSECT	stone nearby unverified lost	3140003.119	686980.857	7269.448
3323W1607/06	120600										
		sixteenth corner	Existent	aluminum cap	BLM	1993	none	w1/16 06/07	3142297.263	680903.247	7722.983
3323W1607/18	120500										
		sixteenth corner	Existent	aluminum cap	BLM	1993	mound	w1/6 07/08	3140681.078	680941.053	7893.83
3323W1608/17	220500										
		sixteenth corner	Existent	aluminum cap	BLM	1993	fence	w1/6 08/17	3140712.52	682542.563	7579.609
3323W1620/17	220400										
		sixteenth corner	Existent	aluminum cap	BLM	1993	mound/fence	w1/16 20/17	3139111.811	682584.261	7814.802
3323W1626/35	520200										
		sixteenth corner	Existent	aluminum cap	USFS	1985	signs	between 35 & 26 w1/16 26/35	3135994.268	687476.885	7302.151
3323W17	200440										
		quarter corner	Existent	brass cap	BLM	1970	fence		3139901.513	682166.078	7819.645
3323W18	100440										
		quarter corner	Lost	none	other	0	none	none	3139869.285	680587.196	8270.87

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3323W19	100340	quarter corner	Existent	stone corner	GLO	0	marked stone	mound	3138247.69	680619.644	8671.8
3323W21	300340	quarter corner	Lost	none	other	0	FENCE \ GATE	LOTS OF ROCKS no mound	3138325.549	683803.731	7824.938
3323W22	400340	quarter corner	Lost	none	other	0	rocks	rocks NO MOUND	3138362.37	685411.019	7645.554
3323W23	500340	quarter corner	Lost	none	other	0	METAL PIPE 30 FEET N		3138401.936	687018.214	7417.121
3323W24	600340	quarter corner	Lost	none	other	0	NONE		3138439.109	688626.665	7201.895
3323W25	600240	quarter corner	Obliterated	cedar fence post	other	0	FENCE INTERSECTION	REF PLAT 322	3136826.415	688671.359	7171.283
		Quarter Corner	No Observation	Nail	other	0	Mound of Stone	Found nail in mound of stone, Corner Card dated 2005	3146553.182	688457.252	0
3323W27	400240	quarter corner	Existent	stone corner	GLO	0	marked stone	mound	3136743.777	685436.642	7600.304
3323W28	300240	quarter corner	Existent	stone corner	GLO	0	MOUND\ROCK	CLOSE TO STAKEOUT FROM BOTH DIRECTIONS	3136709.937	683841.572	7860.801

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3323W30	100240	quarter corner	Lost	none	other	0	fence line	none	3136634.754	680655.631	8666.593
3323W35	500140	quarter corner	Lost	none	other	0	old fence corner	rock missing	3135176.701	687090.738	7408.521
3323W36	600140	quarter corner	Obliterated	aluminum cap	County	2008	stone mound	3' east of N/S fence PLSS	3135218.213	688702.734	7108.32
3323WEW35	525200	256th	Existent	aluminum cap	USFS	1985	signs	between 35 & 26 256 corner	3135996.713	687577.665	7269.851
3324C31	140140	quarter corner	Obliterated	aluminum cap	other	0	N/S fenceline(in road)	2-1/2"BC in vault in rd Utah RLS #4946	3135277.766	691091.071	6875.566
3324E01	700640	quarter corner	Lost	none	other	0	fence intersect	road/fenceline 30' N	3143547.164	699754.219	6796.883
3324E04	400640	quarter corner	Lost	none	other	0	none	suspect stone nearby	3143417.637	694922.722	6831.33
3324E05	300640	quarter corner	Lost	none	other	0	fence intersection		3143392.309	693305.015	6891.769
3324E08	300540	quarter corner	Lost	none	other	0	none		3141783.583	693379.541	6810.683
3324E12	700540										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Lost	none	other	0	fence intersect	road/fenceline 30' W	3141936.155	699793.29	6811.61
3324E13	700440										
		quarter corner	Lost	none	other	0	none	cultivated field	3140319.04	699832.406	6816.123
3324E17	300440										
		quarter corner	Lost	none	other	0	none	fenceline 20' W	3140167.99	693392.159	6821.761
3324E18	200440										
		quarter corner	Lost	none	other	0	intersection	at fence jct	3140128.743	691781.518	6876.248
3324E20	300340										
		quarter corner	Lost	none	other	0	fence intersect		3138558.148	693433.69	6835.314
3324E23	600340										
		quarter corner	Lost	none	other	0	FENCE INTERSECT		3138672.25	698260.416	6823.26
3324E24	700340										
		quarter corner	Lost	none	other	0	fence	fenceline 14' E	3138710.804	699875.645	6829.264
3324E25	700240										
		quarter corner	Lost	none	other	0	none	fenceline 20' E	3137102.491	699917.33	6812.495
3324E26	600240										
		quarter corner	Lost	none	other	0	FENCE		3137066.34	698298.386	6804.833
3324E30	200240										
		quarter corner	Lost	none	other	0	NONE	fence intersection	3136905.489	691859.457	6897.495
3324E31	200140										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Obliterated	aluminum cap	Local	1994	on E/W fenceline	2 1/2" alum cap LS#6796	3135293.846	691892.634	6922.545
<i>3324E35</i>	<i>600140</i>										
		quarter corner	Lost	none	other	0	none	in roadway	3135448.15	698340.91	6808.3
<i>3324E36</i>	<i>700140</i>										
		quarter corner	Lost	none	other	0	none	in fence jnct.	3135493.356	699945.87	6834.799
<i>3324N01</i>	<i>640700</i>										
		Quarter Corner	Obliterated	Re-bar	other	1911	FNC PRJ N-S	RD 332 N	3144333.314	698927.229	6773.463
<i>3324N02</i>	<i>540700</i>										
		quarter corner	Lost	none	other	0	none	in roadway	3144293.971	697316.014	6804.305
<i>3324N03</i>	<i>440700</i>										
		quarter corner	Lost	none	other	0	none	plowed field	3144255.475	695707.683	6824.715
<i>3324N04</i>	<i>340700</i>										
		quarter corner	Lost	none	other	0	none	fenceline 14.5' W	3144217.227	694094.956	6865.775
<i>3324N05</i>	<i>240700</i>										
		quarter corner	Lost	none	other	0	none		3144177.005	692491.178	6925.827
<i>3324N06</i>	<i>140700</i>										
		quarter corner	Lost	none	other	0	none	plowed field	3144142.254	690900.46	6887.201
<i>3324N13</i>	<i>640500</i>										
		quarter corner	Lost	none	other	0	none	in plowed field	3141103.723	699008.69	6803.148
<i>3324N14</i>	<i>540500</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3324N15</i>	<i>440500</i>	quarter corner	Lost	none	other	0	none	fenceline 5' E	3141065.137	697402.128	6810.16
<i>3324N16</i>	<i>340500</i>	quarter corner	Lost	none	other	0	none	in dry lake bed	3141029.328	695792.133	6804.355
<i>3324N17</i>	<i>240500</i>	quarter corner	Lost	none	other	0	mound of stones west	fence jct. 36' W	3140990.671	694172.719	6832.035
<i>3324N18</i>	<i>140500</i>	quarter corner	Lost	none	other	0	none	in cultivated field	3140944.844	692591.609	6819.976
<i>3324N19</i>	<i>140400</i>	quarter corner	Lost	none	other	0	none	in bar ditch	3140906.711	690953.201	6899.51
<i>3324N20</i>	<i>240400</i>	quarter corner	Lost	none	other	0	none	fenceline 15' W	3139304.93	691004.773	6979.605
<i>3324N21</i>	<i>340400</i>	quarter corner	Lost	none	other	0	none	plowed field	3139343.217	692610.45	6861.872
<i>3324N23</i>	<i>540400</i>	quarter corner	Lost	none	other	0	fence intersect	fenceline 7' W	3139381.86	694214.174	6791.184
<i>3324N24</i>	<i>640400</i>	quarter corner	Lost	none	other	0	none	fence 3.4' E	3139456.749	697439.928	6836.538
<i>3324N26</i>	<i>540300</i>	quarter corner	Lost	none	other	0	none	fnc cor 18' E&N	3139501.029	699053.672	6829.605

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3324N27	440300	quarter corner	Obliterated	aluminum cap	Local	0	none	see SP#69 flush with ground	3137849.037	697477.799	6820.21
3324N28	340300	quarter corner	Lost	none	other	0	none	fence jct. 5' S	3137808.438	695869.059	6799.995
3324N29	240300	quarter corner	Lost	other	other	0	fence corner	fence corner 45' W	3137771.879	694249.452	6793.489
3324N31	140200	quarter corner	Lost	none	other	0	fence intersect	fenceline 15' W	3137734.293	692650.703	6857.818
3324N32	240200	quarter corner	Lost	none	other	0	none	in HWY	3136078.81	691073.192	6969.952
3324N33	340200	quarter corner	Lost	none	none	0	none	in HWY 491	3136116.142	692682.078	6843.669
3324N34	440200	quarter corner	Lost	none	other	0	none	HWY fence 45'E	3136163.938	694287.349	6821.337
3324NE01	700700	quarter corner	Lost	none	other	0	in highway	fenceline 26' E in HWY 491	3136202.147	695917.362	6750.465
3324NE05	300700	section corner	Lost	none	other	0	none	in road jct.roads 332 & 333	3144351.954	699734.505	6795.391

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		section corner	Lost	none	other	0	none	in roadway	3144195.854	693295.346	6904.486
3324NE12	700600										
		section corner	Lost	none	other	0	fence intersect	road/fenceline 2' N	3142732.147	699773.787	6797.212
3324NE17	300500										
		section corner	Lost	none	other	0	single cemented post	fenceline 45' W	3140972.032	693365.934	6817.542
3324NE18	200500										
		section corner	Lost	none	other	0	none	bar ditch/ rocks near	3140926.038	691787.47	6876.42
3324NE20	300400										
		section corner	Existent	stone corner	GLO	0	marked stone	@nearfence jct.	3139360.42	693415.61	6790.257
3324NE23	600400										
		section corner	Lost	none	other	0	none	in bar ditch	3139476.037	698243.053	6825.969
3324NE26	600300										
		section corner	Lost	other	other	0	FENCE POST\BARN		3137869.818	698283.411	6824.19
3324NE28	400300										
		section corner	Lost	none	other	0	none	fence jct.	3137800.643	695066.239	6718.601
3324NE31	200200										
		section corner	Obliterated	aluminum cap	County	2010	ROS#322	PK nail dcp_4154 set new alum. cap	3136097.471	691877.457	6894.314
3324NW01	600700										
		section corner	Existent	brass cap	GLO	1911	none	buried 5 inches	3144313.373	698120.173	6786.028

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3324NW02	500700	section corner	Lost	none	other	0	none	junct. roads 365&332	3144274.681	696511.89	6816.365
3324NW03	400700	section corner	Lost	none	other	0	none		3144236.299	694903.579	6831.733
3324NW05	200700	section corner	Lost	none	other	0	old fence corner	fenceline 17' W	3144160.816	691681.581	6896.602
3324NW06	100700	section corner	Existent	stone corner	GLO	0	mound of stones/fence	Original Stone	3144123.626	690096.302	6933.535
3324NW10	400600	section corner	Lost	none	other	0	none	in dry lakebed	3142618.532	694949.879	6795.841
3324NW13	600500	section corner	Lost	none	other	0	fence	fenceline 10' W	3141084.345	698201.427	6816.531
3324NW14	500500	section corner	Lost	none	other	0	none	fenceline 9' N	3141048.538	696596.295	6809.779
3324NW15	400500	section corner	Lost	none	other	0	none	in road edge	3141010.163	694987.976	6828.329
3324NW18	100500	section corner	Lost	none	other	0	none	bar ditch/fence 17'	3140888.834	690173.968	6966.946
3324NW19	100400										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		section corner	Lost	none	other	0	NONE		3139282.741	690234.825	6937.535
<i>3324NW20</i>	<i>200400</i>										
		section corner	Lost	none	other	0	fence intersect		3139319.664	691802.73	6913.084
<i>3324NW23</i>	<i>500400</i>										
		section corner	Lost	none	other	0	none	in plowed field	3139437.526	696634.732	6829.412
<i>3324NW26</i>	<i>500300</i>										
		section corner	Obliterated	nail	Local	0	2 REF POINTS	buried 1" in roadway see SP#69	3137829.233	696673.195	6811.97
<i>3324NW28</i>	<i>300300</i>										
		section corner	Lost	none	other	0	fence	in fenceline	3137752.183	693459.114	6867.192
<i>3324NW29</i>	<i>200300</i>										
		section corner	Existent	stone corner	other	0	mound of rocks	near fence jct.	3137708.918	691840.456	6848.74
<i>3324NW31</i>	<i>100200</i>										
		section corner	Obliterated	aluminum cap	Local	2005	RP's on LAMP POSTS	10.13 ft of back curb	3136064.727	690292.773	7027.412
<i>3324NW33</i>	<i>300200</i>										
		section corner	Lost	none	other	0	none	fenceline 38' W	3136144.961	693485.369	6776.376
<i>3324NW34</i>	<i>400200</i>										
		section corner	Lost	none	other	0	none	in HWY 491	3136183.068	695105.239	6729.77
<i>3324S01</i>	<i>640600</i>										
		quarter corner	Lost	none	other	0	fence	in fence	3142720.053	698963.277	6785.793
<i>3324S02</i>											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3324S02	540600	quarter corner	Lost	none	other	0	none	in cultivated field	3142685.652	697354.818	6813.323
3324S03	440600	quarter corner	Lost	none	other	0	none	middle of field	3142647.195	695746.19	6816.099
3324S04	340600	quarter corner	Lost	none	other	0	mound of stone	in cultivated field	3142606.661	694128.287	6835.415
3324S05	240600	quarter corner	Lost	none	other	0	fence intersection	fenceline 15' E	3142569.032	692524.673	6863.322
3324S06	140600	quarter corner	Lost	none	other	0	none	plowed field	3142533.897	690937.671	6905.622
3324S15	440400	quarter corner	Lost	none	other	0	none	fence jct. 24' E	3139421.973	695828.384	6816.474
3324S19	140300	quarter corner	Lost	none	other	0	FENCE INTERSECT	40' N	3137686.549	691058.443	6882.594
3324S24	600340	quarter corner	Lost	other	other	0	4-way fence	fnc jct	3137882.748	699092.436	6817.167
3324S25	640200	quarter corner	Lost	none	other	0	fence	in roadway CR 335	3136273.55	699127.288	6809.145
3324S26	540200	quarter corner	Obliterated	aluminum cap	Local	0	FENCE	at fence intersection	3136233.06	697517.394	6820.848

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USft)</i>
3324S31	140100	quarter corner	Existent	stone corner	GLO	0	marked stone	at fence corner	3134473.857	691110.283	6939.218
3324S32	240100	quarter corner	Existent	aluminum cap	Local	1993	original stone	east of fence	3134510.432	692720.972	6717.185
3324S33	340100	quarter corner	Existent	stone corner	GLO	0	mound of stone	In N/S fenceline	3134548.716	694336.096	6754.493
3324S34	440100	quarter corner	Existent	stone corner	GLO	0	mound of stone	In place	3134585.347	695953.624	6642.788
3324S35	540100	quarter corner	Obliterated	rebar	Local	0	old fence	rebar & cap LS#155675 proportioned	3134631.354	697554.66	6785.407
3324S36	640100	quarter corner	Lost	none	other	0	tall gate post	near gatepost	3134674.62	699164.493	6823.901
3324SE05	300600	section corner	Existent	stone corner	GLO	0	mound of stone	in fenceline	3142587.689	693324.124	6875.483
3324SE13	700400	section corner	Lost	none	other	0	fence corner	fence corner 85' N	3139540.872	699855.865	6855.944
3324SE24	700300	section corner	Lost	none	other	0	fence intersection	fenceline 20'E	3137899.361	699896.104	6826.003
3324SE25	700200										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		section corner	Lost	none	other	0	fence	in roadway CR 335	3136296.71	699950.486	6829.112
<i>3324SE26</i>	<i>600200</i>										
		section corner	Lost	none	other	0	fence		3136254.337	698321.964	6770.391
<i>3324SE31</i>	<i>200100</i>										
		section corner	Obliterated	aluminum cap	Local	0	none	1-1/2" al. cap LS#2764	3134492.047	691915.759	6814.866
<i>3324SE32</i>	<i>300100</i>										
		section corner	Obliterated	rebar	Local	0	fence	Rebar @ cap LS#155675 proportioned.	3134529.538	693528.468	6780.177
<i>3324SE33</i>	<i>400100</i>										
		section corner	Lost	none	other	0	none	in plowed field	3134567.704	695140.243	6752.158
<i>3324SE36</i>	<i>700100</i>										
		section corner	Lost	none	other	0	none	road/fenceline 16' N	3134694.188	699968.639	6825.765
<i>3324SW01</i>	<i>600600</i>										
		section corner	Lost	none	other	0	rock pile	fence jct. 10' S	3142701.719	698164.487	6791.782
<i>3324SW02</i>	<i>500600</i>										
		section corner	Lost	none	other	0	none	fenceline	3142666.415	696550.335	6808.353
<i>3324SW05</i>	<i>200600</i>										
		section corner	Lost	none	other	0	none	in wheat field	3142549.865	691715.848	6884.256
<i>3324SW06</i>	<i>100600</i>										
		section corner	Lost	none	other	0	none		3142515.406	690133.764	6946.449

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3324SW15	400400	section corner	Lost	none	other	0	none	fence jnct.	3139401.134	695016.548	6762.54
3324SW26	500200	section corner	Obliterated	aluminum cap	Local	2005	NAIL & WASHER(found)	set 3" cap in vault see SP#69	3136221.411	696713.576	6775.243
3324SW31	100100	section corner	Obliterated	aluminum cap	Local	2005	tee bar	set new 2-1/2" al. cap set ap over tee bar	3134454.366	690327.954	7012.11
3324W01	600640	quarter corner	Existent	stone corner	GLO	0	stone mound/fencepost	post in stone mound	3143509.913	698142.091	6783.839
3324W02	500640	quarter corner	Lost	none	other	0	none	fence	3143470.523	696531.133	6815.761
3324W05	200640	quarter corner	Lost	none	other	0	none	fenceline 25' N	3143365.029	691723.398	6891.654
3324W06	100640	quarter corner	Lost	none	other	0	fence corner	fence corner 9' N	3143316.701	690116.113	6954.01
3324W07	100540	quarter corner	Lost	none	other	0	none	in fence	3141711.1	690156.262	6935.443
3324W08	200540	quarter corner	Lost	none	other	0	fence	fenceline 15' N	3141749.7	691734.61	6851.499
3324W10	400540										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3324W11	500540	quarter corner	Lost	none	other	0	none	fence jnct. 9'	3141817.055	694953.687	6811.142
3324W12	600540	quarter corner	Lost	none	other	0	none	in plowed field	3141862.196	696569.604	6806.896
3324W13	600440	quarter corner	Lost	none	other	0	none	in fence	3141900.98	698182.88	6792.553
3324W14	500440	quarter corner	Lost	none	other	0	winrow		3140280.297	698223.808	6817.463
3324W15	400440	quarter corner	Lost	none	other	0	none	fenceline	3140241.83	696615.568	6789.489
3324W18	100440	quarter corner	Lost	none	other	0	none	fence intersection	3140203.852	694997.518	6798.097
3324W19	100340	Quarter Corner	Lost	None	GLO	1900	NONE	NO EVIDENCE	3140086.046	690198.362	6996.778
3324W20	200340	quarter corner	Existent	stone corner	other	0	MOUND	Found orig mon.	3138478.368	690234.625	7002.965
3324W22	400340	quarter corner	Lost	none	other	0	none	fenceline 30'W	3138519.602	691822.443	6941.832
3324W23	500340	quarter corner	Lost	none	other	0	none	fenceline 10' S	3138591.584	695044.376	6740.696

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Lost	none	other	0	none	bar ditch/ fence 120'	3138633.354	696653.997	6815.801
3324W26	500240										
		quarter corner	Obliterated	nail	other	0	2 RP's alum caps	buried 1' in roadway see SP#69 / 2 RP's	3137024.617	696695.204	6768.805
3324W27	400240										
		quarter corner	Lost	none	other	0	none	in cultivated field	3136986.64	695084.005	6758.582
3324W28	300240										
		quarter corner	Lost	none	other	0	none	in cultivated field	3136949.092	693478.016	6831.276
3324W30	100240										
		quarter corner	Obliterated	rebar	Local	0	rebar LS#155675	buried 15 inches proportioned	3136868.371	690273.159	7003.739
3324W33	300140										
		quarter corner	Lost	none	other	0	fences	junct two fences	3135333.702	693506.784	6748.365
3324W34	400140										
		quarter corner	Lost	none	other	0	none	creek eroded location	3135378.804	695124.289	6626.708
3324W35	500140										
		quarter corner	Lost	none	other	0	none	In road/fenceline 10'N	3135412.442	696732.825	6794.59
3325C28	340240										
		Quarter Corner	Existent	Re-bar	Private	2009	REBAR	ROS 831	3137206.47	703911.448	6866.257

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3325CS1628	340220										
		Sixteenth Corner	Existent	Re-Bar & Cap	Private	2009	REBAR ORNG CAP	ROS 831	3136807.491	703923.748	6869.088
3325CS1629	240220										
		Sixteenth Corner	Existent	Re-Bar & Cap	Private	2006	REBAR	SURVEY 621	3136767.052	702313.279	6854.211
3325CSNW6432	220150										
		1/64th Corner	Existent	Re-Bar & Cap	Private	2005	REBAR ORNG CAP	ROS 461	3135751.199	701938.301	6875.572
3325CW1632	220140										
		Sixteenth Corner	Existent	Re-Bar & Cap	Private	2005	REBAR ORNG CAP	ROS 461	3135550.151	701943.38	6876.754
3325N14	540500										
		Quarter Corner	Lost	None	GLO	0			3141308.154	707014.036	6788.876
3325N15	440500										
		Quarter Corner	Lost	None	GLO	0			3141269.039	705412.651	6790.204
3325N16	340500										
		Quarter Corner	Lost	None	GLO	0			3141231.396	703804.344	6794.603
3325N17	240500										
		Quarter Corner	Lost	None	GLO	0			3141190.66	702199.813	6794.568
3325N18	140500										
		Quarter Corner	Lost	None	GLO	0			3141150.262	700591.708	6823.276
3325N19	140400										
		Quarter Corner	Lost	None	GLO	0			3139544.587	700632.63	6859.425

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3325N20	240400	Quarter Corner	Lost	None	GLO	0			3139585.243	702241.259	6828.23
3325N21	340400	Quarter Corner	Lost	None	County	0			3139615.511	703851.298	6805.321
3325N26	540300	Quarter Corner	Obliterated	None	County	0			3138098.825	707101.571	6838.777
3325N27	440300	Quarter Corner	Obliterated	None	County	0			3138051.088	705495.742	6855.824
3325N28	340300	Quarter Corner	Lost	None	GLO	0		FNC JNC PROJECT NEW	3138005.797	703890.567	6869.283
3325N29	240300	Quarter Corner	Existent	Aluminum Cap	County	2013	Orig. Mon and BT's	Orig mon never set laying in tree	3137975.827	702280.363	6855.406
3325N30	140300	Quarter Corner	Lost	None	County	0			3137935.92	700672.642	6826.558
3325N32	240200	Quarter Corner	Obliterated	None	Private	2006	REBAR OFFSET	ROS 621	3136365.241	702324.555	6879.342
3325NW13	600500	Section Corner	Existent	Aluminum Cap	County	2013	2BT	ORG MON BASE 2 BT	3141330.353	707818.064	6835.094
3325NW14	500500										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Section Corner	Obliterated	Re-bar	County	1970		FND REBAR IN FIELD	3141289.494	706216.052	6789.781
3325NW15	400500										
		Section Corner	Existent	Re-bar	County	1965			3141248.377	704608.61	6811.382
3325NW16	300500										
		Section Corner	Obliterated	Re-bar	County	1965			3141207.868	703002.545	6782.405
3325NW1632	220160										
		Sixteenth Corner	Existent	Re-Bar & Cap	Private	2006	REBAR CAP	ORNG CAP RLS 171004	3135952.282	701933.212	6884.413
3325NW17	200500										
		Section Corner	Existent	Re-bar	County	1970	4 BT	REBAR 4 ORG BTS	3141171.238	701395.836	6813.863
3325NW18	100500										
		Section Corner	Lost	None	County	1965			3141130.284	699816.747	6814.06
3325NW20	200400										
		Section Corner	Existent	Aluminum Cap	County	2013	4 BT	FND ORG MON BASE 4 BTS	3139565.454	701436.951	6900.963
3325NW21	300400										
		Section Corner	Obliterated	Wood Post	County	1902	FNC CRNR	BK111PG3	3139598.052	703047.112	6836.602
3325NW22	400400										
		Section Corner	No Observation	Stone	GLO	0	Stone	Stone laying on ground	3139641.058	704645.012	0
		Section Corner	Lost	None	County	0			3139640.126	704649.594	6812.361
3325NW24	600400										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		Section Corner	Existent	Aluminum Cap	County	2013	ORG. MON 2 BT	SET FROM ORIGINAL BTS	3139723.876	707864.486	6850.973
<i>3325NW25</i>	<i>600300</i>										
		Section Corner	Existent	Aluminum Cap	County	2013	ORG. MON 4 BT	Set new monument from B.T's	3138117.309	707904.326	6936.38
<i>3325NW26</i>	<i>500300</i>										
		Section Corner	Obliterated	None	County	0			3138074.84	706299.609	6850.065
<i>3325NW27</i>	<i>400300</i>										
		Section Corner	Obliterated	None	County	0			3138031.993	704692.703	6859.1
<i>3325NW28</i>	<i>300300</i>										
		Section Corner	Existent	Aluminum Cap	County	2013	2BT	2 BT	3137993.71	703088.185	6854.103
<i>3325NW29</i>	<i>200300</i>										
		Section Corner	Lost	None	County	0			3137955.631	701476.965	6882.103
<i>3325NW32</i>	<i>200200</i>										
		Section Corner	Obliterated	Re-Bar & Cap	Private	2005	FND REBAR		3136343.09	701522.393	6837.348
<i>3325NW33</i>	<i>300200</i>										
		Section Corner	Existent	Re-Bar & Cap	County	2013	4 BT	1 ORG BT	3136387.076	703126.782	6861.845
<i>3325NWNW6432</i>	<i>210170</i>										
		1/64th Corner	Existent	Re-Bar & Cap	Private	2006	REBAR YELLOW CAP	ROS 563	3136147.99	701727.231	6850.075
<i>3325S24</i>	<i>640300</i>										
		Quarter Corner	Lost	None	GLO	1902	NONE	FENCE JUNCTION PROJECTING	3138135.566	708703.522	6912.07

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
									NORTH SOUTH AND WEST		
3325S34	440100										
		Quarter Corner	Lost	None	GLO	0			3134837.635	705583.881	6832.017
3325S35	540100										
		Quarter Corner	Lost	None	GLO	0	NONE	FNC JCT E W S	3134879.08	707198.444	6848.689
3325SE01	700600										
		section corner	Existent	brass cap	GLO	1911	road jct	buried in roadway	3152650.806	709148.824	7027.326
3325SW1628	320220										
		Sixteenth Corner	Existent	Re-Bar & Cap	Private	2009	REBAR ORNG CAP	ROS 831	3136798.092	703521.865	6849.644
3325SW32	200100										
		Section Corner	Obliterated	None	GLO	1902	FNC COR	FNC JNC REBUILT	3134734.129	701562.057	6825.354
3325SW35	500100										
		Section Corner	Existent	Aluminum Cap	County	2013	ORIG BTS	4 NEW BT	3134857.835	706387.978	6861.363
3325W13	600440										
		Quarter Corner	Existent	Aluminum Cap	County	2013	ORIG BT	ORG BT MON BASE	3140525.982	707832.013	6850.753
3325W15	400440										
		Quarter Corner	Obliterated	Wood Post	GLO	1902	FNC CRN/JCT	MAGNAIL AND SIGN	3140444.874	704629.351	6810.802
3325W16	300440										
		Quarter Corner	Lost	None	GLO	1902	NONE	OLD BRACE	3140402.157	703027.835	6801.536

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3325W17	200440	Quarter Corner	Existent	Re-bar	other	0	2 BTS	ORG MON 2 OR BT	3140368.801	701419.21	6851.969
3325W20	200340	Quarter Corner	Existent	Aluminum Cap	County	2013	Orig Mon. set and BTs	Orig mon. was firmly set but had begun to rot	3138760.682	701455.432	6863.321
3325W24	600340	Quarter Corner	Existent	Aluminum Cap	County	2013	FNC JCT ORIG BT	SET 2 BTS	3138920.883	707883.994	6864.344
3325W26	500240	Quarter Corner	Existent	Aluminum Cap	GLO	2013	ORIG BT	ORG BT BASE OF MON	3137270.584	706321.124	6870.802
3325W27	400240	Quarter Corner	Obliterated	None	County	0			3137228.002	704717.794	6867.601
3325W28	300240	Quarter Corner	Lost	None	County	0			3137189.597	703106.969	6858.35
3325W29	200240	Quarter Corner	Lost	None	County	0			3137151.569	701497.109	6819.023
3325W32	200140	Quarter Corner	Obliterated	None	Private	2006	ROS 461	OFFSET REBAR 33FT EAST	3135538.634	701542.267	6847.134
3423C03	440640	Quarter Corner	No Observation	Aluminum Cap	USFS	1997	A.C. 10" above ground	Proportioned corner. In mound of	3133567.549	686336.894	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
3423C07	140540							stone to top of cap.			
		Quarter Corner	No Observation	Aluminum Cap	USFS	1997	A.C. 10" above ground	In rock collar to top. 200' W of N-S trail.	3131849.892	681549.245	0
3423CS1607	140520										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1997	A.C. 10" above ground	In rock collar. W edge of clearing.	3131448.269	681558.665	0
3423CW1605	220640										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1995	A.C. 10" above ground	In rock collar to top.	3133484.396	682718.161	0
3423E1606	160700										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1995	A.C. 6" above ground	9' N of E-W fence. Porportioned corner.	3134270.302	681894.945	0
3423N1606-05	200660										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1995	A.C. 10" above ground	In stone mound at porportioned positioned.	3133877.368	682306.448	0
3423S03	440600										
		Quarter Corner	No Observation	Stone	GLO	0	Stone 13X8X5	Reset at location and rebuild stone mound.	3132763.474	686355.503	0
3423S07	140500										
		Quarter Corner	No Observation	Aluminum Cap	USFS	1997	A.C. 6" above ground	In dense Aspen stand 240' E of N-S trail.	3131046.646	681568.085	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3423S1606-05	200620	Sixteenth Corner	No Observation	Aluminum Cap	USFS	1995	A.C. 8" above ground	On S facing slope. Hike required for access	3133073.203	682325.227	0
3423S1612-07	100520	Sixteenth Corner	No Observation	Aluminum Cap	USFS	1997	A.C. 12" above ground	On S facing Slope at edge of Oak and Aspen stand.	3131430.997	680773.811	0
3423S36	640100	quarter corner	Obliterated	nail	other	0	NONE	80 P nail in rocks	3124800.11	689767.293	6986.828
3423SE04	400600	Quarter Corner	No Observation	None	GLO	0	None	Found 2 BTs but record calls do not work.	3132745.429	685552.244	0
3423SE1607	160520	Sixteenth Corner	No Observation	Aluminum cap	USFS	1997	A.C. 6" above ground	On east edge of Aspen stand	3131457.161	681960.76	0
3423SW1605	220620	Sixteenth Corner	No Observation	Aluminum Cap	USFS	1995	A.C. 6" above ground	In oak on edge of clearing.	3133082.324	682727.611	0
3423SW1607	120520	Sixteenth Corner	No Observation	Aluminum Cap	USFS	1997	A.C. 10" above ground	In W edge of clearing 50' W of N-S stream.	3131439.426	681156.568	0
3423SW36	600100	section corner	Existent	stone corner	GLO	0	NONE	cfm @ fence jct	3124778.965	688961.582	7005.134

"Utah Coordinate System 1983 South Zone"

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3423W03	400640	Quarter Corner	No Observation	Aluminum Cap	GLO	0	Stone 14X8X7	Well marked Stone with rock mound 3' W.	3133549.663	685533.194	0
3423W07	100540	Quarter Corner	No Observation	Aluminum Cap	USFS	1997	A.C. 8" above ground	On S facing slope in dense Aspen stand	3131832.494	680764.852	0
3423W1607-18	120500	Sixteenth Corner	No Observation	Aluminum cap	USFS	1997	A.C. 6" above ground	In dense Aspen 150' E of road	3131037.863	681165.988	0
3423W1632-05	220700	Sixteenth Corner	No Observation	Aluminum Cap	USFS	1995	A.C. 8" above ground	3.3' N of E-W fence. Porportioned corner	3134287.51	682699.319	0
3423W36	600140	Quarter Corner	Existent	Stone Corner	GLO	1902	mnd stn 2' west	ORIG STONE	3125582.422	688941.235	6913.404
3424E01	700640	quarter corner	Lost	none	GLO	0	NONE		3133892.807	700000.386	6758.074
3424E02	600640	Quarter Corner	Obliterated	Aluminum Cap	Private	2013	Road/Fenceline	Proportioned Corner by private surveyor	3133846.41	698377.519	6789.1
3424E05	300640	quarter corner	Lost	none	GLO	0	NONE	pt on edge of field	3133727.282	693545.473	6801.277

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3424E06	200640	quarter corner	Obliterated	aluminum cap	other	1993	rock pile/fence	in N-S fenceline LS#6769	3133687.547	691937.267	6925.815
3424E07	200540	quarter corner	Lost	none	GLO	0	pt in e-w fence		3132078.636	691977.6	6919.275
3424E08	300540	quarter corner	Lost	none	GLO	0	NONE	pt in plowed field	3132118.935	693584.619	6782.976
3424E12	700540	quarter corner	Lost	none	GLO	0	NONE	pt on edge of road	3132264.535	700025.633	6796.45
3424E13	700440	quarter corner	Lost	none	GLO	0	NONE	pt falls in road	3130656.247	700064.231	6783.187
3424E20	300340	quarter corner	Lost	none	GLO	0	fence	fence 8'S	3128906.475	693662.128	6778.114
3424E24	700340	quarter corner	Lost	none	GLO	0	NONE	pt in road	3129048.049	700102.843	6853.821
3424E25	700240	quarter corner	Lost	none	GLO	0	NONE	pt in road	3127439.747	700141.499	6788.472
3424E31	200140	quarter corner	Existent	stone corner	GLO	0	NONE	in n-s fenceline	3125656.604	692135.321	6744.192
3424E36	700140										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3424N07	140600	quarter corner	Lost	none	GLO	0	NONE	pt in road	3125827.128	700182.858	6702.614
3424N20	240400	quarter corner	Obliterated	aluminum cap	other	1993	ORIG. STONE ?	in e-w fenceline LS#6769	3132863.863	691153.347	7000.531
3424N24	640400	quarter corner	Lost	none	GLO	0	fence	fence 5'E	3129695.177	692838.596	6831.767
3424N30	140300	quarter corner	Lost	none	GLO	0	fnc jnct	S-E-W fnc jnct	3129841.459	699284.371	6806.345
3424NE02	600700	quarter corner	Lost	none	GLO	0	NONE	pt in field	3128049.651	691269.692	6923.297
3424NE07	200600	Section Corner	Obliterated	Not Set	Private	2013	Road/Fenceline	Set by found property corner monuments	3134650.683	698358.556	0
3424NE12	700600	section corner	Obliterated	aluminum cap	other	1993	NONE	in plowed field LS#6769	3132883.233	691958.813	6906.716
3424NE13	700500	section corner	Lost	none	GLO	0	NONE	pt on edge of road	3133068.7	700006.303	6810.66
3424NE24	700400	section corner	Lost	none	GLO	0	NONE	pt on edge of road	3131460.402	700044.95	6837.637

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3424NE36</i>	<i>700200</i>	section corner	Lost	none	GLO	0	NONE	pt falls in road	3129852.122	700083.542	6834.794
<i>3424NW02</i>	<i>500700</i>	section corner	Lost	none	GLO	0	NONE	pt in road	3126635.561	700160.828	6797.038
<i>3424NW07</i>	<i>100600</i>	Section Corner	Obliterated	Plastic Cap	Private	2004	Road/Fenceline	Proportioned Corner by private surveyor	3134608.631	696755.128	6768.7
<i>3424NW14</i>	<i>500500</i>	witness corner	Obliterated	aluminum cap	other	1993	NONE	pt in HWY, mon is wc LS#6769	3132848.419	690392.431	7062.418
<i>3424NW24</i>	<i>600400</i>	section corner	Lost	none	GLO	0	NONE	pt. on road edge	3131402.427	696838.27	6861.447
<i>3424NW29</i>	<i>200300</i>	section corner	Existent	stone corner	GLO	0	new BT, s23	in e-w fenceline	3129822.143	698479.293	6760.254
<i>3424NW30</i>	<i>100300</i>	section corner	Lost	none	GLO	0	fence jnct	10' W fnc jnct	3128067.959	692073.794	6822.439
<i>3424NW36</i>	<i>600200</i>	section corner	Lost	none	GLO	0	NONE	pt in field	3128031.745	690479.586	6907.764
<i>3424S01</i>	<i>640600</i>	section corner	Lost	none	GLO	0	NONE	cleared area	3126596.317	698557.963	6778.208

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Lost	none	GLO	0	e/w fnc jnct 20' N	e/w/s fence jct 80'sw	3133068.943	699214.417	6752.592
3424S02	540600										
		Quarter Corner	Obliterated	Aluminum Cap	Private	2013	Road/Fenceline	Set by fence extensions & road centerline	3133016.334	697589.524	6822.7
3424S03	440600										
		quarter corner	Lost	none	GLO	0	S/E FENCE JCT 80'SW	pt. falls in open wheat field	3132991.405	695995.245	6814.485
3424S04	340600										
		quarter corner	Lost	none	GLO	0	NONE	pt in plowed field	3132942.036	694369.231	6803.744
3424S10	440500										
		Quarter Corner	Existent	Aluminum Cap	County	2012	MAG. MEM X IN STONE BTS 10&15	RESET FRM ORIG BT	3131370.697	696018.253	6805.025
3424S20	240300										
		quarter corner	Lost	none	GLO	0	NONE	pt in field	3128086.709	692877.954	6806.347
3424S23	540300										
		quarter corner	Lost	other	GLO	0	boulder found		3128185.455	697717.351	6611.612
3424S24	640300										
		Quarter Corner	Lost	Stone Corner	GLO	1901	NONE	FNCEPRJN&E	3128229.316	699310.1	6785.215
3424S25	640200										
		Quarter Corner	Lost	Stone Corner	GLO	1901	NONE	OLDFNCPRJN &E	3126616.167	699355.914	6774.233
3424S29	240200										
		quarter corner	Existent	stone corner	GLO	0	BT, s32	in rock pile	3126476.836	692920.055	6735.767

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3424S30	140200	quarter corner	Lost	none	GLO	0	fence	n-s fence 10' west	3126439.735	691311.807	6633.352
3424S31	140100	quarter corner	Existent	stone corner	GLO	0	NONE	-1901	3124838.351	691351.619	6826.661
3424S32	240100	Quarter Corner	Existent	Stone Corner	GLO	1901	NONE	FNC PRJ E&W	3124876.388	692958.979	6736.356
3424S34	440100	Section Corner	Existent	Stone Corner	GLO	1901	ORG BTS	ORG BTS S3&N34 DOWN	3124948.959	696179.33	6502.041
3424S36	640100	quarter corner	Existent	stone corner	GLO	0	new BT, s36,s01		3125003.48	699398.256	6725.715
3424SE02	600600	Section Corner	Obliterated	Not Set	Private	2013	Road/Fenceline	Set by fence extensions	3133040.864	698396.512	0
3424SE05	300600	section corner	Existent	stone corner	GLO	0	BT, s4,s9	in rock pile	3132923.151	693565.077	6744.867
3424SE20	300300	section corner	Lost	none	GLO	0	NONE	pt in field	3128104.713	693681.563	6776.152
3424SE24	700300	section corner	Lost	none	GLO	0	E-W FENCE	fence	3128243.91	700122.131	6788.451
3424SE31	200100										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3424SE36	700100	Section Corner	Lost	None	GLO	1901	NONE	FNC CRNR	3124856.982	692155.731	6828.296
3424SW02	500600	section corner	Lost	none	GLO	0	N/S FENCELINE 25'WEST	pt falls in open plowed field	3125026.948	700206.668	6753.908
3424SW03	400600	Section Corner	Obliterated	Aluminum Cap	Private	2013	Road/Fenceline	Set by boundary fences	3132993.897	696779.739	6807.6
3424SW12	600500	section corner	Lost	none	GLO	0	NONE	pt. falls in open wheat field	3132972.448	695191.02	6810.705
3424SW14	500400	section corner	Lost	none	GLO	0	fence	40' NW of W-E fnc	3131421.269	698440.113	6759.003
3424SW23	500300	section corner	Lost	none	GLO	0	E/S FENCE JCT., 75'SW	pt. in open field plowed field	3129794.177	696877.231	6821.623
3424SW24	600300	section corner	Existent	stone corner	GLO	0	ROCK PILE-WEST	in burn area	3128168.191	696901.859	6509.428
3424SW28	300200	Section Corner	Existent	Stone Corner	GLO	1901	ORIG STN	NEW BTS 23 24 25 26	3128210.438	698507.783	6771.361
3424SW29	200200	section corner	Existent	stone corner	GLO	0	notched BT,s33/ rk mnd	rock mound@locus only	3126496.314	693724.114	6751.523

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3424SW30	100200	section corner	Existent	stone corner	GLO	0	BT, no scribing	in n-s fenceline	3126459.19	692114.397	6681.6
3424SW31	100100	section corner	Lost	none	GLO	0	NONE	pt in field	3126421.722	690520.402	6674.514
3424SW34	400100	section corner	Existent	stone corner	GLO	0	ORIGINAL STONE ?	@ fence jct	3124819.59	690558.006	6867.569
3424SW36	600100	section corner	Existent	stone corner	GLO	0	BT,s34,s03,s04,s33	in rock pile	3124934.78	695374.558	6471.68
3424W02	500640	section corner	Existent	stone corner	GLO	0	BT,s1,s2,s35,s36	in rock pile BT, s36 down, 1901	3124988.056	698597.148	6451.666
3424W03	400640	Quarter Corner	Obliterated	Aluminum Cap	Private	2013	Road/Fenceline	Proportioned Corner by private surveyor	3133800.144	696762.794	6820.1
3424W11	500540	quarter corner	Lost	none	GLO	0	NONE		3133775.737	695171.642	6609.997
3424W12	600540	quarter corner	Lost	none	GLO	0	NONE	pt falls in open wheat field	3132206.563	696818.851	6840.052
3424W13	600440	quarter corner	Lost	none	GLO	0	fence	10' W n-s fence	3132225.327	698420.549	6786.278

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Quarter Corner	Lost	Stone Corner	GLO	1901	NONE	FNCPRJE&W	3130628.518	698457.875	6747.217
3424W14	500440										
		quarter corner	Lost	none	GLO	0	NONE	pt. in open field	3130598.334	696857.72	6840.054
3424W23	500340										
		quarter corner	Lost	none	GLO	0	N/S FENCELINE 50"W	pt. falls in open wheat field	3128990.088	696896.736	6771.818
3424W24	600340										
		quarter corner	Lost	none	GLO	0	NONE	pt falls in open plowed field	3129008.772	698500.25	6819.276
3424W25	600240										
		quarter corner	Lost	none	GLO	0	NONE		3127400.472	698539.596	6658.13
3424W26	500240										
		quarter corner	Lost	none	GLO	0	NONE	diligent search no remaining evidence	3127363.937	696921.163	6339.845
3424W28	300240										
		quarter corner	Existent	stone corner	GLO	0	BT, s27,s28	cfm in rock pile	3127300.538	693701.161	6763.328
3424W29	200240										
		quarter corner	Lost	none	GLO	0	NONE	pt in field	3127262.258	692096.907	6891.94
3424W31	100140										
		quarter corner	Existent	stone corner	GLO	0	NONE	in n-s fenceline	3125623.688	690538.883	6813.844
3424W36	600140										
		quarter corner	Lost	none	GLO	0	NONE	pt. falls in open wheat field	3125792.304	698577.463	6737.26

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3425E06	200640	quarter corner	Existent	brass cap	GLO	1911	NONE	in n-s fenceline	3133909.379	701580.458	6816.679
3425E07	200540	quarter corner	Lost	none	GLO	0	NONE	pt in plowed field	3132300.128	701616.087	6835.519
3425E1607-18	160500	Sixteenth Corner	No Observation	Aluminum Cap	USFS	1997	A.C. 8" above ground	On S slope at edge of dense Oakbrush.	3131055.498	681970.171	0
3425E18	200440	quarter corner	Lost	none	GLO	0	fence jct	n-s-w fnc jct	3130688.389	701647.184	6836.587
3425E19	200340	quarter corner	Existent	brass cap	GLO	1911	NONE	n-s-w fence jct	3129081.2	701680.276	6801.945
3425E30	200240	quarter corner	Existent	brass cap	GLO	1911	NONE	in n-s fence	3127472.907	701717.204	6751.99
3425N07	140600	quarter corner	Existent	brass cap	GLO	1911	fnd out near fnc jct	reset using SP#642	3133084.797	700795.814	6805.538
3425N08	240600	quarter corner	Existent	brass cap	GLO	1911	NONE		3133123.3	702404.783	6824.05
3425N18	140500	Quarter Corner	Lost	None	GLO	1911	NONE	IN RD 338	3131478.203	700831.392	6815.18
3425N31	140200										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3425NE07	200600	quarter corner	Existent	brass cap	GLO	1911	NONE	@ n-s-e fence jnct	3126652.94	700928.749	6780.356
3425NE18	200500	section corner	Existent	brass cap	GLO	1911	NONE	@edge of field	3133104.334	701599.88	6819.498
3425NE19	200400	Section Corner	Lost	None	GLO	1911	NONE	INTERSECTIO N RDS 310&338	3131495.209	701635.618	6816.604
3425NE31	200200	section corner	Lost	none	GLO	0	NONE		3129885.385	701663.713	6831.048
3425NW07	100600	section corner	Existent	brass cap	GLO	1911	NONE	@ n-w fence jnct	3126669.731	701732.312	6746.129
3425S08	240500	closing corner	Existent	brass cap	GLO	1911	NONE	BK1,PG2,3,33	3133065.546	700020.51	6811.263
3425S18	140400	Quarter Corner	Existent	Aluminum Cap	County	2012	OLD BT STUMP	RP S8 NEW BT S17	3131515.495	702439.759	6863.437
3425S19	140300	quarter corner	Existent	brass cap	GLO	1911	NONE	e-w fence 24'-n	3129865.743	700865.507	6855.234
3425SE19	200300	Quarter Corner	Existent	Brass Cap	GLO	1911	ORIG MON	IN FARM FIELD AT FNC NEAR CEDAR POST	3128262.048	700899.059	6798.616

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		section corner	Existent	aluminum cap	County	2007	parol	set by SJC from paroll evidence	3128277.373	701701.964	6799.138
3425SE26	600200										
		Section Corner	No Observation	Spike	Private	2009	Spike w/cap LS 155675	RMs fence corner, telephone box, fire hydrant.	3126828.745	708160.375	0
3425SW07	100500										
		closing corner	Existent	brass cap	GLO	1911	CFM, 1911 GLO Mon.	CC in county rd.	3131461.661	700047.71	6837.044
3425SW18	100400										
		closing corner	Lost	none	GLO	0	NONE	pt falls in road	3129849.101	700086.308	6835.15
3425SW26	500200										
		Section Corner	No Observation	Rebar Cap	Private	2009	Rebar w/cap LS 155675	RMs telephone box, fence corner, powerpole.	3126789.108	706553.177	0
3426N21	340400										
		Quarter Corner	No Observation	Brass Cap	GLO	0	B.C.	34' W of 8" cedar tree.	3130186.24	713724.08	0
3426NE21	400400										
		Section Corner	No Observation	Brass Cap	GLO	0	B.C.	Set aluminum tags in fence post as RMs	3130206.916	714528.527	0
3426S21	340300										
		Quarter Corner	No Observation	Brass Cap	GLO	0	B.C.	Set aluminum tags in fence posts	3128337.675	704108.04	0
3426SE21	400300										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		Section Corner	No Observation	Brass Cap	GLO	0	B.C.	Set aluminum tags in fence posts	3128357.626	704912.032	0
<i>3520N06</i>	<i>140700</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1929	B.C. 6" above ground	100' SE of a dam in the drainage	3124041.346	652826.452	0
<i>3520NW06</i>	<i>100700</i>										
		Section Corner	No Observation	Brass Cap	GLO	1929	B.C. 21" above ground	Three BTs live add sign to them. SW BT dead and down	3124025.812	652022.237	0
<i>3520W06</i>	<i>100640</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1929	B.C. 6" above ground	NW BT alive add sign. NE BT dead not readable.	3123221.617	652037.962	0
<i>3521S13</i>	<i>640400</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1929	B.C. 7" above ground	36' S of E-W fence. BTs dead on ground.	3119568.479	670595.042	0
<i>3521S14</i>	<i>540400</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1929	B.C. 12" above ground	Two BTs 1 is dead on ground.	3119534.484	668988.049	0
<i>3521SE14</i>	<i>600400</i>										
		Section Corner	No Observation	Brass Cap	GLO	1929	B.C. 18" above ground	Three remaining BTs. NE is dead and down.	3119551.694	669789.195	0
<i>3522CS1628</i>	<i>340220</i>										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Sixteenth Corner	No Observation	Brass Cap	BLM	1998	A.C. 6" above ground	SJC reset BLM mon. 2002 set 2 RPs PK nail washer	3116854.003	675463.351	0
3522NE06	100700										
		Section Corner	No Observation	Brass Cap	GLO	1915	B.C. 15" above ground	Fairly open area	3124400.558	671302.492	0
3522NW20	200400										
		Section Corner	Existent	Brass Cap	GLO	1915	ORG MON	FNC 4FT N	3119618.189	672999.276	7147.217
3522S25	640200										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C. 10" above ground	Two BTs. 40' W of fence.	3116552.268	680290.249	0
3522S32	240100										
		quarter corner	Existent	brass cap	GLO	1912	no orig. none set	bent over in sage std.cor.	3114811.878	673897.355	6763.65
3522S33	340100										
		Section Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 1IN N	3114843.358	675501.662	6748.367
3522S34	440100										
		quarter corner	Existent	brass cap	GLO	1912	NONE	in e/w fenceline 7th parallel	3114875.181	677108.541	6723.529
3522S35	540100										
		quarter corner	Existent	brass cap	GLO	1912	NONE	s.c 35/02 7th st. parallel	3114909.064	678716.611	6234.829
3522SE25	700200										
		Section Corner	No Observation	Brass Cap	GLO	1911	B.C. 5" above ground	Near plowed field under tall sage brush.	3116569.209	681095.528	0
3522SE32	300100										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3522SE34	500100	section corner	Existent	brass cap	GLO	1912	no orig,set bt,s32,s5	std corner	3114827.511	674698.904	6620.233
3522SE36	700100	section corner	Existent	brass cap	GLO	1912	BT	s.c. 7th parallel	3114891.91	677912.853	6574.326
3522SW20	200300	section corner	Existent	brass cap	GLO	1911	BT	s.c. 36/31/01 7th st. parallel	3114960.426	681128.263	6173.575
3522SW32	200100	Section Corner	Existent	Brass Cap	GLO	1915	ORIG BT'S	WASH 30FT WEST STEEP SLOPE	3118008.629	673028.443	6714.965
3522SW34	400100	section corner	Existent	brass cap	GLO	1912	BT,S31,S32	std corner	3114796.298	673093.976	6766.328
3522SW36	600100	section corner	Existent	brass cap	GLO	1912	NONE	s.c. 33/34/04 7th st parallel	3114859.122	676304.486	6689.498
3522W20	200340	section corner	Existent	brass cap	GLO	1912	NONE	s.c. 36/35/02 7th st. parallel	3114926.164	679519.686	6176.817
3523CN1604	340660	Quarter Corner	Existent	Brass Cap	GLO	1915	ORG MON	TOP OF RIDGE BEARS N&S	3118813.504	673014.156	6981.992
3523CW1609	320540	Section Corner	No Observation	Aluminum Cap	USFS	1986	A.C. 15" above ground	Rock collar to top of cap	3124290.845	684950.846	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1988	A.C. 10" above ground	Monument set 0.1' E of 1/2" rebar of Private Survey	3122273.278	684601.373	0
3523CW1616	320440										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1988	A.C. 10" above ground	On broken E slope of Devils Canyon	3120666.869	684640.197	0
3523E09	400540										
		Sixteenth Corner	No Observation	Brass Cap	GLO	1911	B.C. 12" above ground	N 6" from 12' tall guard post.	3122298.896	685806.381	0
3523E16	400440										
		Sixteenth Corner	No Observation	Brass Cap	GLO	1911	B.C. 12" above ground	1' NE of fence jct. fences project N,S, and E.	3120692.25	685846.437	0
3523N1608-09	300560										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1989	A.C. 6" above ground	On steep E facing slope.	3122666.227	684188.958	0
3523NW1609	320560										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1988	A.C. 20" above ground	6' SE of old cedar, 23' S of rock mound both with old bndry signs.	3122674.799	684590.511	0
3523S09	340500										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C. 2" above ground	1" W of fence jct. Fences project N,S,and E.	3121478.661	685025.012	0
3523S16	340400										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C. 12" above ground	1 BT found 42' SE of corner a	3119871.931	685059.542	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
									35" Pine		
3523SE09	400500										
		Section Corner	No Observation	Brass Cap	GLO	1911	B.C. 8" above ground	2 BTs one 42' S, and another 100' E.	3121495.611	685828.838	0
3523W1609-16	320500										
		Sixteenth Corner	No Observation	Aluminum Cap	USFS	1988	A.C. 16" above ground	16' N of E-W fence. 125' E of E rim of Devils Canyon. Pvt rebar .3' S	3121470.206	684623.099	0
3523W1616-21	320400										
		Sixteenth Corner	No Observation	Brass Tablet	USFS	1988	Brass tablet in sandstone	Brass tablet set flush in sandstone ledge 7' N of E-W fence.	3119863.482	684657.298	0
3524E12	700540										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C.	Brass cap in stone mound. .5 miles S of road 355 & 384 intersection.	3122613.467	700251.671	0
3525E11	600540										
		Quarter Corner	Obliterated	Aluminum Cap	Private	2013	Old fence 22' East		3122813.226	708246.467	6790.3
3525E14	600440										
		Quarter Corner	Obliterated	Aluminum Cap	Private	2013	None		3121207.265	708284.768	6604.4
		Quarter Corner	Obliterated	Aluminum Cap	Private	2013	None		3121167.184	706675.817	6753.9
3525N10	640700										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C.	Brass cap bent	3125241.591	708996.235	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
3525N14	540500							down to ground. 15' N of fence jct.			
3525NE01	700700	Quarter Corner	Obliterated	Aluminum Cap	Private	2013	None		3121991.242	707460.907	6695.9
3525NE14	500500	Section Corner	No Observation	Aluminum Cap	Private	2005	A.C. below road grade	Set new monument by double porportion. GLO cap found out of position. ROS 748	3125261.779	709799.94	0
3525S02	540600	Section Corner	Obliterated	Aluminum Cap	Private	2013	None		3121972.214	706655.527	6730.3
3525S12	640600	Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C.	At 3-way fence jct. fences project E-W, and S	3123596.957	707428.732	0
		Quarter Corner	No Observation	Aluminum Cap	Private	2005	A.C. below road grade	#5 rebar with Aluminum Cap below grade. ROS 748	3123636.948	709036.603	0
3525S14	540400	Quarter Corner	Existent	Aluminum Cap	Private	2013	Orig. Mon on grnd	Orig BT	3122028.399	709071.462	6701.5
3525SE01	700600	Quarter Corner	Existent	Aluminum Cap	Private	2013	Orig. pipe w/cap alongside		3120383.32	707500.232	6652.8

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Section Corner	No Observation	Aluminum Cap	Private	2005	A.C. below road grade	#5 rebar w/aluminum cap below grade. ROS 748	3123656.671	709840.27	0
3525SE14	600400										
		Section Corner	Existent	Brass Cap	GLO	1911	Orig monument		3120404.295	708303.299	6566.618
3525SW01	600600										
		Section Corner	No Observation	Aluminum Cap	Private	2005	A.C. below road grade	#5 rebar w/ aluminum cap below grade. ROS 748	3123617.294	708232.932	0
3525SW14	500400										
		Section Corner	Obliterated	Aluminum Cap	Private	2013	Orig. Mon. out of ground		3120362.165	706696.114	6738.3
3525W01	600640										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C.	Monument located in N-S fenceline.	3124421.193	708212.678	0
3526NE06	200700										
		Section Corner	No Observation	Aluminum Cap	Private	2005	A.C. below road grade	Reset using orig BT.	3125303.057	711407.468	0
3526S06	140600										
		Quarter Corner	No Observation	Brass Cap	GLO	1911	B.C.	At fence corner fences project N, and W	3123676.614	710643.694	0
3619S36	640100										
		Quarter Corner	No Observation	Brass Cap	BLM	1957	B.C. 4" above ground	Set in rock collar	3105735.824	652300.279	0
3619SE36	700100										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Section Corner	No Observation	Brass Cap	BLM	1957	B.C. 6" above ground	Found in slide area buried 4-6" deep expose and make stone collar	3105750.594	653094.588	0
3620S32	244100										
		Quarter Corner	No Observation	Brass Cap	GLO	1919	B.C. 14" above ground	Top of ridge E of ruin "Lewis Lodge"	3105791.779	655472.572	0
3620SE31	204100										
		Section Corner	No Observation	Brass Cap	GLO	1919	B.C. 16" above ground	On ridge W of ruins "Lewis Lodge" 4 standing BTs NW is dead.	3105777.835	654668.351	0
3620SE32	304100										
		Section Corner	No Observation	Brass Cap	GLO	1919	B.C. 19" above ground	4 BTs dead down and rotting away.	3105805.804	656276.901	0
3620SW31WC	103100										
		Section Corner	No Observation	Stone	GLO	0	Marked Stone	Well marked sandstone.	3105750.789	653104.7	0
3621E13	700440										
		quarter corner	Existent	brass cap	GLO	1929	BT	shot as an offset	3111737.393	672233.635	6469.701
3621E24	700340										
		quarter corner	Existent	brass cap	GLO	1929	BT		3110129.178	672263.316	6255.929
3621N25	640300										
		quarter corner	Existent	brass cap	GLO	1929	BT, s25	in rock pile	3109312.915	671476.64	6210.247
3621N36	640200										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
"Utah Coordinate System 1983 South Zone"											
<i>3621NE13</i>	<i>700500</i>	quarter corner	Existent	brass cap	GLO	1929	BT, s36	in rock pile	3107707.712	671506.7	6074.4
<i>3621SE13</i>	<i>700400</i>	section corner	Existent	brass cap	GLO	1929	BT		3112541.714	672217.299	6565.659
<i>3622C07</i>	<i>140540</i>	section corner	Existent	brass cap	GLO	1929	none		3110933.151	672247.679	6370.01
<i>3622C08</i>	<i>240540</i>	Quarter Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST N 1FT	3113349.054	672928.477	6588.214
<i>3622C13</i>	<i>640440</i>	quarter corner	Existent	aluminum cap	BLM	2010		T-post North of mon.	3113383.762	674532.029	6431.597
<i>3622C17</i>	<i>240440</i>	quarter corner	Existent	aluminum cap	BLM	1979	NONE	c 1/4 - 13 red T post by monmt.	3111993.825	680997.556	6301.711
<i>3622C21</i>	<i>340340</i>	Quarter Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 3IN N	3111780.382	674568.154	6207.054
<i>3622C25</i>	<i>640240</i>	quarter corner	Existent	aluminum cap	BLM	1984	NONE		3110207.118	676208.113	6292.945
<i>3622C27</i>	<i>440240</i>	quarter corner	Existent	brass cap	BLM	1978	NONE	c1/4	3108677.37	681059.561	6015.552
<i>3622C28</i>	<i>340240</i>	quarter corner	Existent	aluminum cap	County	2008	RP1,2	reset by sjc	3108623.517	677850.149	6147.598

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
"Utah Coordinate System 1983 South Zone"											
<i>3622C33</i>		quarter corner	Existent	aluminum cap	BLM	1984	BT,S52W 6.5lks	C1/4 s28	3108596.354	676240.877	6161.013
	340140										
<i>3622C34</i>		quarter corner	Existent	aluminum cap	BLM	1984	NONE		3106988.558	676273.356	6037.731
	440140										
<i>3622CE1607WC</i>		quarter corner	Existent	aluminum cap	BLM	1984	NEW RP'S SET BY SJC,	6"below gnd	3107014.411	677883.84	6040.94
	160540										
<i>3622CE1608</i>		Witness Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	DEEP WSH 5FT W	3113352.318	673332.155	6567.291
	260540										
<i>3622CE1625</i>		Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	IN LRG MNT OF STN	3113392.127	674934.381	6529.941
	660240										
<i>3622CE1628</i>		sixteenth corner	Existent	brass cap	BLM	1978	NONE	CE1/16 s25	3108679.683	681462.23	6011.189
	360240										
<i>3622CE1633</i>		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE		3108602.239	676641.48	6139.439
	360140										
<i>3622CN1613</i>		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE		3106994.107	676677.12	6010.188
	640460										
<i>3622CNN13</i>		sixteenth corner	Existent	aluminum cap	BLM	1979	NONE	cn1/16 - 13	3112459.267	680990.134	6339.173
	640470										
		64th	Existent	aluminum cap	BLM	1979	NONE	cnn 1/64 - 13	3112691.945	680986.418	6308.231

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3622CNNW13	620470										
		64th	Existent	aluminum cap	BLM	1979	NONE	cnw 1/64 - 13	3112699.174	680583.392	6389.516
3622CNSS17	240415										
		1/256th Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 6IN N N&S WSH 5FT E	3111277.832	674579.27	6166.425
3622CNSWSE17	250415										
		1/256th Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	FNC CNR 20FT N	3111282.076	674780.219	6388.398
3622CS1605	240620										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 6IN E	3114586.453	674505.876	6533.969
3622CS1606	140620										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-POST 2IN N	3114556.912	672901.654	6723.52
3622CS1612	640520										
		sixteenth corner	Existent	aluminum cap	BLM	1979	NONE		3113268.037	680975.712	6106.451
3622CS1622	440320										
		Sixteenth Corner	No Observation	Nail	Private	2002	Nail w/washer	2 RMs E and W of mon. in fencelines	3109832.143	677824.688	0
3622CS1628	340220										
		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE		3108193.56	676249.465	6113.845
3622CSNS17	240430										
		1/256th Corner	Existent	Brass Cap	BLM	2010	ORG MON	MON IN LRG BLDR	3111478.823	674574.789	6220.612

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3622CSNWSE17	250425	1/256th Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	MON 18IN W OF FNC PRJ N&S	3111482.873	674775.804	6401.914
3622CW1608	220540	Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	LRG MNT OF STN T-PST 6IN W	3113375.476	674133.784	6466.314
3622CW1613	620440	sixteenth corner	Existent	aluminum cap	BLM	1979	NONE	cw 1/16 - 13	3112046.263	680594.121	6317.67
3622CW1621	320340	sixteenth corner	Existent	aluminum cap	BLM	1984	NONE		3110198.636	675806.262	6311.578
3622CW1628	320240	sixteenth corner	Existent	aluminum cap	BLM	1984	NONE		3108590.776	675837.185	6154.37
3622CW1634	420140	sixteenth corner	Existent	aluminum cap	BLM	1984	BTS34 NE 49'	in rock pile	3107006.836	677481.783	6009.16
3622E08	300540	Quarter Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 2IN N	3113400.54	675336.815	6543.843
3622E12	700540	Quarter Corner	Existent	Brass Cap	BLM	1978	ORG BTS	LEFT SIDE OF LRG DRAW	3113502.959	681764.954	6070.895
3622E13	700440	quarter corner	Existent	brass cap	BLM	1978	NONE	on lt. bank canal	3111890.43	681794.08	6085.594

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3622E1605/08	260600	Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 6IN S	3114191.642	674916.045	6651.985
3622E1606/07	160600	Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T POST 3IN N	3114162.096	673311.56	6679.247
3622E1608/17	260500	Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	TPST 3IN N	3112589.204	674952.839	6332.579
3622E1610	460600	sixteenth corner	Existent	brass cap	BLM	1978	NONE	e1/16 - 10 - 3/10	3114269.621	678125.169	6500.509
3622E1611	560600	witness corner	Existent	brass cap	BLM	1978	NONE	wc e1/16 - 2/11 as described in notes	3114463.162	679752.198	6115.743
3622E1622	460400	sixteenth corner	Existent	brass cap	BLM	1978	NONE	E1/16 s15/22 fence	3111046.974	678201.343	6280.169
3622E1628	360200	sixteenth corner	Existent	aluminum cap	BLM	1984	NONE	E1/16 s28/s33	3107796.869	676659.349	6083.812
3622E1633	360100	sixteenth corner	Existent	aluminum cap	BLM	1984	NONE	E1/16 s33/s4	3106190.579	676691.527	5923.553
3622E1636	660200										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3622E24	700340	sixteenth corner	Existent	brass cap	BLM	1978	NONE	E1/16 s25/s36	3107888.193	681482.676	6011.208
3622E25	700240	quarter corner	Existent	brass cap	BLM	1978	BT		3110286.351	681832.867	6048.757
3622E36	700140	quarter corner	Existent	brass cap	BLM	1978	BT, s25 stone mound		3108682.029	681864.856	6053.7
3622EW13	630500	quarter corner	Existent	aluminum cap	Local	1981	NONE	ros# 692	3107084.091	681902.43	5918.646
3622N05	240700	64th	Existent	aluminum cap	BLM	1979	NONE	ew 1/64 - 12/13	3112920.899	680781.048	6362.884
3622N06	140700	Quarter Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 5IN N	3114823.637	674501.311	6571.643
3622N07	140600	Quarter Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-POST LRG MNT OF STN	3114792.971	672899.601	6750.693
3622N08	240600	Section Corner	Existent	Aluminum Cap	BLM	2009	ORG MON	2 TRK RD 20FT W	3114153.319	672905.07	6687.85
3622N10	440600	quarter corner	Existent	aluminum cap	County	2008	BT, S5,S8	reset from bt's	3114181.948	674513.718	6482.48
3622N11		quarter corner	Existent	brass cap	BLM	1978	Orig. BT S. 3	near starv. resvr.	3114261.044	677721.363	6559.64

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3622N11</i>	<i>540600</i>								"Utah Coordinate System 1983 South Zone"		
		quarter corner	Existent	brass cap	GLO	1939	BT		3114400.713	679339.042	6226.853
<i>3622N12</i>	<i>640600</i>										
		quarter corner	Existent	brass cap	GLO	1939	NONE	in e/w fenceline	3114529.813	680949.49	6111.634
<i>3622N13</i>	<i>640500</i>										
		quarter corner	Existent	brass cap	BLM	1978	BT, s12,s13		3112924.89	680982.77	6315.438
<i>3622N14</i>	<i>540400</i>										
		quarter corner	Existent	brass cap	BLM	1978	NONE	in e/w fenceline	3112787.321	679372.876	6314.793
<i>3622N15</i>	<i>440500</i>										
		quarter corner	Existent	brass cap	BLM	1978	NONE	at fence jct	3112656.774	677760.152	6418.436
<i>3622N16</i>	<i>340500</i>										
		quarter corner	Existent	brass cap	GLO	1912	NONE	at N/S fence jct.	3112619.79	676152.136	6483.116
<i>3622N1613</i>	<i>600460</i>										
		sixteenth corner	Lost	none	other	0	NONE	n1/16 -13/14	3112500.891	680183.59	6342.733
<i>3622N1627</i>	<i>400260</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE	N1/16 s27/s28 N/S/W fence	3109011.605	677035.521	6097.278
<i>3622N1628</i>	<i>300260</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE	N1/16 s28/s29	3108985.55	675426.093	6193.658
<i>3622N17</i>	<i>240500</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3622N18</i>	<i>140500</i>	quarter corner	Existent	brass cap	GLO	1912	BT S8,S17	in rock pile	3112578.71	674550.487	6297.099
<i>3622N20</i>	<i>240400</i>	quarter corner	Existent	brass cap	GLO	1912	BT ,s7		3112545.813	672951.812	6481.797
<i>3622N21</i>	<i>340400</i>	quarter corner	Existent	brass cap	GLO	1912	orig. bt s17,s20	in rock pile	3110976.254	674585.927	6241.043
<i>3622N22</i>	<i>440400</i>	quarter corner	Existent	brass cap	GLO	1912	NONE	N/S/E fence cor.	3111013.054	676192.581	6355.41
<i>3622N23</i>	<i>540400</i>	quarter corner	Existent	aluminum cap	County	2008	RM, S15,S22	reset by sjc	3111041.446	677798.859	6322.85
<i>3622N24</i>	<i>640400</i>	quarter corner	Existent	brass cap	BLM	1978	NONE	at fence jct.	3111072.362	679405.176	6224.661
<i>3622N27</i>	<i>440300</i>	quarter corner	Existent	brass cap	BLM	1978	BT , s13,S24		3111102.536	681011.76	6269.127
<i>3622N28</i>	<i>340300</i>	quarter corner	Existent	nail	BLM	1978	RM,S22,S27	in rdway	3109429.61	677833.456	6208.764
<i>3622N35</i>	<i>540200</i>	quarter corner	Existent	aluminum cap	BLM	1984	NONE	in E/W fenceline	3109400.693	676223.723	6228.416
<i>3622N36</i>	<i>640200</i>	quarter corner	Existent	rebar	Local	0	stone	rebar/no cap	3107853.889	679475.311	6020.686

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Existent	brass cap	BLM	1978	BT, s25		3107892.428	681079.206	6003.605
3622NE05	300700										
		Closing Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 6IN N	3114839.453	675304.561	6681.698
3622NE06CC	200700										
		Closing Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	MON IN LRG MNT OF STN T-PST 6IN E	3114808.044	673697.997	6755.141
3622NE1628	360360										
		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE		3109005.095	676633.98	6175.019
3622NE24	700400										
		section corner	Existent	brass cap	BLM	1978	BT,s18,s19,s24,s13		3111089.023	681812.993	6176.83
3622NE36	700200										
		section corner	Existent	brass cap	BLM	1978	BT, s31, s25		3107883.956	681886.168	5898.971
3622NW03	400700										
		closing corner	Existent	brass cap	GLO	1912	BT	in e/w fenceline	3114871.059	676890.785	6669.624
3622NW04	300700										
		section corner	Lost	brass cap	GLO	1912	NONE		3114837.765	675304.328	6681.356
3622NW08	200600										
		section corner	Existent	brass cap	GLO	1912	BTS5,S8,		3114170.811	673717.917	6648.599
3622NW09	300600										
		section corner	Existent	brass cap	GLO	1912	set new bt,s5,s8	in rks e/w fence	3114201.267	675318.442	6678.756
3622NW10											

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3622NW10</i>	<i>400600</i>								<i>"Utah Coordinate System 1983 South Zone"</i>		
		section corner	Existent	brass cap	BLM	1978	NONE		3114239.316	676905.543	6609.243
<i>3622NW11</i>	<i>500600</i>										
		section corner	Existent	brass cap	GLO	1939	NONE	in n/s fenceline shot as offset	3114278.38	678529.205	6509.883
<i>3622NW12</i>	<i>600600</i>										
		section corner	Existent	brass cap	GLO	1939	BT, s11,s12		3114523.07	680147.843	6202.405
<i>3622NW13</i>	<i>600500</i>										
		section corner	Existent	brass cap	BLM	1978	NONE	In n/s/w fenceline	3112909.027	680176.558	6413.985
<i>3622NW14</i>	<i>500500</i>										
		section corner	Existent	brass cap	BLM	1978	NONE	In hay field red t-post by mont.	3112665.579	678569.305	6360.818
<i>3622NW15</i>	<i>400500</i>										
		section corner	Existent	brass cap	BLM	1978	NONE		3112640.836	676953.085	6491.859
<i>3622NW16</i>	<i>300500</i>										
		section corner	Existent	brass cap	GLO	1912	NONE		3112599.808	675355.167	6571.17
<i>3622NW1613</i>	<i>620460</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1979	NONE	nw 1/16 - 13	3112481.485	680586.94	6364.947
<i>3622NW1628</i>	<i>320260</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE		3108991.974	675829.237	6179.362
<i>3622NW17</i>	<i>200500</i>										
		section corner	Existent	brass cap	GLO	1912	none		3112563.748	673754.494	6545.811

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3622NW18	100500	section corner	Existent	brass cap	GLO	1912	BT		3112530.522	672217.363	6564.084
3622NW21	300400	section corner	Existent	brass cap	GLO	1912	BT ,s17,s16.s21	cap stamped wrong	3110994.338	675390.133	6401.639
3622NW22	400400	section corner	Existent	brass cap	BLM	1978	BT		3111030.181	676993.778	6285.636
3622NW23	500400	section corner	Existent	brass cap	BLM	1978	NONE	E/W fence jct.	3111052.671	678603.74	6251.676
3622NW24	600400	section corner	Existent	brass cap	BLM	1978	NONE	in n/S fenceline	3111092.24	680206.184	6159.33
3622NW25	600300	section corner	Existent	brass cap	BLM	1978	BT, s26	restamped in 2004	3109474.343	680236.826	6116.539
3622NW28	300300	section corner	Existent	brass cap	GLO	1912	BT, s21		3109386.122	675418.481	6225
3622NW34	400200	section corner	Existent	aluminum cap	BLM	1984	NONE	E/W fence jct.	3107802.791	677060.642	6037.781
3622NW35	500200	section corner	Existent	aluminum cap	County	2008	RM,S34,27,26	new mon. set from r.p's	3107834.49	678672.997	6075.024
3622NW36	600200										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		section corner	Existent	aluminum cap	Local	0	NONE	1" alum cap RLS #4946 fence jct.	3107862.622	680273.263	5974.931
3622S1606/05	200620										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	OR MON	T-PST 3IN N	3114572.386	673705.384	6735.37
3622S1607/08	200520										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	RD APPRX 50FT E	3112965.51	673744.996	6584.836
3622S1612	600520										
		sixteenth corner	Existent	brass cap	BLM	1978	NONE	s1/16 - 11/12	3113314.885	680167.729	6361.025
3622S1621	300320										
		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE	S1/16 s20/s21	3109788.24	675411.352	6270.9
3622S1621-22	400320										
		Sixteenth Corner	No Observation	Aluminum Cap	Private	2002	A.C. on 3/4" rebar	Set 3 BTs marked w/blaze and washer	3109819.331	677018.576	0
3622S1625	700220										
		sixteenth corner	Existent	brass cap	BLM	1978	NONE	S1/16 s25/s30	3108282.959	681875.482	6002.504
3622S1627/28	400220										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	1984	ORIG MON	WEST WATER	3108205.413	677051.517	6009.267
3622S1628	300220										
		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE	S1/16 s28/s29	3108181.755	675444.492	6104.147
3622S18											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3622S18	140400	quarter corner	Existent	brass cap	GLO	1912	NONE	shot as an offset	3110945.167	672986.819	6347.521
3622S19	140300	quarter corner	Existent	brass cap	GLO	1912	BT		3109343.563	673023.347	6234.597
3622S23	540300	Quarter Corner	Existent	Nail	other	2008	NONE	N OF ROW MKR	3109459.151	679437.457	6119.693
3622S24	640300	quarter corner	Existent	brass cap	BLM	1978	BT		3109485.035	681039.381	6084.562
3622S27	440200	quarter corner	Existent	aluminum cap	Local	0	NONE	2" alum. Disk stamped RLS#4946	3107818.033	677866.806	6063.451
3622S28	340200	quarter corner	Existent	aluminum cap	BLM	1984	NONE		3107790.741	676257.993	6098.249
3622S31	140100	quarter corner	Existent	stone corner	GLO	0	BT	shot at mid high pt.	3106130.934	673089.029	6016.501
3622S33	340100	quarter corner	Existent	aluminum cap	BLM	1984	BT, s04		3106187.151	676289.084	5972.106
3622S34	440100	quarter corner	Existent	aluminum cap	BLM	1984	NONE	@ E/W fence jnct.	3106206.251	677900.42	5986.501
3622S35	540100										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Existent	aluminum cap	BLM	1984	NONE	E/W N/S fence jnct	3106244.32	679511.342	5940.594
3622S36	640100										
		quarter corner	Existent	aluminum cap	Local	0	NONE	LS#4946 alum cap in conc.	3106267.532	681116.087	5879.297
3622SE1605	260620										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 3IN W	3114595.414	674907.805	6704.955
3622SE1607	120520										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORIG. MON.	T POST 6" N	3112956.453	673342.545	6529.948
3622SE1625	660220										
		sixteenth corner	Existent	brass cap	BLM	1978	NONE	se1/16	3108283.959	681472.378	5950.428
3622SE24	700300										
		section corner	Existent	brass cap	BLM	1978	BT,S24,S19,S25,S30		3109483.807	681847.714	6072.175
3622SE36	700100										
		section corner	Existent	aluminum cap	BLM	1996	NONE	gate	3106281.178	681918.807	5877.77
3622SW1605	220620										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 4IN N	3114579.372	674105.619	6685.026
3622SW1612	620520										
		sixteenth corner	Existent	brass cap	BLM	1978	NONE	sw1/16 - 12	3113291.615	680571.864	6295.196
3622SW1621	320320										
		sixteenth corner	Existent	aluminum cap	BLM	1984	NONE		3109796.076	675813.622	6269.258

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3622SW1627	420220	sixteenth corner	Existent	aluminum cap	BLM	1984	NONE	in N/S fence	3108213.055	677454.985	6094.785
3622SW1628	320220	sixteenth corner	Existent	aluminum cap	BLM	1984	NONE		3108187.588	675847	6122.693
3622SW17	200400	section corner	Existent	brass cap	GLO	1912	none		3110963.792	673790.257	6335.037
3622SW18	100400	section corner	Existent	brass cap	GLO	1912	BT ,s18		3110925.85	672248.31	6368.832
3622SW19	100300	section corner	Existent	brass cap	GLO	1912	BT, s24,s19	BT s30 down BT s25 no evidence	3109326.192	672278.915	6231.665
3622SW20	200300	section corner	Existent	brass cap	GLO	1912	BT		3109358.52	673827.414	6186.243
3622SW22	400300	section corner	Existent	brass cap	BLM	1978	BT, s27		3109415.283	677028.996	6159.789
3622SW23	500300	section corner	Existent	brass cap	BLM	1978	NONE	in N/S fenceline	3109443.957	678638.082	6163.773
3622SW29	200200	section corner	Existent	brass cap	GLO	1912	BT stump s30		3107752.303	673863.55	6141.631
3622SW34	400100										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3622SW35	500100	section corner	Existent	aluminum cap	BLM	1984	BT, s33,s34,ss04	E/W fenceline	3106194.045	677093.921	5973.939
3622SW36	600100	section corner	Existent	aluminum cap	BLM	2004	CFM, BLM Mon. remains	@ end 100E street	3106225.31	678706.02	5950.944
3622W08	200540	section corner	Lost	none	other	0	NONE	in line with E/W fence	3106251.562	680312.029	5893.147
3622W09	300540	quarter corner	Existent	brass cap	GLO	1912	set new bt s8	bent over in sage	3113367.133	673735.569	6627.7
3622W10	400540	quarter corner	Lost	none	GLO	1912	bt s9 down,disturbed	unverified	3113404.029	675337.314	6549.339
3622W11WC	500537	quarter corner	Existent	brass cap	BLM	1978	NONE	at n/s/w fence jct	3113442.981	676931.33	6582.369
3622W12	600540	Witness Corner	Existent	Brass Cap	BLM	1978	ORIG MON	SET BT 10-11	3113452.448	678550.753	6389.516
3622W13	600440	quarter corner	Existent	brass cap	BLM	1978	BT, s11,s12		3113720.854	680159.227	6177.754
3622W14	500440	quarter corner	Existent	brass cap	BLM	1978	BT ,s14,s13		3112098.789	680190.779	6289.813
3622W15	400440	Quarter Corner	Existent	Brass Cap	BLM	1978	ORG BT	FNC PRJ E&W&S	3111859.291	678586.662	6322.712

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3622W16	300440	quarter corner	Existent	brass cap	BLM	1978	NONE	in fence jnct	3111838.392	676959.044	6372.101
3622W1605/08	220600	quarter corner	Existent	brass cap	GLO	1912	orig.bt,s17set bt s16	In rock pile	3111795.491	675371.883	6506.501
3622W1608/17	220500	Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	ORG MON	T-PST 2IN N	3114176.345	674115.882	6637.178
3622W1612	620600	Sixteenth Corner	Existent	Aluminum Cap	BLM	2010	OR MON	T-PST 4IN NE	3112571.208	674152.462	6483.512
3622W1613	620500	sixteenth corner	Existent	other	BLM	1978	wc BC LOCATED	cor. is x in stone photo is of wc BC	3114526.454	680547.535	6191.357
3622W1615	420500	sixteenth corner	Existent	aluminum cap	BLM	1979	NONE	w1/16 - 12/13	3112916.919	680579.845	6378.207
3622W1627	420200	sixteenth corner	Existent	brass cap	BLM	1978	NONE	w1/16 - 10/15	3112648.804	677356.727	6563.36
3622W1628/33	320200	sixteenth corner	Existent	other	BLM	0	NONE	W1/16 s27/s34 cap misssing	3107809.625	677464.514	6061.251
3622W17	200440	sixteenth corner	Existent	aluminum cap	BLM	1984	NONE	W1/16 s28/s33	3107784.666	675856.753	6100.207

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
3622W18	100440	quarter corner	Existent	brass cap	GLO	1912	none area chained		3111765.487	673770.182	6453.833
3622W19	100340	quarter corner	Existent	brass cap	GLO	1912	BT, s13		3111728.123	672233.753	6472.251
3622W20	200340	quarter corner	Existent	brass cap	GLO	1912	BT		3110128.298	672263.325	6257.073
3622W21	300340	quarter corner	Existent	brass cap	GLO	1912	NONE		3110161.017	673808.877	6326.721
3622W22	400340	quarter corner	Existent	aluminum cap	BLM	1984	BT ,s20		3110190.299	675404.317	6274.099
3622W23	500340	Quarter Corner	Existent	Brass Cap	BLM	2005	ORG BTS	FBR PST 6IN S	3110223.394	677008.58	6249.889
3622W24	600340	quarter corner	Existent	brass cap	BLM	1978	NONE	in E/W fenceline	3110246.021	678621.612	6189.008
3622W25	600240	quarter corner	Existent	brass cap	BLM	1978	NONE	N/S E/W fence jct	3110282.941	680216.002	6095.977
3622W26	500240	quarter corner	Existent	brass cap	BLM	1978	NONE		3108672.611	680252.939	6011.409
3622W27	400240	quarter corner	Existent	aluminum cap	County	2008	RP, S26,S27	set new monument	3108639.011	678655.407	6100.285

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Existent	aluminum cap	Local	0	RM	2" alum cap stamped RLS#4946	3108607.908	677042.075	6057.145
3622W28	300240										
		quarter corner	Existent	brass cap	GLO	1912	NONE		3108584.905	675433.605	6152.459
3622W29	200240										
		quarter corner	Existent	brass cap	GLO	1912	BT, s30		3108555.807	673844.72	6172.077
3622W30	100240										
		quarter corner	Existent	stone corner	GLO	0	MOUND AS DESCRIBED	no bt marked	3108524.032	672294.703	6161.361
3622W32	200140										
		quarter corner	Existent	brass cap	GLO	1912	NONE	cedar post west	3106949.931	673868.665	6088.196
3622W34	400140										
		quarter corner	Existent	aluminum cap	BLM	1984	BT S33,S34	in e-w fence	3106999.1	677079.825	5935.819
3622W35	500140										
		quarter corner	Lost	none	other	0	NONE	in street 800S&100E	3107029.964	678689.535	6011.44
3622W36	600140										
		quarter corner	Existent	nail	Local	2008	RP, S36,S35	In road ros 719,692	3107054.395	680293.025	5956.601
3623S12	640500										
		Quarter Corners	No Observation	Brass Cap	GLO	1912	B.C.	Orig BTs in place.	3112929.597	690555.985	0
3623S13	640400										
		Quarter Corner	No Observation	Brass Cap	GLO	1912	B.C.	No orig BTs,	3111322.632	690593.427	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
								made "X" on nearby rocks			
3623SW13	600400										
		Section Corner	No Observation	Brass Cap	GLO	1912	B.C.	Original BTs in place	3111302.367	689788.711	0
3623W13	600440										
		Quarter Corner	No Observation	Brass Cap	GLO	1912	B.C.	Original BTs in place	3112105.884	689770.294	0
3624E10	500540										
		Quarter Corner	No Observation	Brass Cap	GLO	1918		Long Canyon Point Area	3113905.029	697728.628	0
3624E12	700540										
		Quarter Corner	No Observation	Brass Cap	GLO	1918	B.C.	Set new BTs	3113981.828	700940.512	0
3624E15	400440										
		Quarter Corner	No Observation	Brass Cap	GLO	1918		Long Canyon Point Area	3112299.493	697767.279	0
3624S03	440600										
		Quarter Corner	No Observation	Brass Cap	GLO	1918		Long Canyon Point Area	3114689.145	696903.578	0
3624S10	440500										
		Quarter Corner	No Observation	Brass Cap	GLO	1918		Long Canyon Point area	3113083.126	696942.537	0
3624S12	640500										
		Quarter Corner	No Observation	Brass Cap	GLO	1918	B.C.	Set new BTs	3113158.812	700157.638	0
3624S15	440400										
		Quarter Corner	No Observation	Brass Cap	GLO	1918		Long Canyon Point Area	3111477.726	696981.292	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3624S23	540300	Quarter Corner	No Observation	Brass Cap	GLO	1918		Approx. 17 miles down Mont. Cany. Road	3109907.123	698628.716	0
3624SE10	500500	Section Corner	No Observation	Brass Cap	GLO	1918		Long Canyon Point Area	3113102.452	697748.026	0
3624SE11	600500	Section Corner	No Observation	Brass Cap	GLO	1918		Approx. 15 miles down Mont. Cany. Road	3113139.911	699354.894	0
3624SE12	100500	Section Corner	No Observation	Brass Cap	GLO	1918	B.C.	One orig. BT set one new BT.	3113177.793	700960.379	0
3624SE14	600400	Section Corner	No Observation	Brass Cap	GLO	1918		Approx. 16 miles down Mont. Cany. Road	3111532.554	699393.5	0
3624SE15	400400	Section Corner	No Observation	Brass Cap	GLO	1918		Long Canyon Point Area	3111496.525	697786.545	0
3624SW23	500300	Section Corner	No Observation	Brass Cap	GLO	1918		Long Canyon Point Area	3109889.389	697825.27	0
3624W23	500340	Quarter Corner	No Observation	Brass Cap	GLO	1918		Long Canyon Point Area	3110692.957	697805.906	0

"Utah Coordinate System 1983 South Zone"

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3625E19	200340	Quarter Corner	No Observation	Brass Cap	GLO	1922	B.C.	Set 2 BTs	3110808.086	702540.601	0
3625N19	140400	Quarter Corner	No Observation	Brass Cap	GLO	1922	B.C.	Set 2 new BTs	3111589.871	701716.337	0
3625NE19	200400	Section Corner	No Observation	Brass Cap	GLO	1922	B.C.	2 orig BTs	3111612.414	702520.305	0
3625S05	240600	Quarter Corner	No Observation	Brass Cap	GLO	1922	B.C.	Brass Cap in stone mound	3114849.214	703240.286	0
3625S06	140600	Quarter Corner	No Observation	Brass Cap	GLO	1922	B.C.	Brass Cap in stone mound	3114806.218	701632.263	0
3625SE07	200500	Section Corner	No Observation	Brass Cap	GLO	1922	B.C.	Stone collar.	3113221.057	702477.27	0
3625SW05	200600	Section Corner	No Observation	Brass Cap	GLO	1922	B.C.	In fenceline.	3114829.24	702436.108	0
3626C27	440240	Quarter Corner	No Observation	Aluminum Cap	Private	0	A.C. 3/4" rebar	In broken N-S fenceline. Set RPs in old posts	3109543.638	716242.09	0
3626CN1627	440260	Sixteenth Corner	No Observation	Aluminum Cap	Private	2004	A.C. 3/4" rebar	N end of fenceline 31.5' S	3109945.825	716231.882	0
3626N1628-27WC											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
"Utah Coordinate System 1983 South Zone"											
3626N1628 27W400260		Sixteenth Corner	No Observation	Aluminum Cap	Private	2004	A.C. on 3/4" rebar	Set RM in fence W ROW fence.	3109925.033	715428.05	0
3626N27	440300	Quarter Corner	No Observation	Aluminum Cap	Private	2002	A.C. on 3/4" rebar	Set at capless GLO stem. Set 2 RPs.	3110348.021	716221.676	0
3626NE28	400300	Section Corner	No Observation	Aluminum Cap	Private	2004	A.C. 1' below grade	Set 2 RMs in ROW fences. Bug Point road 347	3110327.132	715418.064	0
3626S27	440200	Quarter Corner	No Observation	Iron Bar	Private	0	1" rod in rock cairn	Set 2 RMs in trees	3108739.904	716262.494	0
3626SE28	400200	Section Corner	No Observation	Brass Cap	GLO	1918	B.C. on iron bar	Set RP in power pole.	3108718.735	715458.023	0
3626W22	400340	Quarter Corner	No Observation	Brass Cap	GLO	1918	B.C. on iron bar	Set RP in W ROW fence and power pole.	3111131.742	715398.301	0
3626W27WC	400240	Quarter Corner	No Observation	Aluminum Cap	Private	2004	A.C. in E ROW fence	GLO 1" stem in road 1' below grade. Set WC in E fence.	3109522.934	715438.037	0
37222SE18	200400	section corner	Existent	stone corner	GLO	0	BT s17	notched stone	3101319.872	673977.757	5707.494

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3722C27	440240	quarter corner	Existent	aluminum cap	BLM	1983	ROCK PILE 2FT W		3098964.841	678050.992	5617.46
3722CE1603	460640	sixteenth corner	Existent	aluminum cap	other	2004	NONE	stamped ute mtn. in n/s fenceline	3105417.356	678321.657	5912.872
3722CN1603	440660	sixteenth corner	Existent	other	BLM	0	NAIL/WASH IN PWR POLE	alum. Rod in driveway	3105805.963	677911.09	5956.136
3722CN1610	440560	sixteenth corner	Existent	aluminum cap	other	2004	NONE	by t-post ute mtn. cad survey	3104201.549	677952.079	5854.15
3722CN1627	440260	sixteenth corner	Existent	aluminum cap	BLM	1983	ROCK PILE 2FT-N		3099366.307	678044.642	5600.853
3722CW1603	420640	sixteenth corner	Existent	aluminum cap	other	2004	NONE	stamped ute mtn. at n/s-e/w fence jct	3105395.856	677516.985	5917.646
3722CW1610	420540	sixteenth corner	Existent	aluminum cap	BLM	2004	NONE	In n/s fenceline	3103785.967	677560.084	5826.512
3722CW1627	420240	sixteenth corner	Existent	aluminum cap	BLM	1983	NONE	in rock pile	3098955.545	677651.66	5606.387
3722E01	700640	quarter corner	Existent	aluminum cap	BLM	1996	NONE	in e/w	3105487.434	681934.778	5814.886

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
3722E03	500640							fenceline			
3722E04	400640	Quarter Corner	Existent	Aluminum Cap	County	2012	RP ON POLE	MNT IN VLT	3105428.268	678729.588	5901.008
3722E05	300640	quarter corner	Existent	aluminum cap	BLM	2004	NONE	at fence corner 30ft south of cr 232	3105385.073	677112.272	5912.759
3722E07	200540	quarter corner	Existent	stone corner	GLO	0	BT s04	marked stone	3105362.384	675516.328	5877.92
3722E08	300540	quarter corner	Existent	aluminum cap	County	2006	BT s07, s08 stump	using BT set 3" alumn. cap	3103739.122	673931.633	5840.658
3722E10	500540	quarter corner	Existent	stone corner	GLO	0	BT stump s09	marked stone found buried -reset	3103752.814	675548.78	5847.074
3722E11	600540	quarter corner	Lost	none	other	0	NONE	cleared land shot @ n/s-e/w fence	3103842.628	680380.887	5763.97
3722E12	700540	quarter corner	Existent	aluminum cap	BLM	1997	none	in n/s wash t- post next to mon.	3103871.539	681969.838	5730.228
3722E13	700440										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Existent	aluminum cap	BLM	1997	BT s13, s18	in rock pile stamped wrong	3102265.421	682001.664	5708.388
3722E14	600440										
		quarter corner	Lost	none	other	0	none	cleared land shot 25ft s E/W fence	3102235.568	680428.085	5714.587
3722E16	400440										
		quarter corner	Lost	none	other	0	NONE	shot on fenceline	3102164.6	677184.596	5776.959
3722E1610	460600										
		sixteenth corner	Existent	aluminum cap	other	2004	NONE	in plowed field e1/16,3-10,ute svy	3104617.75	678348.247	5870.42
3722E18	200440										
		quarter corner	Existent	stone corner	GLO	0	BT s17	marked stone	3102127.795	673958.539	5774.247
3722E21	400340										
		quarter corner	Lost	none	other	0	fence 4ft north		3100556.042	677219.282	5704.957
3722E22	500340										
		quarter corner	Lost	none	other	0	NONE	pt falls in plow fld. shot @ fence 100 ft-s	3100593.489	678827.071	5717.147
3722E23	600340										
		quarter corner	Lost	none	other	0	scattered rocks	field chained/railed	3100622.741	680460.194	5707.125
3722E24	700340										
		quarter corner	Existent	aluminum cap	BLM	1987	BT S24, s19	in rock pile	3100655.419	682033.698	5660.359
3722E25	700240										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Existent	aluminum cap	BLM	1997	none	cap on rebar in stone	3099045.024	682074.729	5525.07
<i>3722E31</i>	<i>200140</i>										
		quarter corner	Existent	aluminum cap	County	2006	BT s31	use BT set 3"alum. Cap in mound of stones	3097298.119	674067.857	5533.418
<i>3722E36</i>	<i>700140</i>										
		quarter corner	Existent	aluminum cap	BLM	1997	none	in rock pile	3097438.72	682113.523	5419.966
<i>3722N05</i>	<i>240700</i>										
		quarter corner	Existent	aluminum cap	County	2006	BT S05	use BT set 3"alum. Cap in mound of stones	3106161.8	674677.223	5983.735
<i>3722N07</i>	<i>140600</i>										
		quarter corner	Existent	stone corner	GLO	0	BT s07	marked stone	3104543.277	673125.394	5924.367
<i>3722N08</i>	<i>240600</i>										
		quarter corner	Existent	stone corner	GLO	0	BT s05, s08	marked stone	3104565.099	674735.062	5899.76
<i>3722N14</i>	<i>540500</i>										
		quarter corner	Lost	none	other	0	NONE	cleared land shot on n/s fence	3103026.529	679594.624	5764.414
<i>3722N16</i>	<i>340500</i>										
		quarter corner	Existent	stone corner	GLO	0	BT s16, s09	marked stone both bt down	3102974.661	676371.442	5675.709
<i>3722N1603</i>	<i>400660</i>										
		sixteenth corner	Existent	aluminum cap	BLM	2004	BT s03, s04	n1/16, 3-4 in rock pile	3105787.536	677103.148	5918.747

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3722N1610	400560	sixteenth corner	Existent	aluminum cap	BLM	2004	none	n1/16,9-10 by t-post	3104179.096	677145.934	5827.161
3722N1627	400260	sixteenth corner	Existent	aluminum cap	BLM	1983	NONE	n 1/16, 27-28 by t-post IUC propty	3099349.109	677244.699	5652.216
3722N20	240400	quarter corner	Lost	none	other	0	NONE		3101327.13	674782.652	5458.798
3722N23	540400	quarter corner	Lost	none	other	0	NONE	cleared fields n/s/e/w shot n/s-e/w fence jc	3101410.557	679621.942	5705.581
3722N24	640400	quarter corner	Lost	none	other	0	NONE	no evidence of monumet. or acc. ?	3101443.869	681212.619	5628.999
3722N25	640300	quarter corner	Existent	stone corner	GLO	0	mound of stone N	marked stone	3099837.452	681276.019	5487.971
3722N26	540300	quarter corner	Lost	none	other	0	NONE	N\S fence 15ft east	3099834.126	679652.769	5682.951
3722N27	440300	quarter corner	Existent	aluminum cap	BLM	1983	NONE	Stamped incorrectly	3099768.094	678038.153	5561.54
3722N28	340300										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
"Utah Coordinate System 1983 South Zone"											
<i>3722N29</i>	<i>240300</i>	quarter corner	Existent	aluminum cap	BLM	1983	NONE	by rock pile	3099744.834	676438.406	5666.363
<i>3722N32</i>	<i>240200</i>	quarter corner	Existent	stone corner	GLO	0	ROCK PILE	marked stone	3099731.974	674815.259	5389.093
<i>3722N35</i>	<i>540200</i>	quarter corner	Existent	stone corner	GLO	0	BT S29	marked stone	3098110.06	674861.631	5571.036
<i>3722N36</i>	<i>640200</i>	quarter corner	Existent	stone corner	GLO	0	BT S26, s35	marked stone rocks next to corner	3098193.493	679680.079	5569.009
<i>3722NE05</i>	<i>300700</i>	quarter corner	Existent	stone corner	GLO	0	ROCK PILE	marked stone	3098231.62	681298.412	5352.106
<i>3722NE07</i>	<i>200600</i>	section corner	Existent	stone corner	GLO	1907	BT s04, s05	notched stone	3106177.85	675488.973	5842.129
<i>3722NE08</i>	<i>300600</i>	section corner	Existent	stone corner	GLO	0	BT S05, S06, S07	notched stone lying down -reset	3104540.816	673921.189	5898.243
<i>3722NE10</i>	<i>500600</i>	section corner	Existent	stone corner	GLO	0	BT S05, S08	notched stone reset	3104556.901	675532.02	5855.077
<i>3722NE12</i>	<i>700600</i>	section corner	Existent	aluminum cap	BLM	2004	NONE	at n/s-e/w fence k. ivins prop.	3104629.297	678753.422	5866.607

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3722NE13	700500	section corner	Existent	aluminum cap	BLM	1996	NONE	at n/s-e/w fence jct.	3104678.508	681954.679	5793.109
3722NE14	600500	section corner	Existent	aluminum cap	BLM	1997	BT s13	at n/s-e/w fence jct.	3103071.173	681984.707	5720.192
3722NE1603	460660	section corner	Lost	none	other	0	NONE	cleared land shot @ n/s-e/w fence	3103053.551	680406.984	5740.495
3722NE1610	460560	sixteenth corner	Existent	aluminum cap	other	2004	NONE	in n/s fenceline stamp ute mtn.	3105816.693	678312.504	5942.936
3722NE24	700400	sixteenth corner	Existent	aluminum cap	other	2004	NONE	in plowed field ute cad svy	3104212.845	678356.217	5835.743
3722NE25	700300	section corner	Existent	aluminum cap	BLM	1997	BT s24	rock pile-W stamped wrong	3101461.483	682015.732	5698.132
3722NE36	700200	section corner	Existent	aluminum cap	BLM	1997	BT s30	rock pile-W range line	3099848.83	682050.524	5668.161
3722NW05	200700	section corner	Existent	aluminum cap	BLM	1997	ROCK PILE	stone next to mon	3098241.465	682098.799	5257.699
3722NW06		section corner	Existent	stone corner	GLO	0	rocks pile	notched stone found buried -reset	3106147.996	673891.971	6007.38

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3722NW06	100700	section corner	Existent	brass cap	GLO	1947	BT s01, s06, s31, s36	in rock pile	3106118.02	672342.782	5929.812
3722NW07	100600	section corner	Existent	brass cap	GLO	1947	BT, s01,s07	wood post in rocks w	3104523.073	672371.842	5856.858
3722NW10	400600	section corner	Obliterated	aluminum cap	other	0	BT s09	in rock pile horrocks eng	3104583.137	677132.669	5860.843
3722NW1603	420660	sixteenth corner	Existent	nail	BLM	0	NAIL/WASHER IN POST	80p nail on s. side c. road 232	3105796.732	677507.135	5956.424
3722NW1610	420560	sixteenth corner	Existent	aluminum cap	BLM	2004	NONE	in e/w drainage	3104190.329	677549.002	5795.2
3722NW1627	420260	sixteenth corner	Existent	aluminum cap	BLM	1983	NONE	in rock pilenext to t-post	3099357.745	677644.697	5640.739
3722NW22	400400	section corner	Lost	none	other	0	NONE	cleared land fence jct n&e of pt.	3101360.475	677201.938	5730.934
3722NW26	500300	section corner	Existent	aluminum cap	BLM	1983	NONE	in rock pile	3099820.844	678843.714	5710.927
3722NW27	400300	section corner	Existent	aluminum cap	BLM	1983	ROCK PILE	by t-post IUC property	3099751.869	677237.191	5667.825
3722NW28											

"Utah Coordinate System 1983 South Zone"

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3722NW28	300300	section corner	Existent	stone corner	GLO	0	BT s29	notched stone	3099732.709	675635.899	5626.165
3722NW29	200300	section corner	Existent	aluminum cap	County	2006	BT s19, s20, s30	use BT set 3"alum cap in mound of stone	3099710.647	674012.369	5496.615
3722NW31	100200	section corner	Existent	brass cap	GLO	1951	none	in rock pile	3098074.69	672493.853	5268.324
3722NW32	200200	section corner	Existent	stone corner	GLO	0	BT s29,s30,s31,s32	notched stone rock pile-W	3098102.647	674047.01	5380.564
3722NW35	500200	section corner	Existent	stone corner	GLO	0	BTs27, ROCK PILE	notched stone	3098180.53	678874.479	5620.981
3722NW36	600200	section corner	Existent	stone corner	GLO	0	BT s26, ROCK PILE-W	notched stone	3098198.284	680495.265	5586.53
3722S01	640600	quarter corner	Lost	none	other	0	NONE	stone @ calc. pt. no marks /clear land	3104659.617	681150.878	5775.788
3722S02	540600	quarter corner	Lost	none	other	0	NONE	60ft s. of point	3104628.566	679558.383	5867.666
3722S04	340600	quarter corner	Existent	stone corner	GLO	0	BT s04	marked stone in rock pile	3104575.314	676322.307	5866.813
3722S07											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3722S07	140500	quarter corner	Existent	stone corner	GLO	0	NONE	marked stone	3102931.992	673143.614	5819.691
3722S08	240500	quarter corner	Existent	stone corner	GLO	0	BT s08, s17	marked stone	3102957.42	674759.402	5751.749
3722S10	440500	quarter corner	Lost	none	other	0	NONE	pt. falls in plow fld	3102991.422	677976.737	5785.945
3722S12	640500	quarter corner	Lost	none	other	0	NONE	cleared land no evidence	3103054.551	681181.363	5694.786
3722S15	440400	quarter corner	Lost	none	other	0	NONE	cleared land shot @ n/s-e/w fence	3101380.089	678008.018	5704.65
3722S16	340400	quarter corner	Existent	stone corner	GLO	0	BT s21	on EW FENCELINE	3101358.117	676399.066	5748.37
3722S1601/06	700620	sixteenth corner	Existent	aluminum cap	BLM	1996	NONE	in n/s fence S1/16, s01-s06	3105082.963	681944.694	5819.018
3722S1603	400620	sixteenth corner	Existent	aluminum cap	BLM	2004	NONE	s1/16,3-4 n/s fence 12 ft. west	3104984.101	677122.451	5896.649
3722S1627	400220	witness corner	Existent	aluminum cap	BLM	1983	NONE	wp for s1/16, 27- point falls in hwy	3098666.31	677257.518	5616.528

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3722S18	140400	quarter corner	Lost	none	other	0	buried stones	stones 6ft north 3ft west of shot	3101302.097	673173.674	5730.141
3722S19	140300	quarter corner	Existent	stone corner	GLO	0	BT s30	marked stone	3099678.449	673212.304	5607.993
3722S27	440200	quarter corner	Existent	aluminum cap	BLM	1983	BT S34 ,s27	in rocks	3098167.142	678063.623	5589.008
3722S28	340200	quarter corner	Lost	none	other	0	NONE	pt. falls in cleared IUC property	3098123.849	676463.39	5629.417
3722S30	140200	quarter corner	Existent	aluminum cap	County	2006	BT s30	use BT set 3"alum cap in mound of stone	3098096.762	673241.716	5313.399
3722S31	140100	quarter corner	Existent	stone corner	GLO	0	BT s06, s31, rock pile	marked stone	3096473.703	673285.62	5129.223
3722S32	240100	quarter corner	Lost	none	other	0	NONE	pt. falls in e/w road shot at e/w fence 12n	3096499.304	674901.542	5560.358
3722S33	340100	quarter corner	Lost	none	other	0	NONE	near fence jct n/s	3096530.125	676510.52	5562.295
3722S34	440100										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USft)
		quarter corner	Lost	none	other	0	NONE	no monument evidentno accessories	3096553.154	678106.619	5510.334
3722S35	540100										
		quarter corner	Existent	other	GLO	0	ROCK PILE	marked boulder not as described	3096592.51	679716.011	5347.651
3722S36	640100										
		quarter corner	Existent	stone corner	GLO	0	ROCK PILE	marked stone	3096620.401	681327.517	5309.946
3722SE07	200500										
		section corner	Existent	stone corner	GLO	0	ROCK MOUND	notched stone	3102936.972	673948.475	5776.868
3722SE08	300500										
		section corner	Existent	rebar	GLO	0	BT s08, s17, s16	5\8 rebar & t-post stone not found	3102949.924	675562.893	5596.307
3722SE10	500500										
		section corner	Obliterated	brass cap	other	0	NONE	in n/s fenceline bc stamped NLS 7914	3103008.715	678781.162	5777.307
3722SE14	600400										
		section corner	Existent	aluminum cap	County	2006	BT S14	use BT set 3"alum cap set in mnd of stone	3101431.315	680445.87	5630.102
3722SE15	500400										
		section corner	Lost	none	other	0	none	cleared land shot@N/S-EW fence jct	3101396.203	678811.913	5722.644
3722SE23	600300										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		section corner	Existent	stone corner	GLO	0	8' post next to stone	notched stone lying flat - reset	3099814.611	680471.116	5673.643
3722SE36	700100										
		section corner	Existent	aluminum cap	BLM	1997	NONE	in rock pile twp.&rng. line	3096632.954	682132.688	5534.826
3722SW01	600600										
		Section Corner	Obliterated	Re-Bar & Cap	Private	2009	NONE	Observed using ROS793 as reference	3104644.66	680356.591	5808.62
3722SW07	100500										
		section corner	Existent	brass cap	GLO	1947	BT s12, s18,		3102911.509	672404.12	5795.086
3722SW10	400500										
		section corner	Obliterated	brass cap	other	0	NONE	by fence jct stamped NRS 7914	3102972.521	677176.935	5795.07
3722SW16	300400										
		section corner	Existent	stone corner	GLO	0	BTs21, ROCK PILE	notched stone lying down-reset	3101342.507	675586.998	5726.847
3722SW18	100400										
		section corner	Existent	brass cap	GLO	1947	BT s13, s18, s24	in rock pile	3101292.464	672426.072	5722.516
3722SW19	100300										
		section corner	Existent	brass cap	GLO	1947	BT s19, s24, s25	next to t-post	3099685.193	672462.357	5643.709
3722SW27	400200										
		section corner	Lost	none	other	0	NONE	pt. falls in hwy. r.m.s destroyed	3098140.626	677267.234	5599.89

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3722SW28	300200	section corner	Lost	none	other	0	NONE	pt. falls in cleared IUC property	3098121.471	675670.66	5620.607
3722SW31	100100	section corner	Existent	brass cap	GLO	1947	BT s06	e/w fence line 4fts.c.r.280	3096467.18	672516.721	5077.219
3722SW32	200100	section corner	Existent	stone corner	GLO	0	ROCK PILE	notched stone	3096488.899	674086.527	5551.007
3722SW33	300100	section corner	Lost	none	other	0	NONE	pt. falls near n/s-e/w fence jct	3096512.974	675706.253	5539.617
3722SW34	400100	section corner	Lost	none	other	0	NONE	falls in highxay	3096537.09	677301.719	5567.385
3722SW35	500100	section corner	Existent	stone corner	GLO	0	ROCK PILE	notched stone	3096569.827	678910.429	5513.599
3722SW36	600100	section corner	Existent	stone corner	GLO	0	ROCK PILE	notched stone	3096595.843	680522.213	5230.472
3722W01	600640	Quarter Corner	Lost	None	Private	2009	ROS793	In intersection of CR 206 & 219	3105447.581	680335.708	5860.308
3722W05	200640	quarter corner	Lost	none	other	0	hack marks on tree	no scribes	3105345.12	673900.273	5973.071
3722W06											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3722W06	100640	quarter corner	Existent	brass cap	GLO	1947	BT s06, s01	in rock pile	3105326.858	672352.391	5886.034
3722W07	100540	quarter corner	Existent	brass cap	GLO	1947	none	area railed	3103715.903	672392.976	5867.363
3722W10	400540	quarter corner	Obliterated	brass cap	other	0	BT s09	BC in concrete stamp NLS 7914	3103774.997	677159.078	5765.42
3722W14	500440	quarter corner	Lost	none	other	0	NONE	cleared land shot @ n/s-e/w fence	3102200.123	678801.692	5748.93
3722W16	300440	quarter corner	Lost	none	other	0	NONE	pt. falls in stream channel, bank eroded	3102146.749	675569.939	5529.523
3722W1603	420700	sixteenth corner	Existent	aluminum cap	BLM	2004	NONE	w1/16 s34/s033	3106200.099	677497.234	5964.093
3722W1610	420600	sixteenth corner	Existent	aluminum cap	other	2004	NONE	w 1/16,3-10 in rock pile,ute svy	3104594.654	677537.877	5852.195
3722W1627	420300	sixteenth corner	Existent	aluminum cap	BLM	1983	NONE	w16, 22/27	3099760.006	677637.691	5644.498
3722W18	100440										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>3722W19</i>	<i>100340</i>	quarter corner	Existent	brass cap	GLO	1947	BT s18	leaning in rock pile	3102098.246	672413.84	5765.454
<i>3722W20</i>	<i>200340</i>	quarter corner	Existent	brass cap	GLO	1947	BT s19		3100491.705	672446.905	5669.412
<i>3722W21</i>	<i>300340</i>	quarter corner	Existent	stone corner	GLO	0	BT S19, S20	marked stone	3100513.325	673991.637	5575.198
<i>3722W25</i>	<i>600240</i>	quarter corner	Existent	stone corner	GLO	0	BT s21, s20	marked stone	3100537.542	675613.166	5619.013
<i>3722W26</i>	<i>500240</i>	quarter corner	Existent	stone corner	GLO	0	BT s25, s26	marked stone	3099006.144	680482.442	5629.576
<i>3722W27</i>	<i>400240</i>	quarter corner	Existent	aluminum cap	BLM	1983	NONE	in rock pile	3098983.77	678858.88	5667.467
<i>3722W28</i>	<i>300240</i>	quarter corner	Existent	aluminum cap	BLM	1983	NONE	by rock pile IUC property	3098946.218	677252.206	5631.536
<i>3722W29</i>	<i>200240</i>	quarter corner	Existent	stone corner	GLO	0	BT s29, s28	marked stone	3098925.668	675652.884	5611.244
<i>3722W30</i>	<i>100240</i>	quarter corner	Existent	stone corner	GLO	0	ROCK PILE	marked stone	3098907.447	674030.376	5387.755
<i>3722W31</i>	<i>100140</i>	quarter corner	Existent	brass cap	GLO	1951	BTs30 ,s25		3098879.457	672480.258	5411.371

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Existent	brass cap	GLO	1951	rock pile W		3097270.394	672505.186	5018.333
3722W33	300140										
		quarter corner	Lost	none	other	0	NONE	pt. falls on tailings IUC property	3097317.212	675688.503	5576.481
3722W34	400140										
		quarter corner	Lost	none	other	0	NONE	pt in highway	3097336.397	677284.601	5577.96
3722W35	500140										
		quarter corner	Existent	stone corner	GLO	0	BT s35, s34	marked stone rock pile 2ft west	3097375.182	678890.066	5571.418
3722W36	600140										
		quarter corner	Existent	other	GLO	0	ROCK PILE/MARKING	marked boulder	3097398.472	680501.093	5329.715
3725SW32	200100										
		Section Corner	No Observation	Brass Cap	GLO	1920	B.C.	In N-S fenceline. Set single BT	3097152.715	702862.793	0
3725SW33	300100										
		Section Corner	No Observation	Brass Cap	GLO	1920	B.C.	Set 2 new BTs	3097192.014	704472.802	0
3726C05	240640										
		Quarter Corner	No Observation	Aluminum Cap	Private	2001	A.C.	Set 2 BTs. SE, and SW	3106243.547	713107.971	0
3726CE1605	260640										
		Sixteenth Corner	No Observation	Aluminum Cap	Private	2001	A.C.	Set 2 BTs both in SE	3106254.256	713509.451	0
3726E05	300640										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C.	Found 2 orig. BTs SW, and NE	3106264.955	713910.93	0
<i>3726E06</i>	<i>200640</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C.	Set RPs SW, and SE	3106222.139	712305.01	0
<i>3726E1605-08</i>	<i>260600</i>										
		Sixteenth Corner	No Observation	Aluminum Cap	Private	2001	A.C.	Set 2 BTs NW, and NE	3105450.836	713530.513	0
<i>3726E1605-32</i>	<i>260700</i>										
		Sixteenth Corner	No Observation	Aluminum Cap	Private	2001	A.C.	Set RPs on fence posts.	3107059.966	713488.329	0
<i>3726N05</i>	<i>240700</i>										
		Quarter Corner	No Observation	Aluminum Cap	Private	2001	A.C.	Set RPs on fence posts.	3107049.419	713086.939	0
<i>3726NE05</i>	<i>300700</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C.	Set RPs on fence posts	3107070.543	713889.718	0
<i>3726NE06</i>	<i>200700</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C.	Found orig BTs NE, and SW	3107028.364	712284.156	0
<i>3726S05</i>	<i>240600</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C.	Found Orig. BTs NW, and SW	3105440.115	713128.933	0
<i>3726SE05</i>	<i>300600</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1915	B.C.	Found orig. BTs SW, and NE	3105461.577	713932.082	0

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
3726SE06	200600	Section Corner	No Observation	Brass Cap	GLO	1915	B.C.	Found orig BTs NE, and SW	3105418.723	712325.792	0
3912S31	140100	Quarter Corner	Existent	Aluminum Cap	County	2013	Grooves in sandstone	Aluminum Cap re-set by SJC from evidence	3075735.142	577203.521	0
3921N26	540300	quarter corner	Existent	brass cap	GLO	1952	NONE	in sandstone	3080323.846	670396.892	4605.961
3921W33	300140	quarter corner	Existent	brass cap	GLO	1947	NONE		3077827.118	666429.883	4926.257
3924N24	640400	Quarter Corner	Existent	Brass Cap	BLM	2003	None	100' south of CR 414	3082599.559	700844.142	4677.617
3924W1624-13	620400	Sixteenth Corner	Existent	Brass Cap	BLM	2003	None	Near fence,boulders & CR414	3082589.922	700439.83	4688.298
3925E18	200440	Section Corner	Existent	Brass Cap	GLO	1912	Mound of Stones - W	In N-S fence Jct.	3083460.941	703218.319	4794.42
3925NW18	100500	Section Corner	Existent	Brass Cap	GLO	1912	None	Near old Gravel pit	3084227.318	701610.025	4750.464
3925NW19	100400	Section Corner	Existent	Brass Cap	BLM	2003	None	Re-set at magnet	3082618.764	701652.727	4664.021

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
									"Utah Coordinate System 1983 South Zone"		
									location		
3925SE18	200400	Section Corner	Existent	Brass Cap	GLO	1912	None	At N-W Fence Jct.	3082657.149	703239.907	4917.955
3925W18	100440	Quarter Corner	Existent	Brass Cap	GLO	1912	None	In E-W fenceline	3083423.113	701631.411	4691.553
3925W19	100340	Quarter Corner	Existent	Brass Cap	BLM	2003	None	Projected from Offset due to overhang	3081814.634	701674.408	4810.481
4020S36	640100	quarter corner	Existent	brass cap	GLO	1907	BT, s36,ROCK PILE N.	in rock pile	3067294.386	662626.207	4543.186
4021C24	640340	Quarter Corner	Existent	Re-Bar & Cap	Private	2000	RLS 171004 CAP	BIG BLDR.	3071512.66	672194.197	4523
4021C25	640240	quarter corner	Existent	aluminum cap	BLM	1981	NONE	mon. found, no record	3069903.289	672227.421	4313.331
4021C26	540240	Quarter Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 1IN N	3069873.446	670618.396	4346.433
4021C27	440240	quarter corner	Existent	aluminum cap	BLM	1998	NONE		3069839.656	669011.356	4439.984
4021C33	340140	quarter corner	Existent	brass cap	BLM	1981	NONE	ground level in old UDOTpit area	3068197.984	667434.803	4381.135

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4021C34	440140	quarter corner	Existent	aluminum cap	BLM	1981	NONE		3068232.079	669043.878	4295.289
4021CE1627	460240	sixteenth corner	Existent	aluminum cap	BLM	1998	NONE		3069848.529	669413.132	4395.902
4021CE1633	360140	sixteenth corner	Existent	aluminum cap	BLM	1981	NONE	in e-w powerline	3068206.04	667837.066	4388.821
4021CEW27	430240	64th	Existent	aluminum cap	BLM	1998	NONE	1/64	3069835.192	668810.172	4457.498
4021CN1626	540260	Sixteenth Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 2IN N	3070275.65	670610.133	4377.675
4021CNS27	440230	64th	Existent	aluminum cap	BLM	1998	NONE	stamped wrong 1/64	3069638.331	669016.043	4434.664
4021CS1624	640320	Sixteenth Corner	Existent	Aluminum Cap	Private	1994	RLS 156785	T-PST E AS GRD. ON NW BANK EARTEN DAM	3071111.536	672202.541	4359.227
4021CS1627	440220	sixteenth corner	Existent	aluminum cap	BLM	1998	NONE		3069437.037	669020.201	4425.454
4021CS1633	340120	sixteenth corner	Existent	aluminum cap	BLM	1981	NONE	10" below ground @ sand island	3067795.414	667442.487	4295.025

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
								parking			
4021CW1624	620340										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 18IN N	3071505.541	671791.554	4337.828
4021CW1633	320140										
		sixteenth corner	Existent	aluminum cap	BLM	1981	NONE		3068189.936	667032.708	4387.076
4021E01	700640										
		quarter corner	Existent	brass cap	GLO	1947	NONE		3076352.762	672900.416	4679.233
4021E03	500640										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3076288.329	669678.409	4763.27
4021E10	500540										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3074679.774	669715.888	4781.962
4021E12	700540										
		quarter corner	Existent	aluminum cap	BLM	1979	STONE WEST	leaning to north	3074745.242	672932.731	4675.26
4021E13	700440										
		quarter corner	Existent	aluminum cap	BLM	1979	ROCK PILE-WEST		3073135.629	672966.902	4669.015
4021E15	500440										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3073073.101	669748.021	4819.246
4021E16	400440										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3073040.858	668139.35	4963.678
4021E1627	460200										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		sixteenth corner	Existent	aluminum cap	BLM	1998	NONE	e1/16,27-34	3069043.923	669429.71	4342.894
4021E21	400340										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3071430.608	668172.844	4898.129
4021E24	700340										
		witness corner	Existent	brass cap	BLM	1953	B.O. 12"X IN S.STONE	wc e 1/4 s24	3071471.332	673000.676	4664.933
4021E27	500240										
		quarter corner	Existent	aluminum cap	BLM	1981	NONE	rock pile west	3069857.473	669814.899	4343.961
4021E34	500140										
		meander corner	Lost	none	other	0	NONE		3068299.007	669847.24	4297.592
4021E36	700140										
		quarter corner	Existent	brass cap	BLM	1953	NONE		3068308.365	673066.92	4739.838
4021MC25-36	604200										
		meander corner	Existent	aluminum cap	BLM	1981	NONE	mc for lot 1	3069087.868	671558.886	4306.741
4021MC35/36	600194										
		Meander Corner	Lost	None	BLM	0	NONE		3069034.927	671439.147	4305.846
4021N01	640700										
		quarter corner	Existent	brass cap	GLO	1947	NONE		3077144.182	672075.947	4628.019
4021N02	540700										
		quarter corner	Existent	brass cap	GLO	1929	NONE	in rock pile	3077108.819	670460.553	4635.349
4021N03	440700										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4021N04	340700	quarter corner	Existent	brass cap	GLO	1947	NONE		3077076.899	668853.998	4782.57
4021N05	240700	quarter corner	Existent	brass cap	GLO	1929	NONE		3077040.869	667250.882	4920.598
4021N12	640600	witness corner	Existent	brass cap	GLO	1929	NONE	wc, (pt. fell in wash)	3077002.357	665498.113	4645.923
4021N13	640500	Quarter Corner	Existent	Brass Cap	BLM	1979	ORG MON	3 LRG STNS 1FT N	3075534.489	672110.824	4403.504
4021N14	540500	quarter corner	Existent	aluminum cap	BLM	1979	NONE		3073923.784	672144.625	4629.26
4021N1625/26	600260	quarter corner	Existent	aluminum cap	BLM	1979	NONE	in large rk pile on sandstone ledge rk	3073891.65	670532.951	4686.329
4021N1626/27	500260	Sixteenth Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 3IN N	3070291.669	671413.618	4331.928
4021N20	240400	Sixteenth Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 6IN N	3070259.626	669806.561	4380.765
4021N24	640400	quarter corner	Existent	brass cap	GLO	1929	NONE	10" below ground	3072187.987	665742.127	4490.638

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		quarter corner	Existent	brass cap	BLM	1979	NONE	in bedrock	3072317.126	672177.483	4723.406
<i>4021N25</i>	<i>640300</i>										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE	at e/w/n fence jct	3070710.742	672210.956	4384.271
<i>4021N26</i>	<i>540300</i>										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE	in rock pile mon leaning, reset	3070677.876	670601.877	4425.496
<i>4021N27</i>	<i>440300</i>										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3070645.999	668993.999	4530.487
<i>4021N28</i>	<i>340300</i>										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3070610.744	667384.34	4948.2
<i>4021N29</i>	<i>240300</i>										
		quarter corner	Existent	aluminum cap	BLM	1979	ROCK PILE NORTH		3070586.507	665772.976	4633.016
<i>4021N31</i>	<i>140200</i>										
		witness corner	Existent	brass cap	GLO	1929	NONE	in rock pile wc n 1/4 s31	3068937.638	664314.954	4472.811
<i>4021N35</i>	<i>540200</i>										
		quarter corner	Lost	none	other	0	NONE		3069069.893	670635.904	4301.964
<i>4021NE01</i>	<i>700700</i>										
		section corner	Existent	brass cap	GLO	1912	NONE		3077159.04	672885.311	4651.495
<i>4021NE02</i>	<i>600700</i>										
		section corner	Existent	brass cap	GLO	1947	ROCK PILE WEST		3077126.808	671259.612	4451.284
<i>4021NE03</i>	<i>500700</i>										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		section corner	Existent	brass cap	GLO	1947	ORIGINAL STONE		3077091.823	669657.918	4734.725
4021NE12	700600										
		section corner	Existent	aluminum cap	BLM	1979	ROCK PILE-WEST		3075550.392	672916.572	4614.391
4021NE13	700500										
		section corner	Existent	aluminum cap	BLM	1979	STONE MOUND		3073939.816	672949.683	4599.643
4021NE24	700400										
		section corner	Existent	brass cap	BLM	1953	ROCK PILE WEST		3072331.122	672982.471	4781.998
4021NE25	700300										
		section corner	Existent	brass cap	BLM	1953	NONE	1\2" rebar east	3070721.976	673016.308	4341.549
4021NE25RJ	700300										
		Section Corner	Existent	Aluminum Cap	Private	1979	NONE	ORG STN BURD ALNG SIDE	3070725.76	673017.132	4341.671
4021NE27	500300										
		section corner	Existent	aluminum cap	BLM	1979	NONE		3070661.759	669798.142	4484.043
4021NE28	400300										
		section corner	Existent	aluminum cap	BLM	1979	NONE	in large rk pile	3070625.629	668189.6	4834.867
4021NESW27	430230										
		64th	Existent	aluminum cap	BLM	1998	NONE	t-post north 1/64 by sw cor bluff dump	3069633.969	668814.338	4446.535
4021NW03	400700										
		section corner	Existent	brass cap	GLO	1929	ORIGINAL STONE		3077058.076	668054.286	4841.372
4021NW04											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
"Utah Coordinate System 1983 South Zone"											
4021NW04	300700	section corner	Existent	brass cap	GLO	1929	BT S04, BT S33	in bedrock	3077022.953	666446.836	4877.304
4021NW05	200700	section corner	Existent	brass cap	GLO	1929	BT, s31,s32,s5	in lg. rock pile	3076987.328	664840.466	4847.016
4021NW06	100700	section corner	Existent	brass cap	GLO	1929	NONE	t-post west	3076952.268	663241.451	4523.589
4021NW07	100600	section corner	Existent	brass cap	GLO	1929	NONE		3075344.198	663273.046	4503.311
4021NW09	300600	section corner	Existent	brass cap	GLO	1929	NONE		3075422.001	666482.294	4656.129
4021NW13	600500	witness corner	Existent	brass cap	BLM	1979	NONE	1.14ch n of cnrpt wc to s11,s12,s13, s14	3073934.687	671338.282	4374.069
4021NW1626	520260	Sixteenth Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 2IN N	3070267.634	670208.35	4387.568
4021NW20	200400	section corner	Existent	brass cap	GLO	1929	BT, S20	in lg. rock pile	3072171.516	664935.407	4686.191
4021NW23	500400	Section Corner	Existent	Brass Cap	GLO	1979	ORG MON	RPS NEEDED STEEP SLOPE	3072269.863	669763.798	4745.591
4021NW24	600400										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		section corner	Existent	brass cap	BLM	1979	NONE		3072303.277	671372.401	4378.041
4021NW25	600300										
		section corner	Existent	aluminum cap	BLM	1979	NONE		3070693.79	671405.441	4412.631
4021NW28	300300										
		section corner	Existent	aluminum cap	BLM	1979	NONE		3070595.845	666579.074	4965.44
4021NW29	200300										
		section corner	Existent	aluminum cap	BLM	1979	NONE	in lg. rock pile	3070563.256	664969.828	4501.138
4021NW31	100200										
		section corner	Existent	brass cap	GLO	1929	NONE	in large rk pile	3068917.128	663398.897	4584.75
4021S02	540600										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3075500.844	670501.53	4836.949
4021S03	440600										
		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3075467.596	668893.091	4819.832
4021S04	340600										
		quarter corner	Existent	brass cap	GLO	1929	NONE		3075437.717	667291.14	4913.129
4021S05	240600										
		quarter corner	Existent	brass cap	GLO	1929	BT, s08		3075403.965	665674.738	4598.349
4021S08	240500										
		witness corner	Existent	brass cap	GLO	1929	NONE	stamped wrong wc, pt. fell in wash	3073792.898	665702.298	4554.285
4021S09	340500										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
"Utah Coordinate System 1983 South Zone"											
<i>4021S10</i>		quarter corner	Existent	brass cap	GLO	1929	NONE	in bedrock	3073826.178	667324.479	4834.751
	440500										
<i>4021S14</i>		quarter corner	Existent	brass cap	BLM	1979	NONE		3073859.449	668927.537	4842.249
	540400										
<i>4021S15</i>		quarter corner	Existent	aluminum cap	BLM	1979	NONE	in large rk pile	3072281.671	670567.932	4765.504
	440400										
<i>4021S16</i>		quarter corner	Existent	aluminum cap	BLM	1979	NONE	in large rk pile on sandstone ledge rk	3072251.55	668961.154	4849.639
	340400										
<i>4021S1623/24</i>		quarter corner	Existent	aluminum cap	BLM	1979	NONE		3072220.42	667351.141	4989.047
	600320										
<i>4021S1625/26</i>		Sixteenth Corner	Existent	Brass Cap	BLM	2008	ORG MON	T-PST 7FT N	3071096.129	671397.155	4482.636
	600220										
<i>4021S1627/26</i>		Sixteenth Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 4IN N	3069487.294	671430.014	4306.531
	500220										
<i>4021S1628</i>		sixteenth corner	Existent	aluminum cap	BLM	1998	NONE	at e/w/n fence jct	3069455.351	669823.262	4347.688
	400220										
<i>4021S1632</i>		sixteenth corner	Existent	aluminum cap	BLM	1998	NONE		3069419.588	668215.356	4451.375
	300120										
		sixteenth corner	Existent	aluminum cap	BLM	1981	NONE	s1/16,32-33	3067779.144	666638.964	4396.645

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
4021S19	140300	quarter corner	Existent	brass cap	GLO	1929	BT, s19,s30	in lg. rock pileon bank of wash	3070542.377	664165.908	4566.312
4021S27	440200A	quarter corner	Existent	aluminum cap	BLM	1979	NONE	T-POST 2 FT W	3069034.669	669027.836	4400.806
4021S28	340200	quarter corner	Existent	aluminum cap	BLM	1979	NONE		3069001.905	667418.252	4440.648
4021S29	240200	quarter corner	Existent	aluminum cap	BLM	1979	NONE	in e/w fenceline	3068970.316	665809.013	4583.361
4021S31	140100	quarter corner	Existent	brass cap	GLO	1929	MARKED STONE NORTH	8th st. parallel	3067326.548	664234.373	4505.924
4021S32	240100	quarter corner	Existent	brass cap	GLO	1929	MARKED STONE NORTH	8th st. parallel in e-w fenceline	3067360.266	665843.586	4479.933
4021S34	440100	quarter corner	Existent	brass cap	BLM	1953	NONE	18" below ground st. corner	3067423.629	669060.98	4297.878
4021S35	540100	quarter corner	Existent	brass cap	BLM	1953	NONE	st. corner	3067455.627	670670.637	4917.072
4021S36	640100	quarter corner	Existent	brass cap	BLM	1953	NONE	st. corner	3067487.733	672279.577	4819.76

"Utah Coordinate System 1983 South Zone"

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4021SE03	500600										
		section corner	Existent	aluminum cap	BLM	1979	NONE		3075483.648	669699.146	4776.39
4021SE10	500500										
		section corner	Existent	aluminum cap	BLM	1979	NONE		3073876.079	669732.613	4785.661
4021SE1627	460220										
		sixteenth corner	Existent	aluminum cap	BLM	1998	NONE	t-post east	3069446.275	669421.412	4390.707
4021SE25	700200										
		Section Corner	Existent	Aluminum Cap	BLM	2009	ORG MON	FNC PRJ N&S	3069112.978	673050.028	4312.236
4021SE26	600200										
		Section Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 4IN N	3069085.14	671438.196	4311.744
4021SE27	500200										
		section corner	Existent	aluminum cap	BLM	1981	NONE	t-post west	3069053.269	669831.555	4298.494
4021SE36	700100										
		Section Corner	Existent	Brass Cap	BLM	2010	ORG MON	LRG MNT STN 1FT N	3067504.582	673083.68	4802.091
4021SMC25	620114										
		meander corner	Existent	aluminum cap	BLM	1982	NONE	smc in n/s fence on n/s 1/16 line	3069439.558	671833.625	4316.818
4021SW01	600600										
		Section Corner	Existent	Brass Cap	BLM	1979	ORIG. MON.		3075518.451	671305.023	4622.74
4021SW03	400600										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		section corner	Existent	aluminum cap	BLM	1979	ORIGINAL STONE		3075454.412	668086.926	4875.407
<i>4021SW05</i>	<i>200600</i>										
		section corner	Existent	brass cap	GLO	1929	NONE	in lg. rock pile	3075384.954	664867.393	4874.347
<i>4021SW07</i>	<i>100500</i>										
		section corner	Existent	brass cap	GLO	1929	NONE		3073734.636	663304.916	4451.924
<i>4021SW09</i>	<i>300500</i>										
		section corner	Existent	brass cap	GLO	1929	NONE		3073809.42	666514.723	4620.81
<i>4021SW10</i>	<i>400500</i>										
		section corner	Existent	aluminum cap	BLM	1979	NONE		3073843.187	668122.023	4919.164
<i>4021SW15</i>	<i>400400</i>										
		section corner	Existent	aluminum cap	BLM	1979	ORIGINAL STONE		3072236.066	668156.154	4935.322
<i>4021SW16</i>	<i>300400</i>										
		section corner	Existent	brass cap	GLO	1929	BT,s16,s17,s20	in bedrock	3072204.791	666546.501	4903.869
<i>4021SW1624</i>	<i>620320</i>										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 4IN N	3071103.8	671799.846	4332.245
<i>4021SW1625</i>	<i>620220</i>										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2009	ORG MON	T-PST 4IN W	3069494.649	671832.473	4317.278
<i>4021SW1627</i>	<i>420220</i>										
		sixteenth corner	Existent	aluminum cap	BLM	1998	NONE	t-post east	3069428.342	668617.451	4443.891
<i>4021SW18</i>	<i>100400</i>										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		section corner	Existent	brass cap	GLO	1929	ROCK PILE WEST		3072128.202	663336.515	4431.774
<i>4021SW19</i>	<i>100300</i>										
		section corner	Existent	brass cap	GLO	1929	BT, s19,s25,s30	in lg. rock pile	3070521.389	663368.081	4994.508
<i>4021SW27</i>	<i>400200</i>										
		section corner	Existent	aluminum cap	BLM	1979	NONE	rock pile west	3069017.279	668224.041	4422.281
<i>4021SW28</i>	<i>300200</i>										
		section corner	Existent	aluminum cap	BLM	1979	NONE	rock pile west	3068986.449	666613.702	4462.356
<i>4021SW29</i>	<i>200200</i>										
		section corner	Existent	brass cap	GLO	1929	ROCK PILE WEST		3068953.876	665004.575	4523.962
<i>4021SW31</i>	<i>100100</i>										
		section corner	Existent	brass cap	GLO	1929	NONE	st. corner,8th	3067309.775	663430.168	4437.767
<i>4021SW32</i>	<i>200100</i>										
		section corner	Existent	brass cap	GLO	1929	NONE	8th st. parallel @ corner n/e-w fence	3067343.414	665038.683	4496.839
<i>4021SW33</i>	<i>300100</i>										
		witness corner	Existent	brass cap	GLO	1929	NONE	in e-w fence wcmc	3067375.496	666592.185	4372.547
<i>4021SW34</i>	<i>400100</i>										
		section corner	Existent	brass cap	BLM	1953	NONE	12" below ground st. corner	3067407.833	668255.807	4290.626
<i>4021SW35</i>	<i>500100</i>										
		section corner	Existent	brass cap	BLM	1953	NONE	in rock pile st. corner	3067439.645	669866.57	4933.726

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4021SW36	600100										
		section corner	Existent	brass cap	BLM	1953	NONE	st. corner	3067471.691	671475.056	4854.025
4021W01	600640										
		quarter corner	Existent	brass cap	BLM	1979	NONE	in lg. rock pile	3076322.681	671282.412	4689.096
4021W03	400640										
		quarter corner	Existent	aluminum cap	BLM	1979	ROCK PILE WEST		3076258.842	668071.177	4883.587
4021W04	300640										
		quarter corner	Existent	brass cap	GLO	1929	NONE		3076227.445	666464.42	4693.597
4021W05	200640										
		witness corner	Existent	brass cap	GLO	1929	BT, s05,s06	in sandstone stamp not as per note	3076188.731	664849.589	4871.385
4021W06	100640										
		quarter corner	Existent	brass cap	GLO	1929	NONE		3076148.527	663257.254	4488.235
4021W07	100540										
		quarter corner	Existent	brass cap	GLO	1929	NONE		3074540.278	663288.941	4491.575
4021W09	300540										
		quarter corner	Existent	brass cap	GLO	1929	BT,s09,ROCK PILE WEST	in bedrock	3074615.152	666498.428	4900.769
4021W10	400540										
		quarter corner	Existent	brass cap	BLM	1979	NONE		3074650.795	668104.425	4863.408
4021W12	600540										
		Quarter Corner	Existent	Brass Cap	BLM	2012	MON.	RESET PER	3074715.096	671321.889	4587.855

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
								NOTICE GIVEN			
4021W13	600440										
		quarter corner	Existent	brass cap	BLM	1979	ROCK PILE-W		3073107.623	671355.606	4382.959
4021W16	300440										
		quarter corner	Existent	brass cap	GLO	1929	NONE	firm in ground leaning to north	3073007.237	666530.835	4946.66
4021W1623/26	520300										
		Sixteenth Corner	Existent	Aluminum Cap	BLM	2008	ORG MON	T-PST 1IN N	3070669.801	670200.016	4466.565
4021W1624/25	620300										
		Sixteenth Corner	Existent	Re-Bar & Cap	BLM	1998	ORG MON	CDR PST 1IN E	3070702.382	671808.163	4326.197
4021W1627/34	420200										
		sixteenth corner	Existent	aluminum cap	BLM	1998	NONE	t-post se w1/16,27-34	3069025.973	668625.949	4418.825
4021W17	200440										
		quarter corner	Existent	brass cap	GLO	1929	BT, s17,s18	in lg rock pile	3072975.17	664918.314	4819.432
4021W18	100440										
		quarter corner	Existent	brass cap	GLO	1929	ROCK PILE WEST		3072931.468	663320.752	4433.928
4021W19	100340										
		quarter corner	Existent	brass cap	GLO	1929	STONE WEST		3071325.279	663352.3	4385.288
4021W20	200340										
		quarter corner	Existent	brass cap	GLO	1929	BT, s19,s20		3071365.85	664951.872	4560.984
4021W21											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4021W21	300340	quarter corner	Existent	aluminum cap	BLM	1979	NONE	in large rock pile	3071400.387	666562.863	4912.035
4021W23WC	500347	Witness Corner	Existent	Aluminum Cap	BLM	1979	ORG MON	IN LRG MNT OF STN	3071565.568	669779.047	4724.421
4021W24	600340	Quarter Corner	Existent	Brass Cap	GLO	1981	ORG MON	T-PST 6FT N	3071498.46	671388.94	4665.41
4021W25	600240	quarter corner	Lost	none	other	0	rebar	5/8" rebar 2.5ft NW	3069889.46	671421.846	4325.632
4021W27	400240	quarter corner	Existent	aluminum cap	BLM	1979	NONE	in rock pile	3069821.884	668206.71	4479.629
4021W28	300240	quarter corner	Existent	aluminum cap	BLM	1979	NONE		3069791.2	666596.839	4561.039
4021W29	200240	quarter corner	Existent	brass cap	GLO	1929	NONE		3069758.781	664987.146	4529.214
4021W31	100140	quarter corner	Existent	brass cap	GLO	1929	NONE	in rock pile	3068113.473	663414.572	4544.908
4021W32	200140	quarter corner	Existent	brass cap	GLO	1929	ROCK PILE WEST	in n-s fenceline	3068148.556	665021.423	4613.376
4021W33	300140	quarter corner	Existent	nail	BLM	0	RM S 32,33	BC is under hwy set mag nail from RPs	3068181.844	666630.685	4428.869

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4021W34	400140	quarter corner	Existent	aluminum cap	BLM	1979	NONE	rock pile west	3068214.109	668239.61	4387.689
4021W36	600140	Quarter Corner	Existent	Brass Cap	BLM	2011	ORG MON	T-PST 6IN N	3068276.012	671458.215	4821.002
4021WCMC36/31	700194	Witness Point	Lost	None	BLM	1979	NONE	NO EVIDENCE	3069105.323	673050.211	4308.949
4022AP1	771030	angle point	Existent	aluminum cap	BLM	1998	NONE	angle point 1 40/22/28, tract 37	3069970.161	676920.495	4330.246
4022AP10	771160	Angle Point	Existent	Aluminum Cap	BLM	1998	ORG MON	FNC PST N86W	3070156.409	675116.681	4323.663
4022AP11	771170	angle point	Existent	aluminum cap	BLM	1998	NONE	angle point 11 40/22/28 tract 37	3070054.97	675116.061	4324.766
4022AP2	771040	angle point	Existent	aluminum cap	BLM	1998	NONE	angle point 2 40/22/28, tract 37	3069986.034	676865.853	4330.875
4022AP3	771060	angle point	Existent	aluminum cap	BLM	1998	NONE	angle point 3 40/22/28 tract 37	3070109.919	676489.65	4331.664
4022AP4	771070										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		angle point	Existent	aluminum cap	BLM	1998	NONE	angle point 4 40/22/29 tract 37	3070190.142	676196.71	4331.338
4022AP5	771080										
		angle point	Existent	aluminum cap	BLM	1998	NONE	angle point 5 40/22/29 tract 37	3070289.542	676123.636	4332.066
4022AP6	771090										
		angle point	Lost	none	other	0	NONE	pt fell in edge of cultivated field	3070304.884	675952.491	4327.891
4022AP7	771110										
		angle point	Existent	aluminum cap	BLM	1998	NONE	angle point 740/22/29 tract 37	3070483.049	675626.678	4327.01
4022AP8	771120										
		angle point	Existent	aluminum cap	BLM	1998	NONE	angle point 8 40/22/29 tract 37	3070494.496	675504.557	4325.332
4022AP9	771140										
		Angle Point	Existent	Aluminum Cap	BLM	1998	ORG MON	FNC PST N5W	3070415.419	675330.359	4325.988
4022C30	140240										
		quarter corner	Existent	aluminum cap	BLM	1981	NONE	in thick marsh area	3069932.751	673834.436	4312.526
4022CC28-29	300250										
		closing corner	Existent	aluminum cap	BLM	1998	NONE	cc s28/29	3070180.186	676233.062	4329.246
4022CE1630	160240										
		sixteenth corner	Existent	brass cap	BLM	1981	NONE	in open field 1" pvc pipe	3069940.179	674236.248	4322.514

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
								south			
4022E08	300540										
		quarter corner	Existent	brass cap	BLM	1979	ROCK PILE WEST		3074813.48	676147.088	4796.093
4022E16	400440										
		quarter corner	Existent	brass cap	BLM	1979	NONE	in n/s fenceline	3073249.407	677783.594	4694.274
4022E1630	160300										
		sixteenth corner	Existent	brass cap	GLO	1981	NONE	in sandstone e1/16, s19-30	3070743.139	674218.891	4623.881
4022E21	400340										
		quarter corner	Existent	stone corner	GLO	0	ROCK PILE		3071628.349	677816.858	4564.694
4022E28	400240										
		quarter corner	Existent	brass cap	BLM	1979	ROCK PILE WEST		3070020.401	677851.466	4401.014
4022E30	200240										
		quarter corner	Existent	aluminum cap	BLM	1998	NONE	in open field 6" below grnd surface	3069947.593	674638.055	4323.417
4022E32	300140										
		quarter corner	Existent	aluminum cap	BLM	1998	NONE		3068374.19	676272.977	4638.703
4022MC1	300254										
		meander corner	Existent	aluminum cap	BLM	1998	NONE	mc s28/29 not stamp as per note	3070250.918	676238.496	4331.876
4022N04	340700										
		Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON MND STONE		3077239.719	676897.424	4911.713
4022N05											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
"Utah Coordinate System 1983 South Zone"											
4022N05	240700	Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON	MND STN AT BASE	3077208.288	675288.259	4817.929
4022N06	140700	Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON	ORIG STN BURIED ALONGSIDE	3077192.254	673678.248	4670.609
4022N07	140600	Quarter Corner	Lost	None	GLO	1899	NONE	CEDAR POST ON GRND	3075565.986	673713.746	4694.945
4022N08	240600	Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG STN BURIED N	HWY 191 600' E.	3075599.229	675321.499	4743.177
4022N09	340600	Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON	MND STN 2' W	3075634.179	676929.189	4944.072
4022N14	540500	Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON		3074092.671	680149.075	4612.296
4022N15	440500	Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON	LRG MND N	3074044.149	678566.019	4766.498
4022N16	340500	quarter corner	Existent	brass cap	BLM	1979	ROCK PILE NORTH	in e-w fenceline	3074024.889	676957.469	4783.632
4022N1630	260200	sixteenth corner	Existent	aluminum cap	BLM	1999	T-POST & SIGN, NW	in open field N1/16 s29/s30	3070349.809	674629.209	4324.226
4022N17	240500										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		Quarter Corner	Existent	Aluminum Cap	County	2014	ORIG STONE	MAGNET AS MEMORIAL	3073989.038	675357.477	4739.692
4022N18	140500										
		Quarter Corner	Lost	None	GLO	1899	NONE		3073956.741	673748.567	4645.934
4022N19	140400										
		quarter corner	Existent	aluminum cap	Local	2006	ORIG. STONE	PLS#161297	3072347.245	673780.981	4671.316
4022N20	240400										
		quarter corner	Lost	none	GLO	0	NONE		3072380.156	675387.544	4643.807
4022N22	440400										
		Quarter Corner	Existent	Brass Cap	BLM	1979	MON.	ORIG STN BURIED ALNGSIDE	3072450.961	678603.716	4581.805
4022N23	540400										
		Quarter Corner	Lost	None	GLO	1898	NONE	DIRTWORK IN AREA	3072481.668	680209.705	4564.998
4022N26WC	547300										
		Witness Corner	Existent	Brass Cap	BLM	1979	ORIG MON	T-POST AS GUARD N	3070878.942	680343.908	4353.19
4022N27	440300										
		Quarter Corner	Existent	Brass Cap	BLM	1979	MON.	IN LARGE STONE MND	3070841.951	678637.53	4453.58
4022N30	140300										
		quarter corner	Existent	brass cap	GLO	1979	BO UNKNWN ORIGIN	in sandstone in rock pile	3070734.319	673817.35	4599.194
4022NE08	300600										
		section corner	Existent	brass cap	BLM	1979	ROCK PILE W, T-POST E	on west road edge	3075616.32	676125.476	4811.063

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4022NE16	400500	section corner	Existent	brass cap	BLM	1979	ORIG. STONE NORTH	at e-w-s fencejct	3074042.466	677766.124	4790.686
4022NE20	300400	section corner	Lost	none	GLO	0	fence	e/n fence corner	3072398.03	676191.153	4644.744
4022NE30	200300	section corner	Existent	brass cap	BLM	1979	ROCK PILE WEST		3070751.99	674620.431	4624.762
4022NW04	300700	Section Corner	Existent	Brass Cap	BLM	1979	MON MND STONE	REBUILD MND STN	3077223.655	676092.385	4861.851
4022NW05	200700	Section Corner	Existent	Brass Cap	BLM	1979	ORIG. MON	NOTES CALL ORIG STN BURIED ALONGSIDE	3077188.769	674486.871	4760.219
4022NW08	200600	Section Corner	Existent	Brass Cap	BLM	1979	MON.	POWER LINE 95'NW	3075582.16	674517.631	4746.613
4022NW13	600500	Section Corner	Existent	Brass Cap	BLM	1979	ORIG MON	2 RPS UNKNON ORIGIN	3074107.776	680954.1	4455.655
4022NW14	500500	Section Corner	Existent	Brass Cap	BLM	1979	MON IN MND STN	STEEP SLOPE FALLS NORTH	3074045.912	679366.562	4744.137
4022NW16	300500										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		section corner	Existent	brass cap	BLM	1979	ROCK PILE WEST	at n-s-e-w fence corn	3074007.688	676148.494	4766.291
4022NW1629	220260										
		sixteenth corner	Existent	aluminum cap	BLM	1999	T-POST, EAST	in open field 4' west of n-s fence	3070363.156	675030.813	4326.693
4022NW17	200500										
		Section Corner	Lost	None	GLO	1899	NONE	POST FRAGMENT NOT IN NOTES	3073971.478	674552.545	4683.11
4022NW20	200400										
		section corner	Existent	aluminum cap	Local	2006	MOUND OF STONE	PLS#161297	3072362.776	674583.267	4610.062
4022NW23	500400										
		Section Corner	Existent	Brass Cap	BLM	1979	ORIG MON		3072464.269	679405.398	4589.337
4022NW25	600300										
		Section Corner	Existent	Brass Cap	BLM	1979	MON.	T-POST N	3070893.566	681050.084	4352.344
4022NW28	300300										
		section corner	Existent	aluminum cap	BLM	1998	NONE	in lg. rock pile on e. canyon ledge	3070789.76	676226.63	4432.371
4022NW32	200200										
		section corner	Existent	aluminum cap	BLM	1998	NONE	in lg. rock pile	3069145.161	674646.601	4585.81
4022S16	340400										
		quarter corner	Lost	none	GLO	0	fence	in e/w fenceline	3072415.251	676996.073	4644.263
4022S20	240300										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		quarter corner	Existent	aluminum cap	BLM	1998	LG. ROCK PILE, NORTH	in solid s.stone	3070778.763	675423.417	4573.732
4022S21	340300										
		quarter corner	Existent	brass cap	BLM	1979	ROCK PILE WEST		3070803.701	677030.056	4502.747
4022S28	340200										
		witness corner	Existent	aluminum cap	BLM	1998	NONE	in rock pile wc, s1/4, s28	3069194.306	677019.762	4556.126
4022S29	240200										
		quarter corner	Existent	aluminum cap	BLM	1998	ROCK PILE NORTH		3069161.791	675450.871	4548.917
4022S33	340100										
		quarter corner	Existent	brass cap	BLM	1953	NONE	st. corner 8th st. parallel	3067586.546	677095.49	4689.736
4022SE16	400400										
		section corner	Existent	brass cap	BLM	1979	ORIG. STONE	at n-s-w fencejct	3072432.999	677800.33	4623.054
4022SE21	400300										
		section corner	Existent	brass cap	BLM	1979	ROCK PILE	in lg. rock pile	3070823.627	677833.774	4519.636
4022SE28	400200										
		section corner	Existent	other	BLM	0	MAGNET 36" IN GRND.	mon. missing found depositedmag net	3069212.011	677864.754	4336.857
4022SMC1	320244										
		meander corner	Existent	brass cap	BLM	1981	NONE	smc, w/28 at jct s-w-se fence	3070132.93	676643.03	4333.269
4022SMC2	240266										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
		meander corner	Existent	aluminum cap	BLM	1998	NONE	smc s29 1' east of n-s fence	3070536.687	675428.832	4329.76
4022SMC29-81	220224										
		Special Meander Corner	Existent	Aluminum Cap	BLM	1981	ORG MON	FNC CRNR SE 10FT	3069636.705	675046.889	4321.629
4022SMC29-98	000000										
		Special Meander Corner	Existent	Aluminum Cap	BLM	1998	ORG MON	FNC CRNR NE APPROX 6FT	3070043.297	675037.884	4324.524
4022SMC30	950110										
		Special Meander Corner	Existent	Aluminum Cap	BLM	2011	ORG MON	FNC PRJ N&S	3069618.802	674243.277	4319.143
4022SW28	300200										
		section corner	Existent	aluminum cap	BLM	1998	NONE	in lg. rock pile	3069178.499	676255.146	4560.522
4022SW32	200100										
		section corner	Existent	brass cap	BLM	1953	NONE	st. corner 8th st. parallel	3067536.57	674681.876	4723.377
4022SW33	300100										
		section corner	Existent	brass cap	BLM	1953	NONE	st. corner 8th st. parallel	3067569.894	676290.785	4682.844
4022SW34	400100										
		section corner	Existent	brass cap	BLM	1953	NONE	st. corner 8th st. paralell	3067603.259	677900.129	4673.992
4022W04	300640										
		Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON MND STONE	MND STN 2' W	3076419.341	676109.727	4825.736
4022W05											

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4022W05	200640	Quarter Corner	Existent	Aluminum Cap	County	2014	MND STONES	2' EAST OF STONE MND	3076384.631	674503.397	4731.883
4022W08	200500	Quarter Corner	Lost	None	GLO	1899	NONE	NO EVIDENCE	3074776.803	674536.47	4695.167
4022W13	60040	Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON	REBLND MND STN	3073304.921	680984.15	4482.772
4022W14	500440	Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON	STONE RING	3073271.441	679391.861	4645.486
4022W16	300440	quarter corner	Lost	none	GLO	0	fence	N?S fenceline 15ft E	3073203.153	676165.573	4692.19
4022W1628	320300	sixteenth corner	Existent	brass cap	BLM	1979	ROCK PILE	in lg. rockpile W1/16, s28,s21	3070796.764	676628.347	4540.086
4022W1629	220300	sixteenth corner	Existent	brass cap	BLM	1979	ROCK PILE NORTH	w 1/16, s29,s20	3070765.336	675021.977	4601.449
4022W17	200440	Quarter Corner	Lost	None	GLO	1899	NONE	OLD WAGON ROAD	3073167.085	674565.672	4658.16
4022W20	200340	quarter corner	Existent	aluminum cap	Local	2006	ORIG. STONE	PLS#161297 orig. stone beside	3071557.707	674602.202	4604.194

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4022W21	300340	quarter corner	Existent	other	GLO	0	X IN SANDSTONE	from 1899 survey rock pile scattered	3071594.276	676208.093	4575.215
4022W23	500340	Quarter Corner	Existent	Brass Cap	BLM	1979	ORIG MON	MND STN W	3071664.46	679423.958	4552.637
4022W24	600340	Quarter Corner	Existent	Brass Cap	BLM	1979	MON.	TALL STONE MND	3071697.914	681032.066	4465.555
4022W28	300240	quarter corner	Existent	brass cap	BLM	1998	NONE	in atcity camp	3069982.495	676237.268	4330.503
4022W30	100240	Quarter Corner	Existent	Aluminum Cap	BLM	2009	ORG MON	CFM AT CANAL	3069917.495	673033.179	4310.68
4022WCSMC1	800635	witness corner	Existent	aluminum cap	BLM	1998	NONE	s29 wc,smc aux. meander line	3069404.32	675175.058	4322.346
4022WP2	771130	witness corner	Existent	aluminum cap	BLM	1998	NONE	wp aux. meander n-s c/l s29&1899 mean	3070473.207	675457.652	4326.6
4023E1625-36	660200	Sixteenth Corner	No Observation	Rebar	Private	0	#5 Rebar no cap	Set RM NW	3069520.103	691925.603	0
4023NE12	100603										

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
		Section Corner	No Observation	Brass Cap	BLM	1953	B.C.	Set RPs NW, and NE	3066500.488	692310.168	0
<i>4023SE25</i>	<i>700200</i>										
		Section Corner	No Observation	Brass Cap	BLM	1942	B.C.	Set RMs NW, and SW	3069530.457	692331.492	0
<i>4023SE36</i>	<i>700100</i>										
		Section Corner	No Observation	Brass Cap	BLM	1953	B.C.	In E-W fence line	3067921.483	692369.019	0
<i>4023SW25</i>	<i>600200</i>										
		Section Corner	No Observation	Aluminum Cap	BLM	1980	A.C.	Set RMs SW, and SE	3069495.033	690707.632	0
<i>4024C32</i>	<i>240140</i>										
		Quarter Corner	No Observation	Aluminum Cap	BLM	2003	A.C.	Set RMS NW, and NE	3068783.563	694738.808	0
<i>4024E32</i>	<i>300140</i>										
		Quarter Corner	No Observation	Aluminum Cap	BLM	2003	A.C.	Set RMs SW, and NW	3068799.433	695570.045	0
<i>4024S32</i>	<i>240100</i>										
		Quarter Corner	No Observation	Brass Cap	GLO	1933	B.C.	Set RMs NW, and N	3067979.101	694755.54	0
<i>4024SE1632</i>	<i>260120</i>										
		Sixteenth Corner	No Observation	Aluminum Cap	BLM	2003	A.C.	Set RMs NE, and SE	3068389.961	695161.509	0
<i>4024SE32</i>	<i>300100</i>										
		Section Corner	No Observation	Aluminum Cap	BLM	2003	A.C.	Set RMs W, and SW	3067997.776	695581.622	0
<i>4120N01</i>	<i>640700</i>										

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
4121N01	640700	Quarter Corner	Existent	Brass Cap	GLO	1929	ORG MON	IN LRG MNT OF STN SET MAG NAIL	3067297.527	662790.37	4524.02
4121N02	540700	quarter corner	Existent	brass cap	BLM	1953	NONE		3067486.631	672224.601	4821.933
4121N03	440700	quarter corner	Existent	brass cap	BLM	1953	NONE		3067454.469	670615.55	4922.698
4121N05	240700	quarter corner	Existent	brass cap	BLM	1953	NONE	6" below ground	3067423.403	669006.076	4296.142
4121N06	140700	quarter corner	Existent	brass cap	GLO	1929	NONE	in e-w fenceline buried 28" below grnd	3067363.437	666007.987	4478.062
4121NE01	700700	quarter corner	Existent	brass cap	GLO	1929	NONE	in rock pile	3067330.116	664398.314	4499.892
4121NE06	200700	closing corner	Existent	brass cap	BLM	1953	NONE		3067502.749	673028.954	4804.335
4121NW01	600700	section corner	Existent	brass cap	GLO	1929	NONE	in e-w fenceline	3067346.613	665202.923	4497.052
4121NW02	500700	section corner	Existent	brass cap	BLM	1953	NONE		3067470.495	671420.034	4862.004

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>4121NW03</i>	<i>400700</i>	section corner	Existent	brass cap	BLM	1953	NONE	in rock pile	3067438.492	669811.477	4926.651
<i>4121NW04</i>	<i>300700</i>	section corner	Existent	brass cap	BLM	1953	NONE	10" below ground	3067406.803	668200.98	4290.411
<i>4121NW06</i>	<i>100700</i>	section corner	Lost	none	other	0	NONE		3067379.474	666812.344	4285.892
<i>4123NE01</i>	<i>700700</i>	witness corner	Existent	brass cap	GLO	1929	NONE	wc to cc 4121nw06	3067285.246	663595.453	4471.624
<i>4223SW34</i>	<i>400100</i>	Section Corner	No Observation	Aluminum Cap	Private	2004	A.C.	Set using parole evidence	3067919.394	692277.348	0
<i>4223SW35</i>	<i>500100</i>	Section Corner	No Observation	Brass Cap	BLM	1953	B.C.	Monument in mound of stone	3048688.341	687891.295	0
<i>AP-5</i>	<i>297700</i>	Section Corner	No Observation	Iron Pipe	Other	0	Iron Pipe	Iron pipe in stone mound	3048727.061	689501.194	0
<i>AP-6</i>	<i>197700</i>	angle point	Existent	brass cap	GLO	1911	none	angle point	3194810.172	683005.492	5705.275
<i>CWENE30</i>	<i>165260</i>	angle point	Existent	brass cap	GLO	1916	BT,s06,s05	8"abv mnd of stn angle point	3194775.854	681394.757	5690.868

Point ID	GCDB #	Corner Type	Status	Monument Type	Agency	Stamp Date	Evidence	Notes	Northing (m)	Easting (m)	Elevation (USsft)
"Utah Coordinate System 1983 South Zone"											
		256th	Existent	aluminum cap	BLM	1981	T-POST & SIGN, EAST	1/256, s30	3070344.181	674328.236	4323.528
<i>Line Tree A</i>											
	700643										
		line tree	Existent	line tree	GLO	0	marked tree	2723E01 85ft to S line tree standing	3203861.491	689238.992	7811.948
<i>Line Tree B</i>											
	600453										
		line tree	Existent	line tree	GLO	0	marked tree	2723W13 795ft to S line Tree down	3200809.897	687693.513	6867.817
<i>smc 3</i>											
	464140										
		meander corner	Existent	aluminum cap	BLM	1981	none	smc,e-w cl se1/4, sec. 34	3068245.457	669643.549	4295.509
<i>SWNENE30</i>											
	165265										
		256th	Existent	aluminum cap	BLM	1981	NONE	1/256 corner on unstable hillside	3070444.645	674325.603	4352.714
<i>UT/CO MP-102+31</i>											
	2726MP102+31										
		State Line Marker	No Observation	Stone	GLO	1885	Stone	State line "signal " along Utah Colorado line. mile 102 +31 chains (2046')	3204389.398	712878.379	0
<i>UT/CO MP-103</i>											
	721103										
		State Line Mile Marker	No Observation	Stone	GLO	1885	Stone	State line between Utah and Colorado Mile Point 103	3205363.574	712850.464	0
<i>UT/CO MP-91</i>											
	721091										
		State Line Mile Marker	No Observation	Stone	GLO	1885	Stone	State line between Utah and Colorado Mile Point 91	3185971.15	713344.745	0

<i>Point ID</i>	<i>GCDB #</i>	<i>Corner Type</i>	<i>Status</i>	<i>Monument Type</i>	<i>Agency</i>	<i>Stamp Date</i>	<i>Evidence</i>	<i>Notes</i>	<i>Northing (m)</i>	<i>Easting (m)</i>	<i>Elevation (USsft)</i>
<i>"Utah Coordinate System 1983 South Zone"</i>											
<i>UT/CO MP-92</i>	<i>721092</i>										
		State Line Mile Marker	No Observation	Stone	GLO	1885	Stone	State line between Utah and Colorado Mile Point 92	3187574.802	713302.35	0
<i>UT/CO MP-94</i>	<i>721094</i>										
		State Line Mile Marker	No Observation	Stone	GLO	1885	Stone	State line between Utah and Colorado Mile Point 94	3190785.96	713221.863	0
<i>UT/CO MP-95</i>	<i>721095</i>										
		State Line Mile Marker	No Observation	Stone	GLO	1885	Stone	State line between Utah and Colorado Mile Point 95	3192400.66	713178.314	0
<i>UT/CO MP-96</i>	<i>721096</i>										
		State Line Mile Marker	No Observation	Stone	GLO	1885	Stone	State line between Utah and Colorado Mile Point 96	3194018.537	713137.2	0